

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13177B

Date In:	17 FEB 26	Author:	KOTT
Promised Date:	31 DEC 26	Stock No:	11570
:	:	Year:	2026
Customer Name:	1000 - GREENEWAY RV SA	Manufacturer:	FOREST RIVER
Address:	8220 STATE HWY 13 SOUT	Brand:	PUMA DESTINATION
:	WISCONSIN RAPIDS, WI	Model:	421LFT
Postal/Zip:	54494	Miles/Hrs:	0
Phone#(res):	800-758-2272	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DB: 2/17
Purchased Date:	:	:	:
Delivery Date:	:	:	:
InService Date:	:	:	:
Serial#:	4X4TPU826TP107730	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 -rear bathroom mirror  W    1021    FORES
        has a scratch in the center.
        CAUSE:        scratch mirror
        CORRECTION:   remove and installed new mirror in rear
        bathroom all clips are secured to mirror
        . REQUEST .50  WARR AUTH: .10
WARR    COMPLAINT:  WARRANTY REPAIR 2 - the fromt bathroom  W    1021    FORES
        shower door is siliconed shut on the
        right side.
        CAUSE:        The glass sliding door was siliconed
        shut on the right side, i was able to
        get it unstuck and in the process found
        a could areas silicone needed to be
        touched up so i did as well
        CORRECTION:   Done REQUEST .60 WARR AUTH: .50
WARR    COMPLAINT:  WARRANTY REPAIR 3 -the ladder to the    W    1021    FORES
        rear loft is uneven.
        CAUSE:        The rear loft ladder is uneven, the
        bracket holding the ladder was slightly
        off level, i leveled it and it no longer
        wiggles
        CORRECTION:   Done REQUEST .40 WARR AUTH: .20
WARR    COMPLAINT:  WARRANTY REPAIR 4 -there is a scratch on W    1021    FORES
        the floor infront of the left side of
        the fridge.
        CAUSE:        There were a couple nicks in the
        flooring infront of the fridge, i
        coverer them the best i could with
```

Continued on page 2

Work Order : 13177B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
putty.
WARR    CORRECTION: Done REQUEST .30 WARR AUTH: .30
COMPLAINT: WARRANTY REPAIR 5 - there are multiple W 1021 FORES
putty stains on the carpet on the ods
living room/kitchen slide.
CAUSE:   The carpet on the ods kitchen slide had
some putty stains on it, the stains came
out after scubbing them with stain
remover
WARR    CORRECTION: Done REQUEST: .50 WARR AUTH: .50
COMPLAINT: WARRANTY REPAIR 6 - there is exposed W 1021 FORES
wood on the bottom corner of the side of
the slide causing water to get onto the
carpet.
CAUSE:   On all of the slides in the bottom
inside corner the metal does not go all
the way to the edge past the seal so
there is exposed wood, i took black non
level dycore and covered the exposed
wood.
1       CORRECTION: Done REQEUST 1 HOURS WARR AUTH: 1.00
COMPLAINT: Transferred to GRV*13177C on 10 MAR 26 W 1021 FORES
Estimate amount was 0.00 4 slide out
lower corners near fascia boards needs
to be seal due to exterior metal panels
cut to short exposure of wood causes
leaking
CAUSE:   manu did not finish completely sealing
the slide out
CORRECTION: need to seal the boards req: 8 hours

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WARR0 82203979     CONTINENTAL MIRRORED GRA W-1021      1      27.35      27.35
WARR0 677917009220 EDPM LAP SEAL 10.3 OZ.TU W-1021      1      10.02      10.02

```

```

*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
ARR01 Z992 MISC LABOUR CODE (WARR EG W-1021 0.10 140.00 14.00
ARR01 WARR MANUFACTURER WARRANTY JS W-1021 0.00 140.00 0.00
ARR02 Z992 MISC LABOUR CODE (WARR EG W-1021 0.55 140.00 77.00
ARR03 Z992 MISC LABOUR CODE (WARR EG W-1021 0.38 140.00 53.20
ARR04 Z992 MISC LABOUR CODE (WARR EG W-1021 0.30 140.00 42.00
ARR05 Z992 MISC LABOUR CODE (WARR EG W-1021 0.35 140.00 49.00
ARR05 Z992 MISC LABOUR CODE (WARR EG W-1021 0.15 140.00 21.00
ARR06 Z992 MISC LABOUR CODE (WARR EG W-1021 0.50 140.00 70.00
ARR06 Z992 MISC LABOUR CODE (WARR EG W-1021 0.50 140.00 70.00

```

Continued on page 3

Work Order : 13177B

```

*****
Job#  Lab Code  Description   LABOUR   Mech Bill to    Hrs    Rate    Total
*****
ARR01 WARR      MANUFACTURER WARRANTY JS    W-1021    0.90   140.00   126.00

```

```

*****
Job #   Excode   Description   EXTRAS      bill to    Qty    Price    Total
*****
ARR01   SSE      SHOP SUPPLIES - EXTERNAL W-1021    1.00    0.00    0.00
ARR01   FRT      FREIGHT      W-1021    1.00   46.87   46.87

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras      Tax      Total
*****
W      1021      37.37    522.20     0.00    46.87      0.00    606.44
      Totals      37.37    522.20     0.00    46.87      0.00    606.44

```

&k2S
&k0S