

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13177B

Date In:	17 FEB 26	Author:	KOTT
Promised Date:	31 DEC 26	Stock No:	11570
:	:	Year:	2026
Customer Name:	1000 - GREENEWAY RV SA	Manufacturer:	FOREST RIVER
Address:	8220 STATE HWY 13 SOUT	Brand:	PUMA DESTINATION
:	WISCONSIN RAPIDS, WI	Model:	421LFT
Postal/Zip:	54494	Miles/Hrs:	0
Phone#(res):	800-758-2272	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DB: 2/17
Purchased Date:	:	:	:
Delivery Date:	:	:	:
InService Date:	:	:	:
Serial#:	4X4TPU826TP107730	:	:

```
*****
Job #   Description          JOB INFORMATION          Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 -rear bathroom mirror W    1021    FORES
        has a scratch in the center.
        CAUSE:      There is a scratch in the rear bathroom
                    mirror, we will need to order a new
                    mirror H:26 1/8 W: 17 1/8
        CORRECTION: . REQUEST .50
WARR    COMPLAINT:  WARRANTY REPAIR 2 - the fromt bathroom W    1021    FORES
        shower door is siliconed shut on the
        right side.
        CAUSE:      The glass sliding door was siliconed
                    shut on the right side, i was able to
                    get it unstuck and in the process found
                    a could areas silicone needed to be
                    touched up so i did as well
        CORRECTION: Done REQUEST .60
WARR    COMPLAINT:  WARRANTY REPAIR 3 -the ladder to the W    1021    FORES
        rear loft is uneven.
        CAUSE:      The rear loft ladder is uneven, the
                    bracket holding the ladder was slightly
                    off level, i leveled it and it no longer
                    wiggles
        CORRECTION: Done REQUEST .40
WARR    COMPLAINT:  WARRANTY REPAIR 4 -there is a scratch on W    1021    FORES
        the floor infront of the left side of
        the fridge.
        CAUSE:      There were a couple nicks in the
                    flooring infront of the fridge, i
                    coverer them the best i could with
```

Continued on page 2

Work Order : 13177B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
putty.
CORRECTION: Done REQUEST .30
WARR COMPLAINT: WARRANTY REPAIR 5 - there are multiple W 1021 FORES
putty stains on the carpet on the ods
living room/kitchen slide.
CAUSE: The carpet on the ods kitchen slide had
some putty stains on it, the stains came
out after scubbing them with stain
remover
CORRECTION: Done REQUEST .30
WARR COMPLAINT: WARRANTY REPAIR 6 - there is exposed W 1021 FORES
wood on the bottom corner of the side of
the slide causing water to get onto the
carpet.
CAUSE: On all of the slides in the bottom
inside corner the metal does not go all
the way to the edge past the seal so
there is exposed wood, i took black non
level dycore and covered the exposed
wood.
CORRECTION: Done REQEUST 1 HOURS

```

```

*****
Job # Part No   Description   PARTS   Bill to   Qty   Price   Total
*****
WARR0 677917009220 EDPM LAP SEAL 10.3 OZ.TU W-1021 1 10.02 10.02

```

```

*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
ARR01 Z992 MISC LABOUR CODE (WARR EG W-1021 0.50 140.00 70.00
ARR02 Z992 MISC LABOUR CODE (WARR EG W-1021 0.50 140.00 70.00
ARR03 Z992 MISC LABOUR CODE (WARR EG W-1021 0.50 140.00 70.00
ARR04 Z992 MISC LABOUR CODE (WARR EG W-1021 0.50 140.00 70.00
ARR05 Z992 MISC LABOUR CODE (WARR EG W-1021 0.35 140.00 49.00
ARR05 Z992 MISC LABOUR CODE (WARR EG W-1021 0.15 140.00 21.00
ARR06 Z992 MISC LABOUR CODE (WARR EG W-1021 0.27 140.00 37.80
ARR06 Z992 MISC LABOUR CODE (WARR EG W-1021 0.23 140.00 32.20

```

```

*****
Job # Excode Description EXTRAS bill to Qty Price Total
*****
ARR01 SSE SHOP SUPPLIES - EXTERNAL W-1021 1.00 0.00 0.00

```

```

*****
BILLINGS SUMMARY
Type Bill Id Parts Labour Sublet Extras Tax Total
*****
W 1021 10.02 420.00 0.00 0.00 0.00 430.02

```

Continued on page 3

Work Order : 13177B

BILLINGS SUMMARY

Type Bill Id	Parts	Labour	Sublet	Extras	Tax	Total

Totals	10.02	420.00	0.00	0.00	0.00	430.02

&k2S
&k0S