

DEALER ACCOUNT #	0009497	CLAIM STATUS	Paid
GREENEWAY INC		CLAIM	2583310
DBA GREENEWAY RV SALES & SERVICE		CLAIM ORIGIN	WEB
8220 STATE HWY 13 SOUTH		ORIGINAL CLAIM ID	
WISCONSIN RAPIDS, WI 54494		VIN	4X4TPU826TP107730
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	420 / 420
Labor rate:	\$140.00	ITEM #	PUT421LFT
OWNER INFORMATION		DEALER RO #	13177B
		CLAIM START DATE	02/17/2026
		CLAIM END DATE	03/11/2026
Retail Date of Purchase		WARRANTY EXPIRATION DATE	

Labor			
Line# 1	Operation Code	Operational Description	
	30-92-01-00-002698	Wall Mirror - Interior/Interior Miscellaneous/Replace/No Tread Code	
	Complaint, Cause, Correction		
	Original Note : greeneway@dealer-advisors.com, 2026-02-17 16:04:57 :: Complaint: Rear bathroom mirror has a scratch in the center. Cause: There is a scratch in the rear bathroom mirror from manufacturer install. Correction: R&R mirror H: 26 1/8 W 17 1/8		
Model#	Dlr Sub Hrs	0.50	Sub Labor Amt \$70.00
Serial#	Appr Hrs	0.10	Appr Labor Amt \$14.00
	Notes		
	flat rate to r/r mirror		

Line# 1	Item #		Description			
	F100233979		MIRROR, 17 X 26-3/16 ELLIPSE, PE, SB			
	Model #		Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$27.35	Sub Freight	\$46.87
	Appr Qty	1.00	Appr Dlr Price	\$27.35	Appr Freight	\$46.87
	Notes					

Line# 2	Operation Code 60-141-02-00-001612	Operation Description Glass Shower Door - Plumbing/Shower, Tub Surround/Adjust/No Tread Code
Complaint, Cause, Correction Original Note : greeneway@dealer-advisors.com, 2026-02-17 16:06:43 :: Complaint: The front bathroom shower door is siliconed shut on the right side. Cause: The glass sliding door was siliconed shut on the right side from install. Correction: Was able to get it unstuck, but also noticed a couple areas that needed to be touched up with silicone so we did that as well. Additional Note : greeneway@dealer-advisors.com, 2026-02-17 16:08:27 :: No repair code for glass shower door.		
Model#	Dlr Sub Hrs	0.60
		Sub Labor Amt \$84.00
Serial#	Appr Hrs	0.50
		Appr Labor Amt \$70.00
Notes flat rate .30 clean silicone .20 spot seal		

Line# 1	Item #	Description				
	USERPART	Shop supplies - silicone				
	Model #	Serial #			Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$1.40	Sub Freight	\$0.00

Appr Qty	1.00	Appr Dlr Price	\$1.40	Appr Freight	\$0.00
Notes					

Labor**Line# 3**

Operation Code	Operational Description
30-94-01-16-000944	Bunk Ladder - Interior/Overhead Bunk Area/Replace/Structure
Complaint, Cause, Correction	
Original Note : greeneway@dealer-advisors.com, 2026-02-17 16:09:12 :: Complaint: The ladder to the loft is uneven. Cause: The rear loft ladder is uneven, the bracket holding the ladder was slightly off level. Correction: Leveled the bracket. Additional Note : greeneway@dealer-advisors.com, 2026-02-17 16:09:27 :: No repair code	
Model#	Dlr Sub Hrs 0.40 Sub Labor Amt \$56.00
Serial#	Appr Hrs 0.20 Appr Labor Amt \$28.00
Notes	
flat rate to adjust bracket	

Labor**Line# 4**

Operation Code	Operational Description
30-103-24-00-001125	Linoleum - Interior/Flooring/Repair/No Tread Code
Complaint, Cause, Correction	
Original Note : greeneway@dealer-advisors.com, 2026-02-17 16:10:21 :: Complaint: There is a scratch on the floor in front of the left side of the fridge. Cause: There were a couple nicks in the flooring in front of the fridge from manufacturer. Correction: Covered them the best we could with putty.	
Model#	Dlr Sub Hrs 0.30 Sub Labor Amt \$42.00
Serial#	Appr Hrs 0.30 Appr Labor Amt \$42.00
Notes	

Part**Line# 1**

Item #	Description	
USERPART	Shop supplies - putty	
Model #	Serial #	Part tag
Sub Qty 1.00	Sub Dlr Price \$2.10	Sub Freight \$0.00
Appr Qty 1.00	Appr Dlr Price \$2.10	Appr Freight \$0.00
Notes		

Labor**Line# 5**

Operation Code	Operational Description
30-103-04-00-001119	Carpet - Interior/Flooring/Clean/No Tread Code
Complaint, Cause, Correction	
Original Note : greeneway@dealer-advisors.com, 2026-02-17 16:11:45 :: Complaint: There are multiple putty stains on the carpet on the ODS living room/kitchen slide. Cause: The carpet on the ODS kitchen slide had some putty stains on it from the manufacturer. Correction: Stains came out after scrubbing them with stain remover.	
Model#	Dlr Sub Hrs 0.50 Sub Labor Amt \$70.00
Serial#	Appr Hrs 0.50 Appr Labor Amt \$70.00
Notes	

Part**Line# 1**

Item #	Description	
USERPART	shop supplies - stain remover	
Model #	Serial #	Part tag
Sub Qty 1.00	Sub Dlr Price \$3.50	Sub Freight \$0.00
Appr Qty 1.00	Appr Dlr Price \$3.50	Appr Freight \$0.00
Notes		

Labor**Line# 6**

Operation Code	Operational Description
10-11-01-00-000207	Slide Out Corner Block - Frame & Chassis/Slide Out System-Seals/Replace/No Tread Code
Complaint, Cause, Correction	

Original Note : greeneway@dealer-advisors.com, 2026-02-17 16:13:01 :: Complaint: There is exposed wood on the bottom corner of the side of the slide causing water to get onto the carpet. Cause: On all of the slides on the bottom inside corner the metal does not go all the way to the edge past the seal so there is exposed wood. Correction: Took black non-level dicor and covered the exposed wood. Additional Note : greeneway@dealer-advisors.com, 2026-02-17 16:14:46 :: Unsure on correct code.

Model#	Dlr Sub Hrs	1.00	Sub Labor Amt	\$140.00
Serial#	Appr Hrs	1.00	Appr Labor Amt	\$140.00

Notes

Part Line#	1	Item #	Description	Serial #	Part tag
		USERPART	DCR551LSB-1 dicor non-leveling/non-sag lap sealant black		
		Model #			
		Sub Qty	1.00	Sub Dlr Price	\$8.72
		Appr Qty	1.00	Appr Dlr Price	\$8.72
				Sub Freight	\$0.00
				Appr Freight	\$0.00

Notes

Submitted			Approved		
	Labor Amt	\$462.00		Labor Amt	\$364.00
	Parts & Freight	\$89.94		Parts & Freight	\$89.94
	Total	\$551.94		Total	\$453.94

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.