



Warranty Claim Form

Date: 4/16/2026

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573FR3128R3350305
Reflection 270BN
Retail Purchase Date: 4/29/2025
Work Started: 1/30/2026
Work Completed: 4/10/2026

Claim Status: Paid
Dealer Work Order #: 13204
Unit Offline Date: 5/13/2024

Claim #: 979965
Labor: \$560.00
Parts: \$736.36
Shipping: \$30.00
Total: \$1380.04

Notes: RJ 02/02/2026 *Please hold all parts for a minimum of 30 days after claim is paid*

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Customer Information

SHARON ROKUS
1911 90TH STREET N
WISCONSIN RAPIDS, Wisconsin
54494
United States
7155709271

Operation Line # 1

Flat Rate Code: 120021 Brakes - R & R ABS Controller

Fault Code: Improper Installation/Build

Problem: Brake lights are not working.

Hours: 4

Cause: Lowered underbelly, found clip for harness that goes towards front of the camper broken, also when testing lights, the 7-way gets hot but all exterior lights come on when using left or right brake lights and lights flashing.

Amount: 560.00

Remedy: Will need new harness and ABS control module. 2 hours for underbelly, 0.5 hour for module and 1.5 hours for wiring harness. 4 hours total

Sublet Repairs: \$0.00

Manufacturer #: 1

Model #: 1

Serial #: 1

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
120376 WIRE HARNESS 25' ABS MAIN	WIRE HARNESS 25' ABS MAIN		1	1	139.31
120308 ABS CONTROLLER ASSEMBLY	ABS CONTROLLER ASSEMBLY		1	1	597.05

Operation Line # 2

Flat Rate Code: 950003 Misc Charges - Packaging/Handling *Fault Code:* No Problem Identified
Fee

Problem: Invoice 1536699 - \$37.61 Invoice 1537520 - \$16.07

Hours: 0

Cause: Invoice 1536699 - \$37.61 Invoice 1537520 - \$16.07

Amount: 0.00

Remedy: Invoice 1536699 - \$37.61 Invoice 1537520 - \$16.07

Sublet Repairs: \$53.68

Manufacturer #:

Model #:

Serial #: