

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13210B

Date In: 19 FEB 26 Author: KOTT
Promised Date: 04 JUL 26 Stock No: 11558
: Year: 2026
Customer Name: 17917 - WEBER, MITCHEL Manufacturer: GRAND DESIGN
Address: 1009 PROSPECT ST Brand: TRANSCEND XPLOR
: NEILLSVILLE, WI Model: 22RBX
Postal/Zip: 54456 Miles/Hrs: 0
Phone#(res): 520-275-4377 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: MITCHEWEBER@GMAIL.COM Tag#: PU@ST-
Purchased Date: 23 OCT 25 :
Delivery Date: 04 JUL 26 :
InService Date: :
Serial#: 573TT2729T8844205 :

Job #	Description	JOB INFORMATION	Type	Bill To
WARR	COMPLAINT: WARRANTY REPAIR 1 - Water flow on city and fresh tank is very weak CAUSE: It was only the pumped water flow that was weak pump needed adjustment CORRECTION: I removed panel and used Allen wrench to adjust the pumps pressure then tested water flow and all faucets and toilet has good pressure now I put the panel back on REQ: .20		W	1020 GRAND
WARR	COMPLAINT: WARRANTY REPAIR 2 - Wall is cracked behind booth seat CAUSE: Crack in wall panel CORRECTION: I first used very fine sand paper and sand sharp edge then used glue and glued the panel down then used putty to blend REQ" .30		W	1020 GRAND
WARR	COMPLAINT: WARRANTY REPAIR 3 -Edge of slider door to bedroom has a scrape CAUSE: Scrape CORRECTION: Used wood marker to cover REQ: .10		W	1020 GRAND
WARR	COMPLAINT: WARRANTY REPAIR 4 - Deep staple holes in all cabinets and a few walls CAUSE: Deep holes in wall from staples CORRECTION: Used putty to fill holes REQ: .40		W	1020 GRAND
WARR	COMPLAINT: WARRANTY REPAIR 5 - All 6 white ceiling trim have black scuffs stains or scratches CAUSE: Mfg left black marks on white ceiling		W	1020 GRAND

Continued on page 2

Work Order : 13210B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
      trim
CORRECTION: Used quick solve and a cloth to remove
the stains REQ: .50
WARR    COMPLAINT:  WARRANTY REPAIR 6 - Bedroom door does   W    1020   GRAND
not close evenly and the magnets do not
line up
CAUSE:    Door not aligned
CORRECTION: I removed the fascia then I was able to
access the rollers to adjust them now
magnets line up and almost no gap at top
or bottom of slider door to bedroom
REQ: .40 HOURS
WARR    COMPLAINT:  WARRANTY REPAIR 7 - Wall behind kitchen W    1020   GRAND
sink has a bump sticking out of it
CAUSE:    Bump in wall Unable to do anything
about this
CORRECTION: ONLY WANT NOTED WITH MFG IN CASE FUTURE
CUSTOMER DECIDES THEY MAY WANT PANEL
CHANGED
WARR    COMPLAINT:  WARRANTY REPAIR 8 - Panel on back of     W    1020   GRAND
booth seat bottom edge is all chewed up
and lifting
CAUSE:    Mfg bent panel when installing causing
it to peel
CORRECTION: I found some decor tape that matches ,I
measured and cut batten strip then
retaped to match and batten will cover
the damaged area I pin nailer into place
REQ: .50
WARR    COMPLAINT:  WARRANTY REPAIR 9 - where panel and trim W    1020   GRAND
meet next to the shower it looks
unfinished and gap uneven
CAUSE:    Gap and rough edge between wall and trim
next to shower
CORRECTION: I used putty to fill the gap then wiped
down with murpheys oil soap to clean
away any excess REQ: .30

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR01 Z992     MISC LABOUR CODE (WARR HOD W-1020  0.50  140.00  70.00
ARR01 Z992     MISC LABOUR CODE (WARR HOD W-1020  0.00  140.00   0.00
ARR01 Z992     MISC LABOUR CODE (WARR HOD W-1020  0.49  140.00  68.60
ARR02 Z992     MISC LABOUR CODE (WARR HOD W-1020  0.01  140.00   1.40
ARR03 Z992     MISC LABOUR CODE (WARR HOD W-1020  0.49  140.00  68.60
ARR03 Z992     MISC LABOUR CODE (WARR HOD W-1020  0.01  140.00   1.40
ARR04 Z992     MISC LABOUR CODE (WARR HOD W-1020  0.47  140.00  65.80
ARR04 Z992     MISC LABOUR CODE (WARR HOD W-1020  0.03  140.00   4.20

```

Continued on page 3

Work Order : 13210B

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1020    0.00   140.00    0.00
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1020    0.03   140.00    4.20
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1020    0.47   140.00   65.80
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1020    0.49   140.00   68.60
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1020    0.01   140.00    1.40
ARR07 Z992      MISC LABOUR CODE (WARR HOD W-1020    0.03   140.00    4.20
ARR07 Z992      MISC LABOUR CODE (WARR HOD W-1020    0.00   140.00    0.00
ARR08 Z992      MISC LABOUR CODE (WARR HOD W-1020    0.11   140.00   15.40
ARR08 Z992      MISC LABOUR CODE (WARR HOD W-1020    0.39   140.00   54.60
ARR09 Z992      MISC LABOUR CODE (WARR HOD W-1020    0.50   140.00   70.00
*****
```

```
*****
Job #  Excode    Description  EXTRAS      bill to    Qty    Price    Total
*****
ARR01  SSE        SHOP SUPPLIES - EXTERNAL  W-1020    1.00    0.00    0.00
*****
```

BILLINGS SUMMARY

```
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
W      1020      0.00    564.20    0.00    0.00    0.00    564.20
*****
Totals      0.00    564.20    0.00    0.00    0.00    564.20
*****
```

&k2S
&k0S