



Warranty Claim Form

Date: 4/2/2026

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573FR3321F3302847

Reflection 303RLS

Retail Purchase Date: 3/31/2015

Work Started: 3/24/2026

Work Completed: 3/25/2026

Claim Status: Paid

Dealer Work Order #: 13286

Unit Offline Date: 3/11/2015

Claim #: 976781

Labor: \$0.00

Parts: \$0.00

Shipping: \$0.00

Total: \$461.69

Notes: Per CW - ok to approve as a onetime dealer courtesy. please note for future, we will need the labor and the parts to be separated. RL 4/1/26 **sent email to CW - 3/30/26 cc-3/27/26 sublet completed repairs dealer reviewed no visible cracks in welds approve sublet repair 461.69 *****

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Customer Information

Calvin Brockman
603 Sherman St
Mauston, Wisconsin 53948-1168
United States
608-547-1436

Operation Line # 1

Flat Rate Code: 920015 - Customer Satisfaction Campaign - Web Crack *Fault Code:* TSB
Inspection Solitude 310GK/Reflection 303RLS

Problem: Customer received letter that their unit is affected by campaign.

Hours: 0

Cause: inspected customers unit for the recall. the unit looks good. there are no cracks in the frame and the reinforcement will not be needed. v brackets have been installed and all looks correct.

Amount: 0.00

Remedy: V brackets have been installed by sublet.

Sublet Repairs:
\$461.69

Manufacturer #:

Model #:

Serial #: