

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 5781B

Date In:	20 MAR 23	Author:	TPASSER
Promised Date:	31 DEC 24	Stock No:	10071
:	:	Year:	2022
Customer Name:	475 - HOGLUND, DOUGLAS	Manufacturer:	FOREST RIVER
Address:	1669 NELSON RD	Brand:	SIERRA DESTINATION
:	NEW LENNOX, IL	Model:	399LOFT
Postal/Zip:	60451	Miles/Hrs:	0
Phone#(res):	708-878-5432	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	DHOGLUND7@GMAIL.COM	Tag#:	1/30 UPDATED CUSTOMER
Purchased Date:	30 AUG 22	:	:
Delivery Date:	26 MAY 23	:	:
InService Date:	:	:	:
Serial#:	4X4TSES23NJ050728	:	:

Job #	Description	JOB INFORMATION	Type	Bill To
WARR	COMPLAINT:	WARRANTY REPAIR 1 - BATHROOM SINK HAS FINISH RUBBING OFF	W	1021 FORES
	CAUSE:	not the correct sink		
	CORRECTION:	remove the drain pipe ,water lines and the faucet from bathroom sink secured new sink into place silicone the seam around the opening for sink tested water lines and drain for leaks after repairs now ok		
WARR	COMPLAINT:	WARRANTY REPAIR 2 - WOOD NEXT TO FIREPLACE IS SPLIT	W	1021 FORES
	CAUSE:	MFG		
	CORRECTION:	REMOVED OVEN TO REMOVE THE STILE AND REATTCH STILE		
WARR	COMPLAINT:	WARRANTY REPAIR 3 - STAPLES VISIABLE ABOVE FIREPLACE	W	1021 FORES
	CAUSE:	MFG		
	CORRECTION:	REMOVED STAPLE FILLED HOLE WITH PUTTY		
WARR	COMPLAINT:	WARRANTY REPAIR 4 - LINO TORN IN FRONT OF BED	W	1021 FORES
	CAUSE:	MFG		
	CORRECTION:	FIXED FLOOR AND BLENDED COLOR		
WARR	COMPLAINT:	WARRANTY REPAIR 5 - WHOLE INTERIOR TRIM HAS STAPLES POPPING UP, NAIL HOLES, TRIM THAT NEEDED TO BE PUTTIED	W	1021 FORES
	CAUSE:	MFG		
	CORRECTION:	REPAIRED ALL HOLES, STAPLES AND FULLLED WITH MATCHING PUTTY		

Continued on page 2

Work Order : 5781B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 6 - BEDROOM DRESSER           W    1021    FORES
          DRAWER NEEDS TO BE PUTTIED AND COLOR
          BLENDED
          CAUSE:      the drawers manufacturer sent us are
          wrong size pic and measurements taken
          CORRECTION: remove and install two top drawer
          fronts in master bedroom dresser now ok
WARR    COMPLAINT:  WARRANTY REPAIR 7 - BEDROOM CEILING           W    1021    FORES
          ABOVE HEADBOARD IS ALL BUBBLED
          CAUSE:      MFG
          CORRECTION: USED BATTEN STRIP TO COVER
WARR    COMPLAINT:  WARRANTY REPAIR 8 - VENT COVER GOING TO       W    1021    FORES
          THE UPSTAIRS ID DENTED IN.
          CAUSE:      MFG
          CORRECTION: NEED NEW VENT COVER 13 3/4 X 7 3/4
WARR    COMPLAINT:  WARRANTY REPAIR 9 - BATHROOM CUBBYS HAVE W    1021    FORES
          BIG CHIPS
          CAUSE:      MFG
          CORRECTION: PUTTIED AND BLENDED CHIPS
WARR    COMPLAINT:  WARRANTY REPAIR 10 - INSIDE OF THE            W    1021    FORES
          BATHROOM DOOR NEEDS TO BE PUTTIED AND
          COLOR BLENDED
          CAUSE:      MFG
          CORRECTION: PUTTIED AND COLORS BLENDED
WARR    COMPLAINT:  WARRANTY REPAIR 11 - BEDROOM COUNTER IS       W    1021    FORES
          SCUFFED UP
          CAUSE:      pics taken counter top gor master
          bedroom correct size but wrong color
          CORRECTION: wrong color counter top for master
          bedroom will need another one
WARR    COMPLAINT:  WARRANTY REPAIR 15 - FRAME AROUND            W    1021    FORES
          BATHROOM DOOR- TRIM IS PEELING OFF
          CAUSE:      MFG
          CORRECTION: LIGHTLY SANDED AND COLOR MATCHED
WARR    COMPLAINT:  WARRANTY REPAIR 16- MISSING BATTEN STRIP W    1021    FORES
          ABOVE CUBBOARD IN KITCHEN
          CAUSE:      MFG
          CORRECTION: CUT AND SECURED BATTEN STRIP

```

```

*****
Job # Part No   Description           PARTS           Bill to   Qty    Price    Total
*****
WARR0 82203112  SINK, 12" ROUND LAV BOWL, W W-1021      0      40.99     0.00
WARR0 82204517  SINK, W14173 14" X 17" PLAS W-1021      1      38.91    38.91
WARR0 82209746  DRAWER FRONT, 7" X 27" MAPU W-1021      1      24.97    24.97
WARR0 82209746  DRAWER FRONT, 7" X 27" MAPU W-1021      1      24.97    24.97
WARR0 82209755  DRAWER FRONT, 10" X 27" MAP W-1021      0      31.15     0.00
WARR0 82206205  VENT, METAL RETURN AIR GRIL W-1021      1       6.89     6.89
WARR1 822041584 DRESSER TOP SIERRA           W-1021      1     158.30   158.30

```

Continued on page 3

Work Order : 5781B

Job#	Lab Code	Description	LABOUR	Mech	Bill to	Hrs	Rate	Total

ARR01	Z992	MISC LABOUR CODE (WARR JT			W-1021	0.50	105.00	52.50
ARR01	WARR	MANUFACTURER WARRANTY JS			W-1021	0.50	115.00	57.50
ARR01	Z992	INSTALL BATHROOM SINK JS			W-1021	0.13	115.00	14.95
ARR02	Z992	MISC LABOUR CODE (WARR JT			W-1021	0.50	105.00	52.50
ARR03	Z992	MISC LABOUR CODE (WARR JT			W-1021	0.50	105.00	52.50
ARR04	Z992	MISC LABOUR CODE (WARR JT			W-1021	0.50	105.00	52.50
ARR05	Z992	MISC LABOUR CODE (WARR JT			W-1021	0.50	115.00	57.50
ARR06	Z992	MISC LABOUR CODE (WARR JT			W-1021	0.50	115.00	57.50
ARR06	WARR	MANUFACTURER WARRANTY JS			W-1021	0.36	115.00	41.40
ARR06	WARR	MANUFACTURER WARRANTY JS			W-1021	0.14	115.00	16.10
ARR06	WARR	MANUFACTURER WARRANTY			W-1021	0.00	115.00	0.00
ARR07	Z992	MISC LABOUR CODE (WARR JT			W-1021	0.50	115.00	57.50
ARR08	Z992	MISC LABOUR CODE (WARR JT			W-1021	0.50	115.00	57.50
ARR08	Z992	MISC LABOUR CODE (WARR			W-1021	0.00	115.00	0.00
ARR09	Z992	MISC LABOUR CODE (WARR JT			W-1021	0.50	115.00	57.50
ARR10	Z992	MISC LABOUR CODE (WARR JT			W-1021	0.50	115.00	57.50
ARR11	Z992	MISC LABOUR CODE (WARR JT			W-1021	0.50	115.00	57.50
ARR11	Z992	MISC LABOUR CODE (WARR JS			W-1021	1.00	115.00	115.00
ARR11	Z992	INSTALL COUNTERTOP IN JS			W-1021	1.00	115.00	115.00
ARR15	Z992	MISC LABOUR CODE (WARR JT			W-1021	0.50	115.00	57.50
ARR16	Z992	MISC LABOUR CODE (WARR JT			W-1021	0.50	115.00	57.50
ARR01	Z992	INSTALL BATHROOM SINK JS			W-1021	0.20	115.00	23.00
ARR01	Z992	INSTALL BATHROOM SINK JS			W-1021	0.17	115.00	19.55

Job #	Excode	Description	EXTRAS	bill to	Qty	Price	Total

ARR01	FRT	FREIGHT		W-1021	1.00	18.44	18.44
ARR06	FRT	FREIGHT		W-1021	1.00	19.29	19.29
ARR06	FRT	FREIGHT		W-1021	1.00	19.32	19.32
ARR08	FRT	FREIGHT		W-1021	1.00	18.44	18.44
ARR11	FRT	FREIGHT		W-1021	1.00	36.57	36.57
ARR11	FRT	FREIGHT		W-1021	1.00	36.38	36.38

BILLINGS SUMMARY							
Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total

W	1021	254.04	1130.00	0.00	148.44	0.00	1,532.48
Totals		254.04	1130.00	0.00	148.44	0.00	1,532.48

&k2S

&k0S