

DEALER ACCOUNT #	0009497	CLAIM STATUS	Paid
GREENEWAY INC		CLAIM	1928237
DBA GREENEWAY RV SALES & SERVICE		CLAIM ORIGIN	WEB
8220 STATE HWY 13 SOUTH		ORIGINAL CLAIM ID	
WISCONSIN RAPIDS, WI 54494		VIN	5ZT2FSHC8P3027066
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$115.00	SITE/WAREHOUSE	010 / 010G
OWNER INFORMATION		ITEM #	FLTE19FBS
		DEALER RO #	7280B
		CLAIM START DATE	05/23/2024
		CLAIM END DATE	06/03/2024
Retail Date of Purchase		WARRANTY EXPIRATION DATE	

Labor			
Line# 1	Operation Code	Operational Description	
	30-100-24-00-001050	Cabinet Stiles - Interior/Cabinetry/Repair/No Tread Code	
	Complaint, Cause, Correction		
	Original Note : greeneway@dealer-advisors.com, 2024-05-23 14:10:14 :: Complaint: There is a chip in the wood trim below the microwave. Cause: Chip in wood below the microwave. Correction: Filled in with putty.		
Model#	Dlr Sub Hrs	0.50	Sub Labor Amt \$57.50
Serial#	Appr Hrs	0.30	Appr Labor Amt \$34.50
	Notes		
	authorized for .30 based on information provided. Thank you.		

Labor Line# 2	Operation Code		Operational Description	
	30-100-24-00-001050		Cabinet Stiles - Interior/Cabinetry/Repair/No Tread Code	
	Complaint, Cause, Correction			
	Original Note : greeneway@dealer-advisors.com, 2024-05-23 14:23:24 :: Complaint: Chip in wood next to stove.			
	Cause: Chip is in the wood next to the stove. Correction: Filled with putty.			
Model#	Dlr Sub Hrs	0.50	Sub Labor Amt	\$57.50
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$34.50
Notes				
authorized for .30 based on information provided. Thank you.				

Labor Line# 3	Operation Code		Operational Description	
	70-178-01-00-002141		Range-Stove Top Burner - Appliances/Range (Suburban)/Replace/No Tread Code	
	Complaint, Cause, Correction			
	Original Note : greeneway@dealer-advisors.com, 2024-05-23 14:28:19 :: Complaint: Scratch on stove top. Cause: Scratched stove top. Correction: Got new stove top from parts, went out to lot and swapped them out.			
	Model#	0000	Dlr Sub Hrs	0.50
Serial#	00000	Appr Hrs	0.40	Appr Labor Amt \$46.00
	Notes			
	authorized for .40 based on information provided. Thank you.			

Part					
Line# 2	Item #	Description			
	F100322101	RANGE PART - 5Q-2: STOVE TOP COVER, GLASS, W/ ATTACHED BLACK TRAY AND SILVER TRIM - 21" - V# MCFR21TTB: GLASS TOP/NEW STYLE XN			
	Model #	Serial #	Part tag		
	Sub Qty 1.00	Sub Dlr Price \$89.49	Sub Freight	\$34.09	
	Appr Qty 1.00	Appr Dlr Price \$89.49	Appr Freight	\$34.09	

Notes

Labor

Line# 4	Operation Code	Operational Description		
	30-99-01-00-001030	Valance - Interior/Soft Goods/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : greeneway@dealer-advisors.com, 2024-05-23 15:56:52 :: Complaint: Fireproof valance is scratched above sink and stove. Cause: Scratched valance over sink and stove. Correction: Install new valance.			
	Model#	Dlr Sub Hrs	0.50	Sub Labor Amt \$57.50
	Serial#	Appr Hrs	0.20	Appr Labor Amt \$23.00

Notes
authorized for .20 based on information provided. Thank you.

Part

Line# 4	Item #	Description			
	F100211546	VALANCE - PFL: STEEL - 52" - V# 25053 X			
	Model #	Serial #	Part tag		
	Sub Qty	1.00	Sub Dlr Price	\$18.92	Sub Freight \$18.44
	Appr Qty	1.00	Appr Dlr Price	\$19.53	Appr Freight \$18.44

Notes
Hello, please note part cost has been adjusted to the Sales order S3516758, Thank you

Submitted	Labor Amt	\$230.00	Approved	Labor Amt	\$138.00
	Parts & Freight	\$160.94		Parts & Freight	\$161.55
	Total	\$390.94		Total	\$299.55

DEALER _____ DATE _____
SIGNATURE
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE
All repairs described have been inspected and are satisfactory.