

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 7348B

Date In: 22 FEB 23 Author: KOTT
Promised Date: 25 DEC 25 Stock No: 10743
: Year: 2023
Customer Name: 16832 - BERGSTRESER, J Manufacturer: GRAND DESIGN
Address: N1373 WEST HAVEN DRIVE Brand: REFLECTION 150 SERIES
: GREENVILLE, WI Model: 278BH
Postal/Zip: 54942 Miles/Hrs: 0
Phone#(res): 9204504679 Exterior Color:
Phone#(bus): Unit Type: FW-FIFTH WHEEL
Cell Phone: License#:
Email: jbergstreser@hotmail.c Tag#: sent email with refer
Purchased Date: 28 APR 23 :
Delivery Date: 23 MAY 23 :
InService Date: :
Serial#: 573FR3427P3344472 :

Job # Description JOB INFORMATION Type Bill To

DAF COMPLAINT: DAF-WARRANTY REPAIRS- 1. REFER DOESNT I PDI PRE-D
STAY LATCHED- 2. TRIM AROUND ENTRY DOOR
IS TOO SHORT 3. DOOR ON CONTROL CENTER
IS GOUGED IN THE INSIDE 4. OUTSIDE GRILL
IS SCRATCHED AND RUSTY 5. ODS BAGGAGE
LOCK WILL NOT UNLOCK
CORRECTION: REPAIRS WILL BE ON SEPERATE LINES
WARR COMPLAINT: Skylight cracked W 1020 GRAND
CAUSE: Cracked skylight
CORRECTION: Had to replace with a new one from parts
and resealed with 2 tubes of dicor
WARR COMPLAINT: Storage tray is cracked W 1020 GRAND
CAUSE: R&R cracked baggage tray. (1.5hr.)
CORRECTION: Replaced baggage tray with provided
warranty part. Took some extra time to
swap in cord access from damaged tray.
WARR COMPLAINT: Outside griddle is scratched dented and W 1020 GRAND
has rust
CAUSE: Warranty replace griddle (1hr)
CORRECTION: Removed damaged griddle. One screw was
overtightened and had to be drilled.
Had to scrape all the fat off the tray
that collected at bottom. Swapped LP
hose, fastened new griddle tested
burner. And performed leak check. Tested
ok.
WARR COMPLAINT: Plastic black trim piece for sildeout is W 1020 GRAND
cracked

Continued on page 2

Work Order : 7348B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
      CAUSE:      Silde out trim is cracked
      CORRECTION: Got a new one from parts and installed
                  and sealed up
WARR    COMPLAINT: Cabinet door above microwave has holes   W    1020    GRAND
                  in it
      CAUSE:      Warranty replacement cabinet door  (1hr)
      CORRECTION: Removed cabinet door, removed all
                  hardware including hinges anchors,
                  hinges, handle, and door catch.  Used
                  jig to align and drill countersunk/euro
                  hinges, drill and mount hinges anchors,
                  attach hinges, drill and attach handle,
                  align and attach door catch.
WARR    COMPLAINT: Door for control center is gouged and     W    1020    GRAND
                  cracked
      CAUSE:      Door ordered is wrong size. Order
                  correct size. Correct door measures
                  33-1/2"T x 13"W  (1hr)    Order part
                  #661773
      CORRECTION: Brought coach into shop 2/3/25, removed
                  cabinet door, removed hardware for
                  reuse, drilled new hardware holes for
                  fresh cabinet door using concealed hinge
                  jig, place door pull and latch.
                  Reinstall and test. Looks nice
WARR    COMPLAINT: Bathroom cabinet door over toilet has     W    1020    GRAND
                  damage
      CAUSE:      Warranty replacement of cabinet door
                  above toilet
      CORRECTION: Removed cabinet door, removed all
                  hardware including hinges anchors,
                  hinges, handle, and door catch.  Used
                  jig to align and drill countersunk/euro
                  hinges, drill and mount hinges anchors,
                  attach hinges, drill and attach handle,
                  align and attach door catch.  Installed
                  new glass mirror.
WARR    COMPLAINT: Pine pitch on the roof                     W    1020    GRAND
      CAUSE:      Pine pitch or something on the roof
      CORRECTION: Got some roof cleaner and cleaned as
                  much off as I could
WARR    COMPLAINT: Solar charger is inop                       W    1020    GRAND
      CAUSE:      Warranty replacement
      CORRECTION: Replaced per warranty request
1        Transferred to GRV*7348C on 04 FEB 25 Estimate      E    16832    BERGS
      amount was 0.00 REFER HANDLE DAMAGED

```

Continued on page 3

Work Order : 7348B

Job #	Part No	Description	PARTS	Bill to	Qty	Price	Total

WARR0	822040156	SKYLIGHT 14 X 30 SMOKE L	W-1020		1	45.92	45.92
WARR0	677917000333	10.3oz TUBE LAP SEALANT	W-1020		2	8.02	16.04
WARR0	050391158316	BUTYL TAPE 1/8"X3/4"X30'	W-1020		1	9.65	9.65
WARR0	82200538	SADDLE BOX 39" BLACK ABS	W-1020		1	98.46	98.46
WARR0	8220721053	COOKTOP GRIDDLE 2 BURNER	W-1020		1	235.69	235.69
WARR0	82200422	S/O BOTTOM CAP TALL BLAC	W-1020		1	7.58	7.58
WARR0	82202288	DOOR CABINET 14 X 16 BRO	W-1020		1	37.14	37.14
WARR0	82201773	DOOR CABINET 13 X 33 1/2	W-1020		1	64.39	64.39
WARR0	82201698	DOOR CABINET CHSQ 24 x 2	W-1020		0	46.66	0.00
WARR0	82201561	MIRROR 1/8 X 19 1/2 X 19	W-1020		1	21.86	21.86
WARR0	82201752	DOOR CABINET 24 x 24 BRO	W-1020		1	37.52	37.52
WARR1	82200831	SOLAR CHARGE CONTROLLER	W-1020		1	327.39	327.39
1	06-6007	FURRIION DOOR LATCH PARTS	E-16832		0	24.07	0.00

Job#	Lab Code	Description	LABOUR	Mech Bill to	Hrs	Rate	Total

DAF	Z991	DAF-WARRANTY REPAIR	CF	I-PDI	0.10	70.00	7.00
ARR02	Z992	MISC LABOUR CODE (WARR	CF	W-1020	0.10	115.00	11.50
ARR02	Z992	MISC LABOUR CODE (WARR	CF	W-1020	0.40	115.00	46.00
ARR03	Z992	MISC LABOUR CODE (WARR	RW	W-1020	0.00	115.00	0.00
ARR03	Z992	MISC LABOUR CODE (WARR	CF	W-1020	0.05	115.00	5.75
ARR03	Z992	MISC LABOUR CODE (WARR	RW	W-1020	0.45	115.00	51.75
ARR04	Z992	MISC LABOUR CODE (WARR	RW	W-1020	0.42	115.00	48.30
ARR04	Z992	MISC LABOUR CODE (WARR	CF	W-1020	0.08	115.00	9.20
ARR05	Z992	MISC LABOUR CODE (WARR	CF	W-1020	0.03	115.00	3.45
ARR05	Z992	MISC LABOUR CODE (WARR	CF	W-1020	0.47	115.00	54.05
ARR06	Z992	MISC LABOUR CODE (WARR	RW	W-1020	0.44	115.00	50.60
ARR06	Z992	MISC LABOUR CODE (WARR	CF	W-1020	0.06	115.00	6.90
ARR07	Z992	MISC LABOUR CODE (WARR	RW	W-1020	0.37	115.00	42.55
ARR07	Z992	MISC LABOUR CODE (WARR	CF	W-1020	0.06	115.00	6.90
ARR07	Z992	MISC LABOUR CODE (WARR	RW	W-1020	0.07	115.00	8.05
ARR07	Z992	MISC LABOUR CODE (WARR	RW	W-1020	0.00	115.00	0.00
ARR08	Z992	MISC LABOUR CODE (WARR	RW	W-1020	0.00	115.00	0.00
ARR08	Z992	MISC LABOUR CODE (WARR	CF	W-1020	0.07	115.00	8.05
ARR08	Z992	MISC LABOUR CODE (WARR	RW	W-1020	0.43	115.00	49.45
ARR09	Z992	MISC LABOUR CODE (WARR	CF	W-1020	0.50	115.00	57.50
ARR10	Z992	MISC LABOUR CODE (WARR	RW	W-1020	0.49	115.00	56.35
ARR10	Z992	MISC LABOUR CODE (WARR	CF	W-1020	0.01	115.00	1.15
1	RV16Q-3	REFRIGERATOR DOOR HAND	RW	E-16832	0.00	140.00	0.00
ARR07	Z992	MISC LABOUR CODE (WARR	RW	W-1020	0.50	115.00	57.50
ARR07	Z992	MISC LABOUR CODE (WARR	RW	W-1020	0.00	115.00	0.00

Job #	Excode	Description	EXTRAS	bill to	Qty	Price	Total

ARR04	FRT	FREIGHT		W-1020	1.00	28.97	28.97
ARR06	FRT	FREIGHT FOR JOBS 6,7&8		W-1020	0.00	0.00	0.00
ARR07	FRT	FREIGHT		W-1020	1.00	28.54	28.54

Continued on page 4

Work Order : 7348B

```

*****
Job #  Excode   Description  EXTRAS      bill to    Qty    Price    Total
*****
ARR10  FRT      FREIGHT      W-1020     1.00    16.14    16.14
ARR10  FRT      FREIGHT      W-1020     1.00    14.45    14.45

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras      Tax      Total
*****
I      PDI          0.00      7.00      0.00      0.00      0.00      7.00
W      1020         901.64    575.00     0.00     88.10     0.00    1,564.74

      Totals        901.64    582.00     0.00     88.10     0.00    1,571.74

```

&k2S
&k0S