

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 7597E

|                 |                        |                 |                   |
|-----------------|------------------------|-----------------|-------------------|
| Date In:        | 03 APR 23              | Author:         | MGRAY             |
| Promised Date:  | 25 DEC 24              | Stock No:       | 10523             |
| :               | :                      | Year:           | 2023              |
| Customer Name:  | 16534 - STEGEHUIS, RIC | Manufacturer:   | GRAND DESIGN      |
| Address:        | W3144 THIESEN LANE     | Brand:          | IMAGINE XLS       |
| :               | HELENVILLE, WI         | Model:          | 22MLE             |
| Postal/Zip:     | 53137                  | Miles/Hrs:      | 0                 |
| Phone#(res):    | 262-443-5192           | Exterior Color: | :                 |
| Phone#(bus):    | :                      | Unit Type:      | TT-TRAVEL TRAILER |
| Cell Phone:     | :                      | License#:       | :                 |
| Email:          | rstegehuis6262@gmail.c | Tag#:           | :                 |
| Purchased Date: | 09 SEP 22              | :               | :                 |
| Delivery Date:  | 14 OCT 22              | :               | :                 |
| InService Date: | :                      | :               | :                 |
| Serial#:        | 573TE2628P3430721      | :               | :                 |

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
7       COMPLAINT:  ADDED-4/3-CUSTOMER STATES THAT THE          W    1020    GRAND
          LADDER ON THEIR UNIT HAS CRACKED-
          CAUSE:      CUSTOMER WOULD LIKE TO HAVE LOOKED AT-
          Ladder cracked. I inspected the ladder
          and verified that it's the correct one
          this time. I removed the screws in the
          legs, cut the dicor around the top legs,
          and removed the ladder. I cleaned the
          area where the feet sit, puttied the new
          ladder, and put it on. I dicored around
          the top and siliconed around the ones
          attached to the wall.
          CORRECTION: Replacement ladder came in damaged. Anna
          reordered. Done.
RI      COMPLAINT:  PREFORM ROOF INSPECTION AND ADVISE IF      I    SEP    POLIC
          REPAIR IS NEEDED. CUSTOMER NOTICED SMALL
          BUBBLES ALONG EDGE OF ROOF WHICH IS
          POSSIBLY NORMAL BUT WANTS THAT CHECKED
          AS WELL. CHECK TO SEE IF SEALANT IS GOOD
          AROUND MAX AIR FAN AT SCREW HEADS
          CUSTOMER THOUGHT WAS THIN AMOUNT AND WE
          INSTALLED FAN AT TIME OF PURCHASE.
          CAUSE:      1001 CUSTOMER REQUESTED
          CORRECTION: The dicor was thin in spots co I cleaned
          and sealed over it. I found a few other
          spots in the roof that I cleaned and
          sealed and I found three spots where it
          looks like staples are starting to pop
*****
```

Continued on page 2

Work Order : 7597E

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
                                up under the fabric
1      COMPLAINT:  CUSTOMER REQUESTS THE MAIN ENTRY DOOR      W      1020      GRAND
                                LOCK AND HANDLE BE LOOKED AT- DEADBOLT,
                                AND HANDLE NOT WORKING CORRECTLY.
                                DEADBOLT DOESN'T EXTEND OUT ALL THE WAY
      CAUSE:        The dead bolt was hitting the wall and
                                couldn't fully extend
      CORRECTION:  Drilled out the hole and painted it
                                black

```

```

*****
Job # Part No  Description          PARTS          Bill to  Qty    Price    Total
*****
7      822010498 LADDER EXTERIOR 12 X 95 1/2 W-1020      1      154.26    154.26

```

```

*****
Job#  Lab Code  Description          LABOUR    Mech Bill to    Hrs    Rate    Total
*****
  7  WARR      MANUFACTURER WARRANTY  JGK    W-1020      0.00    115.00     0.00
  7  WARR      MANUFACTURER WARRANTY  TD     W-1020      0.02    115.00     2.30
RI Z991  PREFORM ROOF INSPECTIO  I-SEP      0.00     70.00     0.00
  1  WARR      MANUFACTURER WARRANTY  JGK    W-1020      0.50    115.00    57.50
  7  WARR      MANUFACTURER WARRANTY  JGK    W-1020      0.48    115.00    55.20
RI Z991  PREFORM ROOF INSPECTIO  JGK    I-SEP      0.22     70.00    15.40
  7  WARR      MANUFACTURER WARRANTY  JGK    W-1020      0.00    115.00     0.00

```

```

*****
Job #  Excode   Description          EXTRAS          bill to    Qty    Price    Total
*****
  7  FRT        FREIGHT              W-1020      1.00    161.76    161.76
  7  FRT        FREIGHT FOR JOB 7 REPLACEM W-1020      1.00    162.49    162.49
  1  SSE        SHOP SUPPLIES - EXTERNAL  W-1020      1.00     0.00     0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
I      SEP          0.00     15.40     0.00     0.00     0.00     15.40
W      1020        154.26    115.00     0.00    324.25     0.00    593.51

      Totals        154.26    130.40     0.00    324.25     0.00    608.91

```

&k2S  
&k0S