



# Warranty Claim Form

Date: 2/11/2025

1127 Greenway RV Sales & Service  
8220 State Hwy 13 South  
Wisconsin Rapids, WI 54494  
United States  
Ph. 715-325-5170  
mail@greenwayrv.com

### General Information

573FR382XP9922233  
Reflection 324MBS  
Retail Purchase Date: 3/25/2023  
Work Started: 3/13/2024  
Work Completed: 3/13/2024

Claim Status: Paid  
Dealer Work Order #: 8306C  
Unit Offline Date: 8/9/2022

Claim #: 868516  
Labor: \$115.00  
Parts: \$132.03  
Shipping: \$32.04  
Total: \$279.07

Notes: adjusted shipping to invoices. NN 2.3 Do you have an invoice for the other decal then, please? NN 1.30 Please advise, you are claiming part # 590825 twice but on different job lines. Is that correct? Adjusted costs to actual invoice costs and shipping to parts claimed off invoices. NN 1.27 JPH 1-23-25 660009 denied, was not on original PA lines 1,2 approved as a courtesy to dealer

### Dealer Information

1127 Greenway RV Sales & Service  
8220 State Hwy 13 South  
Wisconsin Rapids, WI 54494  
United States

715-325-5170  
mail@greenwayrv.com  
Approved Labor Rate: \$115.00

### Customer Information

DOUGLAS TRUDELL  
2410 WISCONSIN AVE  
PLOVER, Wisconsin 54467  
United States  
715-347-7978

### Operation Line # 1

*Flat Rate Code:* 590061 Decals - (Front & Rear Wall/Cap) - R&R Rear *Fault Code:* Damaged/Maintenance  
Decal/Logo/Die Cut

*Problem:* Customer states the front cap decal needs replacement as it is bubbling/peeling.

*Hours:* .5

*Cause:* Decals are bubbling/peeling.

*Amount:* 57.50

*Remedy:* R&R decal.

*Sublet Repairs:* \$0.00

*Manufacturer #:*

*Model #:*

*Serial #:*

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
591078 DIE CUT 33 RH REFLECTION 2021	DIE CUT 33 RH REFLECTION 2021		1	1	4.10
590825 DIE CUT 9 RH REFLECTION 2020	DIE CUT 9 RH REFLECTION 2020		1	1	26.26
591077 DIE CUT 33 LH REFLECTION 2021	DIE CUT 33 LH REFLECTION 2021		1	1	4.10

**Operation Line # 2**

Flat Rate Code: 510008 Decals - R&R Sidewall Decal/Logo/Die Fault Code: Damaged/Maintenance Cut

Problem: Decal to left of entrance door has some bubbles in it.

Hours: .5

Cause: Decal is bubbling.

Amount: 57.50

Remedy: R&R decal.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
590825 DIE CUT 9 RH REFLECTION 2020	DIE CUT 9 RH REFLECTION 2020		1	1	96.50
960204 Miscellaneous Part for claim use only	Miscellaneous Part for claim use only		1	1	1.07