

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 9862B

Date In:	12 APR 24	Author:	KOTT
Promised Date:	25 DEC 24	Stock No:	10597
:	:	Year:	2022
Customer Name:	14294 - RASMUSSEN, KEV	Manufacturer:	FOREST RIVER
Address:	7045 FRIISGARD WAY	Brand:	CEDAR CREEK COTTAGE
:	WIND LAKE, WI	Model:	40CDL
Postal/Zip:	53185	Miles/Hrs:	0
Phone#(res):	262-332-1184	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	KDRAS4@TDS.NET	Tag#:	:
Purchased Date:	20 OCT 23	:	:
Delivery Date:	12 APR 24	:	:
InService Date:	:	:	:
Serial#:	4X4TCRS24NS230301	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - Both fender skirts      W    1021    FORES
          are cracked
          CAUSE:         install two new fender skirt
          CORRECTION:    remove the damage fender skirts from
                        doorside and off doorside and re
                        attached the new fender skirts now ok
ISR0     COMPLAINT:  INTERNAL STOCK REPAIR 01 30lbs Double      W    1021    FORES
          propane tank cover missing
          CAUSE:         30 lbLp tank cover missing no picture
                        since it's missing
          CORRECTION:    Took one off puma destination vin 1869
                        will need to order new one
SC        COMPLAINT:  SERVICE CALL TO ROME -239 9TH AVE  **    W    1021    FORES
          PERMANENTLY PARKED UNIT
          CAUSE:         CUSOTMER REQUEST
          CORRECTION:    COMPLETE
1         COMPLAINT:  CMR LEFT VM 6/5 STATING HE NEEDS 2 CAMCO E    14294    RASMU
          COVERS FOR VENTS ON THE ROOF THAT HE
          WOULD LIKE TO PURCHASE AND HAVE US
          INSTALL.
          CAUSE:         the customer had purchased the wrong
                        covers pics taken he need max air covers
                        the clip on style he has three vents
                        maybe all three
          CORRECTION:    install 3 max air covers with quick pins
                        now ok
2         COMPLAINT:  CUSTOMER STATES THAT THE SLIDING PATIO    W    1020    GRAND
          DOOR IS STICKING WHEN TRYING TO SLIDE IT
```

Continued on page 2

Work Order : 9862B

```

*****
Job #      Description      JOB INFORMATION      Type Bill To
*****
                OPEN OR CLOSED- 6/18- CUSTOMER STATES
                THAT THE SLIDING DOOR HAS NOW COME OFF
                AND NEEDS TO BE PUT BACK ON- CUSTOMER
                STATES THAT IT ALMOST APPEARS THAT THE
                BOTTOM TRIM IS BENT- WOULD LIKE TO HAVE
                LOOKED AT-
    CAUSE:      screen door for entry sliding door out
                of adjustments WILL NEED .3 FOR
                ADJUSTMENTS AND REPAIR.
    CORRECTION: install the entry sliding screen door
                adjustments made to screen rollers for
                smooth operation the screen door is ok

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WARR0 822062200    FENDER SKIRT, 67", FITS      W-1021      2      32.45      64.90
ISR01 822010175    COVER, PROPANE TANK, DOU      W-1021      1      38.58      38.58
1      752055006123 FANMATE - WHITE              E-14294      3      78.17      234.51

```

```

*****
Job# Lab Code Description LABOUR Mech Bill to      Hrs      Rate      Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR JGK      W-1021      0.30      115.00      34.50
ARR01 RV30L-2    FENDERSKIRT R&R TANDEM JS      W-1021      0.30      115.00      34.50
ISR01 Z991      MISC LABOUR CODE (INTE JT      W-1021      0.10      115.00      11.50
    SC SC      SERVICE CHARGE              JS      W-1021      0.00      115.00      0.00
    1 RV31I-13d ROOF VENTS REPLACE COV JS      E-14294      0.00      140.00      0.00
    2 WARR      MANUFACTURER WARRANTY JS      W-1020      0.30      115.00      34.50
    1 RV31I-13d ROOF VENTS REPLACE COV JS      E-14294      0.80      130.00      104.00

```

```

*****
Job # Excode      Description EXTRAS      bill to      Qty      Price      Total
*****
ARR01 SSE      SHOP SUPPLIES - EXTERNAL      W-1021      1.00      7.80      7.80
ARR01 FRT      FREIGHT              W-1021      1.00      101.37      101.37
ISR01 FRT      FREIGHT              W-1021      1.00      32.94      32.94
    SC SC      SERVICE CALL              W-1021      0.00      3.75      0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
E      14294      234.51      104.00      0.00      0.00      18.63      357.14
W      1020      0.00      34.50      0.00      0.00      0.00      34.50
W      1021      103.48      80.50      0.00      142.11      0.00      326.09

Totals      337.99      219.00      0.00      142.11      18.63      717.73

```

Continued on page 3

Work Order : 9862B

&k2S
&k0S