

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 9862B

Date In: 12 APR 24 Author: KOTT
Promised Date: 20 JUN 24 Stock No: 10597
: Year: 2022
Customer Name: 14294 - RASMUSSEN, KEV Manufacturer: FOREST RIVER
Address: 7045 FRIISGARD WAY Brand: CEDAR CREEK COTTAGE
: WIND LAKE, WI Model: 40CDL
Postal/Zip: 53185 Miles/Hrs: 0
Phone#(res): 262-332-1184 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: KDRAS4@TDS.NET Tag#:
Purchased Date: 20 OCT 23 :
Delivery Date: 04 JUL 24 :
InService Date: :
Serial#: 4X4TCRS24NS230301 :

Job # Description JOB INFORMATION Type Bill To

WARR COMPLAINT: WARRANTY REPAIR 1 - Both fender skirts W 1021 FORES
are cracked
CAUSE: install two new fender skirt
CORRECTION: remove the damage fender skirts from
doorside and off doorside and re
attached the new fender skirts now ok
ISRO COMPLAINT: INTERNAL STOCK REPAIR 01 30lbs Double W 1021 FORES
propane tank cover missing
CAUSE: 30 lbLp tank cover missing no picture
since it's missing
CORRECTION: Took one off puma destination vin 1869
will need to order new one
SC SERVICE CALL TO ROME -239 9TH AVE ** PERMANENTLY W 1021 FORES
PARKED UNIT
1 COMPLAINT: CMR LEFT VM 6/5 STATING HE NEEDS 2 CAMCO E 14294 RASMU
COVERS FOR VENTS ON THE ROOF THAT HE
WOULD LIKE TO PURCHASE AND HAVE US
INSTALL.
CAUSE: the customer had purchased the wrong
covers pics taken he need max air covers
the clip on style he has three vents
maybe all three
CORRECTION: pics taken need max air covers
2 COMPLAINT: CUSTOMER STATES THAT THE SLIDING PATIO W 1020 GRAND
DOOR IS STICKING WHEN TRYING TO SLIDE IT
OPEN OR CLOSED- 6/18- CUSTOMER STATES
THAT THE SLIDING DOOR HAS NOW COME OFF
AND NEEDS TO BE PUT BACK ON- CUSTOMER

Continued on page 2

Work Order : 9862B

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
                STATES THAT IT ALMOST APPEARS THAT THE
                BOTTOM TRIM IS BENT- WOULD LIKE TO HAVE
                LOOKED AT-
    CAUSE:      screen door for entry sliding door out
                of adjustments WILL NEED .3 FOR
                ADJUSTMENTS AND REPAIR.
    CORRECTION: install the entry sliding screen door
                adjustments made to screen rollers for
                smooth operation the screen door is ok

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WARR0 822062200    FENDER SKIRT, 67", FITS W-1021      2      32.45      64.90
ISR01 822010175    COVER, PROPANE TANK, DOU W-1021      1      38.58      38.58
1      014717404334 RV ROOF VENT COVER WHITE E-14294      2      58.84      117.68

```

```

*****
Job# Lab Code Description LABOUR Mech Bill to      Hrs      Rate      Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.50      115.00      57.50
ARR01 RV30L-2    FENDERSKIRT R&R TANDEM JS W-1021      1.00      115.00      115.00
ISR01 Z991      MISC LABOUR CODE (INTE JT W-1021      0.50      115.00      57.50
    SC SC      SERVICE CHARGE JS W-1021      0.00      115.00      0.00
    1 RV31I-13d ROOF VENTS REPLACE COV JS E-14294      0.80      140.00      112.00
    2 WARR      MANUFACTURER WARRANTY JS W-1020      0.50      115.00      57.50

```

```

*****
Job # Excode      Description      EXTRAS      bill to      Qty      Price      Total
*****
ARR01 SSE      SHOP SUPPLIES - EXTERNAL W-1021      1.00      8.40      8.40
ARR01 FRT      FREIGHT W-1021      1.00      101.37      101.37
ISR01 FRT      FREIGHT W-1021      1.00      32.94      32.94
    SC SC      SERVICE CALL W-1021      0.00      3.75      0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
E      14294      117.68      112.00      0.00      0.00      12.64      242.32
W      1020      0.00      57.50      0.00      0.00      0.00      57.50
W      1021      103.48      230.00      0.00      142.71      0.00      476.19

Totals      221.16      399.50      0.00      142.71      12.64      776.01

```

&k2S

&k0S