

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 9866B

Date In: 16 APR 24 Author: MGRAY
Promised Date: 13 APR 24 Stock No: 10291
: Year: 2023
Customer Name: 122479 - STAFFORD, AMA Manufacturer: GRAND DESIGN
Address: W6530 STATE RD 152 Brand: REFLECTION 150 SERIES
: WAUTOMA, WI Model: 298BH
Postal/Zip: 54982 Miles/Hrs: 0
Phone#(res): 920-765-1090 Exterior Color:
Phone#(bus): Unit Type: FW-FIFTH WHEEL
Cell Phone: 920-765-0671 License#:
Email: AMANDASTAFFORD2010@GMA Tag#:
Purchased Date: 21 OCT 23 :
Delivery Date: 13 APR 24 :
InService Date: :
Serial#: 573FR3623P334188 :

Job #	Description	JOB INFORMATION	Type	Bill To
3	COMPLAINT: CRACKED SKYLIGHT LEAKING INTO SHOWER CAUSE: Mfg had screws right through plastic lip causing the cracks in several areas and over time cracked more up into skylight CORRECTION: Used a multi tool carefully to cut away the dicor removed screws wiped away alot of water that had seeped beneath skylight installed putty tape on bottom of new skylight installed screws around skylight then dicored around the skylight		W	1020 GRAND
4	COMPLAINT: BATHROOM SLIDING POCKET DOOR ARE PEELING THE VENEER AT SEAMS CAUSE: Peeling Please order 22w x 74 tall slider door CORRECTION: ..		W	1020 GRAND
5	COMPLAINT: BEDROOM SLIDING POCKET DOOR PEELING VENEER ON EDGES AND SEAM CAUSE: Peeling edge of door Please order 30 x 74 slider door		W	1020 GRAND
WARR	COMPLAINT: WARRANTY REPAIR 6 - screen next to the sofa has a stitch missing which can allow bugs in CAUSE: Thread missing CORRECTION: Removed screen and material installed new material from parts		W	1020 GRAND
WARR	COMPLAINT: WARRANTY REPAIR 7 - exterior grill has damage from mfg not having grill		W	1020 GRAND

Continued on page 2

Work Order : 9866B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                properly secured while transporting
                allowing grill top to jump out of its
                hole then hitting the top front of grill
CAUSE:    Mfg did not secure the grill in place
                while transport. PLEASE ORDER NEW GRILL
                PICS TAKEN
CORRECTION: .....

```

```

*****
Job # Part No      Description      PARTS    Bill to    Qty    Price    Total
*****
3      677917000333  10.3oz TUBE LAP SEALANT  W-1020    3      6.80    20.40

```

```

*****
Job# Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
3 WARR      MANUFACTURER WARRANTY  HOD  W-1020    0.00  115.00    0.00
3 WARR      MANUFACTURER WARRANTY  HOD  W-1020    0.50  115.00   57.50
4 WARR      MANUFACTURER WARRANTY  HOD  W-1020    0.50  115.00   57.50
5 WARR      MANUFACTURER WARRANTY  HOD  W-1020    0.50  115.00   57.50
ARR06 Z992    MISC LABOUR CODE (WARR HOD  W-1020    0.50  115.00   57.50
ARR07 Z992    MISC LABOUR CODE (WARR HOD  W-1020    0.48  115.00   55.20
ARR07 Z992    MISC LABOUR CODE (WARR HOD  W-1020    0.02  115.00    2.30

```

```

*****
Job # Excode    Description  EXTRAS    bill to    Qty    Price    Total
*****
ARR06 SSE      SHOP SUPPLIES - EXTERNAL  W-1020    1.00    0.00    0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
W      1020      20.40    287.50    0.00    0.00    0.00    307.90
      Totals    20.40    287.50    0.00    0.00    0.00    307.90

```

&k2S
&k0S