

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10527B

Date In:	03 JUL 24	Author:	KOTT
Promised Date:	04 JUL 25	Stock No:	11129
:	:	Year:	2024
Customer Name:	1000 - GREENEWAY RV SA	Manufacturer:	GRAND DESIGN
Address:	8220 STATE HWY 13 SOUT	Brand:	TRANSCEND XPLO
:	WISCONSIN RAPIDS, WI	Model:	265BH
Postal/Zip:	54494	Miles/Hrs:	0
Phone#(res):	800-758-2272	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	19 OCT 24	:	:
Delivery Date:	26 OCT 24	:	:
InService Date:	:	:	:
Serial#:	573TT3328R8831322	:	:

Job #	Description	JOB INFORMATION	Type	Bill To
WARR	COMPLAINT:	WARRANTY REPAIR There was a Mark in the trim on the stairs going up to the bunks	W	1020 GRAND
	CAUSE:	From mfg this way NEED .10 FOR REPAIR		
	CORRECTION:	Used putty to cover		
WARR	COMPLAINT:	WARRANTY REPAIR 2 -Wood on the bottom bunk is scraped	W	1020 GRAND
	CAUSE:	From mfg, defect. NEED .10 FOR REPAIR		
	CORRECTION:	Used wood pen to cover		
WARR	COMPLAINT:	WARRANTY REPAIR 3 - Slide room facia has many nail marks	W	1020 GRAND
	CAUSE:	Mfg did not fill the holes NEED .20 FOR REPAIRS		
	CORRECTION:	Used putty to fill holes		
WARR	COMPLAINT:	WARRANTY REPAIR 4 - The overhead cabinets in the bedroom have visible staples and holes	W	1020 GRAND
	CAUSE:	Unfilled staple holes from mfg, need .20 to clean and fill staple holes		
	CORRECTION:	Filled with putty		
WARR	COMPLAINT:	WARRANTY REPAIR 5 -The ceiling trim above the top bunk is hanging down	W	1020 GRAND
	CAUSE:	Loose trim from mfg. NEED .10 FOR REPAIR		
	CORRECTION:	I gently pounded the trim back up into track looks as it should now		
WARR	COMPLAINT:	WARRANTY REPAIR 6 -Exterior of shower base is bowed outwards	W	1020 GRAND
	CAUSE:	Bowed from mfg NEED .50 FOR REPAIRS		
	CORRECTION:	Used a heat gun to get dents out of		

Continued on page 2

Work Order : 10527B

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
                                plastic cut two slips of wood to bring
                                cover out further installed screws now
                                the cover does not appear sunken in
WARR    COMPLAINT:  WARRANTY REPAIR 8 -The TV is installed      W    1020    GRAND
                                crooked
                                CAUSE:      Improper install, NEED .10 TO READJUST
                                AND STRAIGHTEN TV AND BRACKET.
                                CORRECTION:  Loosened screws on tv bracket then
                                adjusted bracket reinstalled screws. Tv
                                now level
WARR    COMPLAINT:  WARRANTY REPAIR 9 -Bathrooms slider door W    1020    GRAND
                                is not installed evenly
                                CAUSE:      Improper install mfg NEED .20 FOR
                                REPAIRS
                                CORRECTION:  Removed fascia header then adjusted
                                glides reinstalled header
WARR    COMPLAINT:  WARRANTY REPAIR 11 -The rear compartment W    1020    GRAND
                                paneling has excessive staple holes
                                CAUSE:      Unfilled staple holes from mfg NEED .20
                                FOR REPAIRS
                                CORRECTION:  Used putty to fill holes

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.50  115.00  57.50
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.50  115.00  57.50
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.50  115.00  57.50
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.50  115.00  57.50
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.50  115.00  57.50
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.50  115.00  57.50
ARR08 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.50  115.00  57.50
ARR09 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.50  115.00  57.50
ARR11 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.34  115.00  39.10
ARR11 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.16  115.00  18.40

```

```

*****
Job #  Excode   Description  EXTRAS      bill to  Qty  Price  Total
*****
ARR01  SSE      SHOP SUPPLIES - EXTERNAL  W-1020  1.00   0.00   0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1020      0.00      517.50      0.00      0.00      0.00      517.50
                                Totals      0.00      517.50      0.00      0.00      0.00      517.50

```

Continued on page 3

Work Order : 10527B

&k2S
&k0S