

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11017B

Date In:	22 AUG 24	Author:	MZYWICKI
Promised Date:	04 JUL 25	Stock No:	11206
:	:	Year:	2025
Customer Name:	17417 - WEDEN, CURT	Manufacturer:	GRAND DESIGN
Address:	2004 DOUGLAS DRIVE	Brand:	IMAGINE
:	SCHOFIELD, WI	Model:	3100RD
Postal/Zip:	54476	Miles/Hrs:	0
Phone#(res):	7152187343	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	CURT.WEDEN@GMAIL.COM	Tag#:	:
Purchased Date:	17 JUL 24	:	:
Delivery Date:	09 OCT 24	:	:
InService Date:	:	:	:
Serial#:	573TE3629S6652004	:	:

```
*****
Job #   Description          JOB INFORMATION          Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - Entrance steps are 3 W    1020    GRAND
        steps and when adjusted so its safe to
        walk down them the door will not close
        if door closes its a much to steep to go
        up and down the steps
        CAUSE:      Mfg may have installed incorrect steps
        From ground to threshold is 36 width of
        door opening is 37 1/4 I have attached
        numbers on steps and number tag on door
        frame PLEASE CONTACT MFG AND SEE IF
        THESE ARE INCORRECT STEPS FOR UNIT AND
        IF SO PLEASE ORDER THE CORRECT STEPS
        CORRECTION: Moved main hinge on steps to try to get
        this to function to no avail
        REQUEST:.50 FOR REPAIR REQUEST: NEW
        STEPS
WARR    COMPLAINT:  WARRANTY REPAIR 2 - very deep staple    W    1020    GRAND
        holes throughout the unit
        CAUSE:      Mfg did not fill staple holes . WILL
        NEED .50 TO DO ENTIRE UNIT.
        CORRECTION: Used putty and filled holes then used
        murpheys oil soap to whip we away excess
WARR    COMPLAINT:  WARRANTY REPAIR 3 - Bed slider door has W    1020    GRAND
        gap at top and close at bottom when door
        is closed towards the wall
        CAUSE:      Improper install NEED.60 FOR REPAIR
        CORRECTION: Removed header adjusted the glides for
```

Continued on page 2

Work Order : 11017B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                                the door tested . Its as it should be
                                then reinstalled fascia
WARR    COMPLAINT:  WARRANTY REPAIR 4 - 2 drawer faces below W      1020    GRAND
                                stove area have gouges in their faces
                                CAUSE:      Gouged from mfg when installed. NEED .40
                                FOR REPAIR.
                                CORRECTION: Filled with putty then wiped away the
                                excess
WARR    COMPLAINT:  WARRANTY REPAIR 5 - Loose trim next to    W      1020    GRAND
                                the stove
                                CAUSE:      Loose trim from mfg
                                CORRECTION: Pin nailed into place
WARR    COMPLAINT:  WARRANTY REPAIR 6 - Excess putty through W      1020    GRAND
                                out unit on walls, trim and slide out
                                wood edges on slide floors
                                CAUSE:      Smeared putty left behind from mfg
                                CORRECTION: Cleaned with murpheys soap and rag
WARR    COMPLAINT:  WARRANTY REPAIR 7 - slide room one not    W      1020    GRAND
                                coming in board just clicks
                                CAUSE:      Wire inside motor is loose when pulling
                                on wire slide would operate came from
                                mfg this way  PLEASE ORDER NEW LIPPERT
                                MOTOR M#1-065-041-012. P#131903.  PICS
                                TAKEN.      I AM LEAVING THE MOTOR IN
                                FRONT COMPARTMENT  THE TIME I HAVE IN IS
                                FOR REASSEMBLING WHAT WAS TAKEN APART
                                REINSTALLED TIRE AND UNDERBELLY
                                DIFFICULT GETTING BOLTS BACK INTO FRAME
                                AREAS HOLDING UNDER BELLY
                                CORRECTION: REQUEST: 2.5 FOR REPAIR REQUEST: PART #
                                170003 ACTUATOR.

```

```

*****
Job # Part No   Description           PARTS           Bill to   Qty     Price     Total
*****
WARR0 822070003 ACTUATOR-40" W/ HIGH SPEED  W-1020         1      663.47    663.47
*****
Job#  Lab Code  Description           LABOUR    Mech Bill to     Hrs     Rate     Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD  W-1020         0.50    115.00    57.50
ARR02 Z992      MISC LABOUR CODE (WARR HOD  W-1020         0.45    115.00    51.75
ARR02 Z992      MISC LABOUR CODE (WARR HOD  W-1020         0.05    115.00     5.75
ARR03 Z992      MISC LABOUR CODE (WARR HOD  W-1020         0.49    115.00    56.35
ARR03 Z992      MISC LABOUR CODE (WARR HOD  W-1020         0.01    115.00     1.15
ARR04 Z992      MISC LABOUR CODE (WARR HOD  W-1020         0.49    115.00    56.35
ARR04 Z992      MISC LABOUR CODE (WARR HOD  W-1020         0.01    115.00     1.15
ARR05 Z992      MISC LABOUR CODE (WARR HOD  W-1020         0.49    115.00    56.35
ARR05 Z992      MISC LABOUR CODE (WARR HOD  W-1020         0.01    115.00     1.15

```

Continued on page 3

Work Order : 11017B

```

*****
Job#  Lab Code  Description   LABOUR   Mech Bill to      Hrs      Rate      Total
*****
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1020    0.47    115.00    54.05
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1020    0.03    115.00     3.45
ARR07 Z992      MISC LABOUR CODE (WARR HOD W-1020    0.00    115.00     0.00
ARR07 Z992      MISC LABOUR CODE (WARR HOD W-1020    0.50    115.00    57.50

```

```

*****
Job #  Excode    Description   EXTRAS      bill to      Qty      Price      Total
*****
ARR01  SSE       SHOP SUPPLIES - EXTERNAL  W-1020     1.00       0.00       0.00
ARR07  FRT       FREIGHT FOR JOB 7        W-1020     1.00      33.00      33.00

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1020        663.47      402.50       0.00       33.00       0.00     1,098.97

      Totals      663.47      402.50       0.00       33.00       0.00     1,098.97

```

&k2S
&k0S