

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 6643C

Date In: 06 DEC 23 Author: SDIAMOND
Promised Date: 04 FEB 24 Stock No: 10499
: Year: 2022
Customer Name: 16144 - JAROSCAK, JOSE Manufacturer: GRAND DESIGN
Address: 1849 93RD AVE Brand: REFLECTION FW
: DRESSER, WI Model: 311BHS
Postal/Zip: 54009 Miles/Hrs: 0
Phone#(res): (715) 417-2273 Exterior Color:
Phone#(bus): Unit Type: FW-FIFTH WHEEL
Cell Phone: License#:
Email: jjaroscak4@gmail.com Tag#: VM FOR HILES GD 1/18 -
Purchased Date: 28 MAY 22 :
Delivery Date: 28 MAY 22 :
InService Date: :
Serial#: 573FR3827N9919416 :

Job # Description JOB INFORMATION Type Bill To

WARR COMPLAINT: Transferred to GRV*6643D on 24 JAN 24 E 16144 JAROS
Estimate amount was 0.00 ADDED 10/20
DOOR ABOVE FIREPLACE IS SPLITTING
CAUSE: Fasteners pulled free on the top left
corner.
CORRECTION: Was able to remove old fasteners and
glue/fasten back together. Done
WARR COMPLAINT: ADDED 10/20 - WARRANTY REPAIR 8 - COOK I SEP POLIC
TOP WORKS BUT OVEN DOESN'T WORK
CAUSE: NPF
CORRECTION: It definitely took longer than I was
expecting, but after about 45 seconds of
holding the pilot knob (while it sparks)
it lit. Seems to work fine now. Must
have had air in the line. Done
WARR COMPLAINT: ADDED 10/20 - - FRONT SLIDE OUT MOVES W 1020 GRAND
OUT ABOUT 1-2 INCHES THEN DOESN'T MOVE
AND BINDS UP
CAUSE: incorrect installation The master
bedroom slide struggles to go out,
especially the front side. In fact the
only way I could get it out was to
override the control board with the 6
click 7th click hold deal. The bottom
rail is getting chewed up and the bottom
of the (front) column looks to be
twisting while running out.
CORRECTION: Will need a new schwintek setup for the

Continued on page 2

Work Order : 6643C

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
front of the master bedroom slide. See
picture of label for ordering info. EVEN
THOUGH OUTSIDE OF WARRANTY TRY TPO GET
COVEERED BY WARRANTY FOR THIS ISSUE OR
NO CHARGE PART AT LEAST PER SD 12/6
WARR    COMPLAINT:  Transferred to GRV*6643D on 24 JAN 24     E    16144  JAROS
          Estimate amount was 0.00 WARRANTY REPAIR
          11 - REAR BATHROOM DUMP VALVE CABLE IS
          MESSED UP - NOT CLOSING
          CAUSE:      Handle shaft was bent.
          CORRECTION: Straightened out and lubed. Works again.
          Done
1        COMPLAINT:  ADDED 11/29 LIPPERT SEAM AT AWNING        W    1020  GRAND
          FABRIC CHECK NEEDS PICTURES
          CAUSE:      1001 CUSTOMER REQUESTED
          CORRECTION: Rear awning looks good. Front awning
          looks good. Front awning does not have a
          sticker/label on it anymore
2        COMPLAINT:  ADDED 11/29 QUICK DISCONNECT RECALL      W    1020  GRAND
          CAUSE:      ADDED 11/29 QUICK DISCONNECT RECALL
          CORRECTION: There are 2 quick disconnects, one on
          each side. Both pass the spray
          leak/visual test. Done
3        COMPLAINT:  ADDED 11/29 LIPPERT SEAM AT AWNING        W    1020  GRAND
          FABRIC CHECK NEEDS PICTURES
          CAUSE:      CU REQUESTED
          CORRECTION: Front awning looks good. Front awning
          does not have a sticker/label on it
          anymore PICS IN LINE 1
4        Transferred to GRV*6643D on 24 JAN 24 Estimate     E    16144  JAROS
          amount was 0.00 HAS ROUTE 66 IF NEEDED FOR COVERAGE
          OF SLIDEOUT STUFF
    
```

```

*****
Job # Part No Description          PARTS          Bill to Qty Price Total
*****
WARR 651329 STILE 18MM X3X9FT RADIUS BRO E-16144 0 29.96 0.00
WARR0 82200636 DNU-MECHANISM SLIDEOUT IN WA W-1020 1 595.02 595.02
    
```

```

*****
Job# Lab Code Description          LABOUR Mech Bill to Hrs Rate Total
*****
WARR Z991 MISC CODE (NTERNAL) NOK E-16144 0.00 105.00 0.00
WARR Z991 MISC CODE (NTERNAL) NOK E-16144 0.00 105.00 0.00
ARR08 Z992 MISC LABOUR CODE (WARR NOK I-SEP 0.10 70.00 7.00
ARR09 Z992 MISC LABOUR CODE (WARR W-1020 0.00 115.00 0.00
ARR09 Z992 MISC LABOUR CODE (WARR NOK W-1020 0.13 115.00 14.95
ARR11 Z992 MISC LABOUR CODE (WARR NOK E-16144 0.00 105.00 0.00
1 WARR MANUFACTURER WARRANTY NOK W-1020 0.30 115.00 34.50
    
```

Continued on page 3

Work Order : 6643C

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
   2  WARR      MANUFACTURER WARRANTY  NOK  W-1020    0.50   115.00   57.50
   3  WARR      MANUFACTURER WARRANTY  NOK  W-1020    0.00   115.00    0.00
ARR09 Z992      MISC LABOUR CODE (WARR NOK  W-1020    0.37   115.00   42.55
*****
```

```
*****
Job #  Excode    Description  EXTRAS      bill to    Qty    Price    Total
*****
ARR09  FRT        FREIGHT FOR JOB 9      W-1020    1.00   38.23   38.23
ARR11  SSE        SHOP SUPPLIES - EXTERNAL  E-16144   0.00    0.00    0.00
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
I      SEP          0.00     7.00     0.00     0.00     0.00     7.00
W      1020        595.02   149.50     0.00    38.23     0.00   782.75

      Totals      595.02   156.50     0.00    38.23     0.00   789.75
*****
```

&k2S
&k0S