

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11722

Date In:	03 FEB 25	Author:	MGRAY
Promised Date:	14 APR 25	Stock No:	11042
:	:	Year:	2024
Customer Name:	17283 - EGNOR, DALLAS	Manufacturer:	FOREST RIVER
Address:	345 BLAINE STREET	Brand:	FLAGSTAFF MICRO-LITE
:	IOLA, WI	Model:	25FBLS
Postal/Zip:	54945	Miles/Hrs:	0
Phone#(res):	6085779341	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	dallas.egnor@gmail.com	Tag#:	TOD
Purchased Date:	06 APR 24	:	:
Delivery Date:	27 APR 24	:	:
InService Date:	:	:	:
Serial#:	4X4TFLA27RD457742	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 2 - CMR STATES "The          W    1021    FORES
          toilet randomly leaks some water. We
          haven't been able to figure out where
          and there doesn't seem to be much of a
          pattern but we're worried as it has
          happened a number of times."  Water leak
          is found on the floor next to the toilet
          and customer is unable to identify the
          source.
          CAUSE:      Test toilet for leaks.
          CORRECTION:  Tested toilet for leaks. had flushed
                      several times and could not find any
                      leaks at this time. ***NOTING***
WARR    COMPLAINT:  WARRANTY REPAIR 3 - CMR STATES "Right by W    1021    FORES
          the entrance there is what I believe to
          be the power converter and it often
          sounds very loud. I have read things
          online about this issue, but I'm not an
          expert by any means."
          CAUSE:      Check converter operation. Customer
                      states that it gets loud sometimes.
          CORRECTION:  If they are referring to the fan noise,
                      that is a tippicle normal sound. It's
                      not making any abnormal noises.
                      ***NOTING***
1       COMPLAINT:  CMR STATES "Chip in front windshield.      E    17283    EGNOR
          Pretty small, but couldn't be repaired
          by a windshield repair place. Basically
```

Continued on page 2

Work Order : 11722

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
                                wanting an estimate on that and your
                                opinion on fixing it." - CMR AWARE THAT
                                THIS REPAIR MAY NOT BE ABLE TO BE DONE
                                HERE DUE TO LACK OF EQUIPMENT NEEDED FOR
                                REPLACEMENT. ALSO EXPLAINED TO CMR THAT
                                THIS WOULD NOT BE A WARRANTABLE ITEM.
CAUSE:   Measure front windsheild for
                                replacement. Measurements are on back
                                page of work order. TOP WIDTH 63" BOTTOM
                                WIDTH 61" OUTSIDE SIDE HEIGHT 23" MIDDLE
                                OF GLASS HEIGHT 28 1/2" * PICTURE OF
                                WINDOW IS ALSO IN WO.
CORRECTION: ...
2 COMPLAINT: Customer requests roof inspection, has I PD GOODW
                                concern it may need touch up on sealant.
CAUSE:   Roof inspection
CORRECTION: Perform roof inspection. Touched up
                                front and rear corners with dicor.

```

```

*****
Job # Part No   Description      PARTS      Bill to   Qty    Price    Total
*****
1      822021700 GLUE IN, TT - 63.251" X 28. E-17283      0    230.80    0.00

```

```

*****
Job# Lab Code Description    LABOUR    Mech Bill to    Hrs    Rate    Total
*****
ARR02 Z992      MISC LABOUR CODE (WARR TD W-1021    0.39    115.00    44.85
ARR03 Z992      MISC LABOUR CODE (WARR TD W-1021    0.50    115.00    57.50
      1 Z990      MISC LABOUR CODE (EXTE TD E-17283    0.50    140.00    70.00
      2 RI        ROOF INSPECTION          TD I-PD      0.30    70.00    21.00
ARR02 Z992      MISC LABOUR CODE (WARR TD W-1021    0.11    115.00    12.65

```

```

*****
Job # Sublet Description      SUBLET      bill to    Vendor    Total
*****
1 NOVUS GLASS REPAIR          E-17283    337-NOVUS AUTO    0.00

```

```

*****
Job # Excode   Description    EXTRAS      bill to    Qty    Price    Total
*****
1 SSE          SHOP SUPPLIES - EXTERNAL E-17283    1.00    5.25    5.25
1 FRT          FREIGHT          E-17283    0.00    0.00    0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id    Parts    Labour    Sublet    Extras    Tax    Total
*****
E 17283         0.00     70.00     0.00     5.25     4.15    79.40

```

Continued on page 3

Work Order : 11722

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
I	PD	0.00	21.00	0.00	0.00	0.00	21.00
W	1021	0.00	115.00	0.00	0.00	0.00	115.00
	Totals	0.00	206.00	0.00	5.25	4.15	215.40

&k2S
&k0S