

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 9747

Date In: 09 OCT 23 Author: MGRAY  
Promised Date: 10 MAY 24 Stock No: 10634  
: Year: 2022  
Customer Name: 1020 - GRAND DESIGN Manufacturer: GRAND DESIGN  
Address: 11333 COUNTY RD 2 Brand: IMAGINE  
: MIDDLEBURY, IN Model: 2600RB  
Postal/Zip: 46540 Miles/Hrs: 0  
Phone#(res): 888-825-2820 Exterior Color:  
Phone#(bus): Unit Type: TT-TRAVEL TRAILER  
Cell Phone: License#:  
Email: NONE Tag#:  
Purchased Date: 28 JAN 23 :  
Delivery Date: 21 MAR 23 :  
InService Date: :  
Serial#: 573TE302XN5509629 :

\*\*\*\*\*  
Job # Description JOB INFORMATION Type Bill To  
\*\*\*\*\*  
1 COMPLAINT: WATER LEAK. WHEN DRAINING THE TANKS FOR W 1020 GRAND  
WINTERIZE THERE WAS WATER COMING OUT OF  
THE PLUMBING UNDER SINK AND KITCHEN -  
WHEN YOU GO TO DUMP GRAY WATER, WATER  
COMES OUT FROM BETWEEN INSULATION AND  
DRAIN HOSE.  
CAUSE: NPF- FILLED TANK TO 1/3 AND OPENDED  
UNDERBELLY TO CHECK FOR ANY WATER- THERE  
WAS NO WATER IN THE UNDERBELLY-  
CORRECTION: WHAT CUSTOMER IS SEEING IS WEEPING OUT  
OF THE CORIGATED UNDERBELLY-  
2 COMPLAINT: THE HEATER IS VERY LOUD, WORKS WELL BUT W 1020 GRAND  
LOUD. IS THAT NORMAL OR?  
CAUSE: Test furnace for operation. Customer  
says it's loud.  
CORRECTION: Furnace is running normal. The exhaust  
noise they hear is normal for that  
model.  
3 COMPLAINT: CMR BOUGHT THE BACK UP CAMERA THE PLUGS E 16732 OEHLE  
IN. WHEN HE HOOKS THE LIGHTS UP TO THE  
TRUCK. SIGNAL LIGHTS WORK BUT NO CAMERA.  
VIDEO SAYS NO SIGNAL. WHEN HOOKS 7-WAY  
ADAPTER UP CAMERA WILL WORK BUT RIGHT  
SIGNAL LIGHT WILL NOT.  
CAUSE: Test all exterior clearance lights for  
operation. Right turn signal inop when  
using 7 way adaptor to vehicle.  
CORRECTION: Need vehicle and adaptor here to test...

Continued on page 2

Work Order : 9747

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                ONCE VEHICLE WAS HERE THERE WAS JUST
                ISSUE WITH PLUG ON MAKING PROPER
                CONNECTION.

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
  2  Z990      MISC LABOUR CODE (EXTE TD  W-1020  1.00  115.00  115.00
  3  DIAG      DIAGNOSTICS                TD  E-16732  0.00  130.00  0.00
  3  DIAG      DIAGNOSTICS                TD  E-16732  0.03  130.00  3.90
  3  DIAG      DIAGNOSTICS                TD  E-16732  0.15  130.00  19.50

```

```

*****
Job #  Excode   Description  EXTRAS  bill to  Qty  Price  Total
*****
  1  SSE      SHOP SUPPLIES - EXTERNAL  W-1020  1.00  1.76  1.76

```

```

*****
                BILLINGS SUMMARY
Type Bill Id  Parts  Labour  Sublet  Extras  Tax  Total
*****
E  16732      0.00   23.40   0.00   0.00   1.30   24.70
W  1020      0.00  115.00   0.00   1.76   0.00  116.76
Totals      0.00  138.40   0.00   1.76   1.30  141.46

```

&k2S  
&k0S