



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$16,946.27

RO# : 40320 Tag# : TB526431

Check-in: Mon Mar 30, 2026 | 12:02 PM  
Ready for Pickup: Wed Apr 1, 2026 | 10:08 AM  
Promise Time: Sat Apr 4, 2026 | 6:00 PM

<b>Customer</b> Jeff Dietsche 1245593 +1 - (715) 262 - 0028 jeff.j.dietsche@gmail.com W10797 566th Avenue Prescott, WI 54021	<b>Pickup-Customer</b> Same as Customer	<b>Vehicle</b> 2026 FOREST RIVER TRACER 5ZT2TRNB6TB526431 2 Mi In Sold Date: 03/21/2026 Stock #: FR26-06	<b>Service Advisor</b> KEVIN GOODIEL goodielk
	<b>Billing-Customer</b> Same as Customer		

<b>A. MISCELLANEOUS</b>	<b>CUSTOMER STATES NO POWER TO REAR CAMERA</b>	<b>Warranty Pay</b>	<b>\$165.00</b>
-------------------------	--	---------------------	-----------------

Job added by KEVIN GOODIEL on Mon Mar 30, 2026 | 12:02 PM

1. Tested and the blue light on camera doesn't come on with tail lights removed the camera from housing and tested wires for power and found the red wire hooked to wire from camper and black hooked to green from camper tested and it was -13.1 volts so the plug for camera is wired backwards removed wires and recrimped wires the right way and tested camera has power now and light turns on like it should remounted camera and sealed up. Requesting .8 to diagnose and repair

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$165.00

Labor Cost: \$31.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
kastenm	-	0.68	1	1	\$165.00	\$31.00

1. Tested and the blue light on camera doesn't come on with tail lights removed the camera from housing and tested wires for power and found the red wire hooked to wire from camper and black hooked to green from camper tested and it was -13.1 volts so the plug for camera is wired backwards removed wires and recrimped wires the right way and tested camera has power now and light turns on like it should remounted camera and sealed up. Requesting .8 to diagnose and repair

<b>Total Labor Sale</b>	<b>Total Labor Cost</b>	<b>Total Parts Sale</b>	<b>Total Parts Cost</b>
\$165.00	\$31.00	\$0.00	\$0.00

<b>B. MISCELLANEOUS</b>	<b>CUSTOMER STATES THERES WATER LEAKING FROM UNDER BELLY BACK TOWARDS THE TANKLESS WATER HEATER</b>	<b>Warranty Pay</b>	<b>\$66.00</b>
-------------------------	---	---------------------	----------------

Job added by KEVIN GOODIEL on Mon Mar 30, 2026 | 12:02 PM

1. Hooked city water connection up and looked for leaks found that the kitchen faucet cold line was leaking where the faucet line screws into the main line. Was able to use a Wrench and tightened up the line and checked for leaks and nothing in isn't leaking any more checked all other fittings by back wall and there's nothing else that's leaking. Requesting .5 for diagnosing and fixing the leak.





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$16,946.27

RO# : 40320 Tag# : TB526431

Check-in: Mon Mar 30, 2026 | 12:02 PM  
Ready for Pickup: Wed Apr 1, 2026 | 10:08 AM  
Promise Time: Sat Apr 4, 2026 | 6:00 PM

<b>Customer</b> Jeff Dietsche 1245593 +1 - (715) 262 - 0028	<b>Billing-Customer</b> Same as Customer	<b>Vehicle</b> 2026 FOREST RIVER TRACER 5ZT2TRNB6TB526431	<b>Service Advisor</b> KEVIN GOODIEL goodielk
--	---	--	---

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$66.00  
Labor Cost: \$12.40

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
kastenm	-	0.36	0.4	0.4	\$66.00	\$12.40

1. Hooked city water connection up and looked for leaks found that the kitchen faucet cold line was leaking where the faucet line screws into the main line. Was able to use a. Wrench and tightened up the line and checked for leaks and nothing in isn't leaking any more checked all other fittings by back wall and there's nothing else that's leaking. Requesting .5 for diagnosing and fixing the leak.

<b>Total Labor Sale</b> \$66.00	<b>Total Labor Cost</b> \$12.40	<b>Total Parts Sale</b> \$0.00	<b>Total Parts Cost</b> \$0.00
------------------------------------	------------------------------------	-----------------------------------	-----------------------------------

<b>C. MISCELLANEOUS</b>	<b>CUSTOMER STATES THE TANKLESS WATER HEATER DONT GET OVER 100 DEGREES ON CITY WATER BUT DOES WHEN DRAWING FROM THE TANK</b>	<b>Warranty Pay</b>	<b>\$16,500.00</b>
-------------------------	--	---------------------	--------------------

Job added by KEVIN GOODIEL on Mon Mar 30, 2026 | 12:02 PM

1. Tested the st42 suburban water heater and with city water hooked up it would only get to 96 degrees I did some research and ended up hooking up water pressure regulator up to city water line and regulated the water to 52 psi and tested and the water heater ended up getting up to the desired temperature so in order for the water heater to be more efficient and get up to temperature do not exceed 60 psi. Requesting 1.0 to diagnose and test the water heater

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$16,500.00  
Labor Cost: \$31.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
kastenm	-	0.92	100	1	\$16,500.00	\$31.00

1. Tested the st42 suburban water heater and with city water hooked up it would only get to 96 degrees I did some research and ended up hooking up water pressure regulator up to city water line and regulated the water to 52 psi and tested and the water heater ended up getting up to the desired temperature so in order for the water heater to be more efficient and get up to temperature do not exceed 60 psi. Requesting 1.0 to diagnose and test the water heater





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$16,946.27

RO# : 40320 Tag# : TB526431

Check-in: Mon Mar 30, 2026 | 12:02 PM

Ready for Pickup: Wed Apr 1, 2026 | 10:08 AM

Promise Time: Sat Apr 4, 2026 | 6:00 PM

<b>Customer</b> Jeff Dietsche 1245593 +1 - (715) 262 - 0028	<b>Billing-Customer</b> Same as Customer	<b>Vehicle</b> 2026 FOREST RIVER TRACER 5ZT2TRNB6TB526431	<b>Service Advisor</b> KEVIN GOODIEL goodielk
--	---	--	---

<b>Total Labor Sale</b> \$16,500.00	<b>Total Labor Cost</b> \$31.00	<b>Total Parts Sale</b> \$0.00	<b>Total Parts Cost</b> \$0.00
--	------------------------------------	-----------------------------------	-----------------------------------

<b>D. MISCELLANEOUS</b>	<b>CUSTOMER STATES THERES AN OUTLET NOT WORKING ON THE DINETTE</b>	<b>Warranty Pay</b>	<b>\$82.50</b>
-------------------------	--	---------------------	----------------

Job added by KEVIN GOODIEL on Mon Mar 30, 2026 | 12:02 PM

1. Tested every outlet in camper and all of them are working like they should with no issues requesting .5 for checking outlets. Attached a picture of the tester in the outlet by the dinette

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$82.50

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
kastenm	-	0.31	0	0	\$0.00	\$0.00

1. Tested every outlet in camper and all of them are working like they should with no issues requesting .5 for checking outlets. Attached a picture of the tester in the outlet by the dinette

<b>Total Labor Sale</b> \$82.50	<b>Total Labor Cost</b> \$0.00	<b>Total Parts Sale</b> \$0.00	<b>Total Parts Cost</b> \$0.00
------------------------------------	-----------------------------------	-----------------------------------	-----------------------------------

<b>E. MISCELLANEOUS</b>	<b>CUSTOMER STATES THE BEDROOM TV JACK DONT WORK</b>	<b>Warranty Pay</b>	<b>\$132.00</b>
-------------------------	--	---------------------	-----------------

Job added by KEVIN GOODIEL on Mon Mar 30, 2026 | 12:02 PM

1. Looked at the bedroom tv cable wasn't screwed into tv took off the tv jack on ceiling and checked the cables everything was in place. Removed camper from shop and. Searched for tv channels and didn't find any on bedroom or living room tvs so couldn't test to see if it was working now or not since there isn't any tv channels to be found. Removed the tv jack outside and the cable is screwed in to it and its grey just like the one from the booster that says set 2 here requesting 1.3 to diagnose





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$16,946.27

RO# : 40320 Tag# : TB526431

Check-in: Mon Mar 30, 2026 | 12:02 PM  
Ready for Pickup: Wed Apr 1, 2026 | 10:08 AM  
Promise Time: Sat Apr 4, 2026 | 6:00 PM

<b>Customer</b> Jeff Dietsche 1245593 +1 - (715) 262 - 0028	<b>Billing-Customer</b> Same as Customer	<b>Vehicle</b> 2026 FOREST RIVER TRACER 5ZT2TRNB6TB526431	<b>Service Advisor</b> KEVIN GOODIEL goodielk
--	---	--	---

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$132.00

Labor Cost: \$24.80

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
kastenm	-	1.13	0.8	0.8	\$132.00	\$24.80

1. Looked at the bedroom tv cable wasn't screwed into tv took off the tv jack on ceiling and checked the cables everything was in place. Removed camper from shop and. Searched for tv channels and didn't find any on bedroom or living room tvs so couldn't test to see if it was working now or not since there isn't any tv channels to be found. Removed the tv jack outside and the cable is screwed in to it and its grey just like the one from the booster that says set 2 here requesting 1.3 to diagnose

<b>Total Labor Sale</b> \$132.00	<b>Total Labor Cost</b> \$24.80	<b>Total Parts Sale</b> \$0.00	<b>Total Parts Cost</b> \$0.00
-------------------------------------	------------------------------------	-----------------------------------	-----------------------------------

<b>F. MISCELLANEOUS</b>	<b>CUSTOMER STATES THERES A GREY TANK HANDLE MISSING</b>	<b>Warranty Pay</b>	<b>\$0.77</b>
-------------------------	--	---------------------	---------------

Tags: Add-on

Job added by KEVIN GOODIEL on Mon Mar 30, 2026 | 12:02 PM

1. On the drain outlet the gate valve toward on the rear is missing the handle the front one has a grey one so think the back one will need a black one installed requesting .2 to install new handle

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
kastenm	-	0.1	0	0	\$0.00	\$0.00

1. On the drain outlet the gate valve toward on the rear is missing the handle the front one has a grey one so think the back one will need a black one installed requesting .2 to install new handle





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
**\$16,946.27**

RO# : 40320 Tag# : TB526431

Check-in: Mon Mar 30, 2026 | 12:02 PM  
 Ready for Pickup: Wed Apr 1, 2026 | 10:08 AM  
 Promise Time: Sat Apr 4, 2026 | 6:00 PM

<b>Customer</b> Jeff Dietsche 1245593 +1 - (715) 262 - 0028	<b>Billing-Customer</b> Same as Customer	<b>Vehicle</b> 2026 FOREST RIVER TRACER 5ZT2TRNB6TB526431	<b>Service Advisor</b> KEVIN GOODIEL goodielk
--	---	--	---

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00  
 Labor Cost: \$0.00

Parts

Parts Total Sale Amount \$0.77  
 Parts Total Cost Amount \$0.59

Name	Quantity	Unit Price	Sale Price	Cost Price
60P14615A - HANDLE, T1003-6N, BLACK	1	\$0.77	\$0.77	\$0.59

<b>Total Labor Sale</b> \$0.00	<b>Total Labor Cost</b> \$0.00	<b>Total Parts Sale</b> \$0.77	<b>Total Parts Cost</b> \$0.59
-----------------------------------	-----------------------------------	-----------------------------------	-----------------------------------

Additional Fees	Sale Amount	Cost Amount
SSC - Shop Supply Charges	\$0.00	\$0.00

Category	Sale	Cost
Labor	\$16,945.50	\$99.20
Parts	\$0.77	\$0.59
Sublet	\$0.00	\$0.00
Sublet Labor	\$0.00	\$0.00
Sublet Parts	\$0.00	\$0.00
Fees	\$0.00	\$0.00
Discounts	\$0.00	-
Tax	\$0.00	-
Deductible	\$0.00	-
Insurance/Warranty	\$0.00	-
<b>Invoice Total</b>	<b>\$16,946.27</b>	<b>\$99.79</b>





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$16,946.27

RO# : 40320 Tag# : TB526431

Check-in: Mon Mar 30, 2026 | 12:02 PM  
Ready for Pickup: Wed Apr 1, 2026 | 10:08 AM  
Promise Time: Sat Apr 4, 2026 | 6:00 PM

**Customer**  
Jeff Dietsche  
1245593  
+1 - (715) 262 - 0028

**Billing-Customer**  
Same as Customer

**Vehicle**  
2026 FOREST RIVER  
TRACER  
5ZT2TRNB6TB526431

**Service Advisor**  
KEVIN GOODIEL  
goodielk

**Clock In Info**

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
A	MISC	Tue Mar 31, 2026	10:08 AM	10:48 AM	0.68 hrs	W	kastenm	1 hrs
Tag: Regular Hour			Reason: -					
D	MISC	Tue Mar 31, 2026	10:49 AM	10:57 AM	0.13 hrs	W	kastenm	0 hrs
Tag: Regular Hour			Reason: -					
E	MISC	Tue Mar 31, 2026	10:57 AM	11:15 AM	0.29 hrs	W	kastenm	0.8 hrs
Tag: Regular Hour			Reason: -					
F	MISC	Tue Mar 31, 2026	11:15 AM	11:21 AM	0.10 hrs	W	kastenm	0 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Tue Mar 31, 2026	11:22 AM	11:43 AM	0.36 hrs	W	kastenm	0.4 hrs
Tag: Regular Hour			Reason: -					
C	MISC	Tue Mar 31, 2026	11:43 AM	12:15 PM	0.53 hrs	W	kastenm	1 hrs
Tag: Regular Hour			Reason: -					
C	MISC	Tue Mar 31, 2026	12:45 PM	1:09 PM	0.39 hrs	W	kastenm	-
Tag: Regular Hour			Reason: -					
E	MISC	Tue Mar 31, 2026	1:09 PM	1:40 PM	0.52 hrs	W	kastenm	-
Tag: Regular Hour			Reason: -					
D	MISC	Wed Apr 1, 2026	8:24 AM	8:35 AM	0.18 hrs	W	kastenm	-
Tag: Regular Hour			Reason: -					
E	MISC	Wed Apr 1, 2026	8:35 AM	8:54 AM	0.32 hrs	W	kastenm	-
Tag: Regular Hour			Reason: -					





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
**\$16,946.27**

RO# : 40320 Tag# : TB526431

Check-in: Mon Mar 30, 2026 | 12:02 PM  
 Ready for Pickup: Wed Apr 1, 2026 | 10:08 AM  
 Promise Time: Sat Apr 4, 2026 | 6:00 PM

**Customer**  
 Jeff Dietsche  
 1245593  
 +1 - (715) 262 - 0028

**Billing-Customer**  
 Same as Customer

**Vehicle**  
 2026 FOREST RIVER  
 TRACER  
 5ZT2TRNB6TB526431

**Service Advisor**  
 KEVIN GOODIEL  
 goodielk

**Accounting Info - Warranty**

GL Account #	Control #	Franchise	Amount
11400	40320	LINK RV	\$16,946.27
57200	40320	LINK RV	-\$16,945.50
67200	40320	LINK RV	\$99.20
14400	kastenm	LINK RV	-\$99.20
54200	40320	LINK RV	-\$0.77
64000	40320	LINK RV	\$0.59
14000	40320	LINK RV	-\$0.59

