



KEYSTONE

Pre-Authorization

Pre-Authorization number: PREAUTH88970 (PA03980637) Reference no.40281 Status: Approved

Servicing Dealer 16105 Name Link Ford & RV Minong LLC Address 1025 Hokah St Minong, WI 54859 VIN 4YDTATL29T8920348 Retail sold on

Root	Operation Description	Sublet	Sub Hours	Hours	Actual hours	Qty	Base hours	Complaint/Cause/Correction
5101906B	Light, Clearance & Taillight - Replace	0	0.8	0.2		1	0.2	<p>Complaint: Dealer states the DS taillight clip is cracked so taillight will not stay attached.</p> <p>Cause: Taillight cover is cracked around the mounting tab causing the cover to keep falling off when the trailer is moving.</p> <p>Correction: Will need to R&R taillight with license plate holder and rewire. Test to verify the light works.</p> <p>KRV – Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.</p> <p>KRV - Please retain part for possible return or additional photos. Keystone will notify you within 48 hours of submitting your claim for disposition of the part. Model+serial #s / vendor tags from complete component / vendor markings required.</p>
								Pre-Authorization number: PREAUTH88970 0.2

For paper claims only use one pre-authorization number per warranty claim form. Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.