



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$0.00

RO# : 40292 Tag# : T8920585

Check-in: Thu Mar 26, 2026 | 1:15 PM
Ready for Pickup: Tue Apr 7, 2026 | 10:19 AM
Promise Time: Tue Mar 31, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222
NO@GMAIL.COM
1025 WI-77
Minong, WI 54859

Pickup-Customer
Same as Customer
Billing-Customer
Same as Customer

Vehicle
2026 Keystone ASPEN
TRAIL
4YDTATG1XT8920585
1 Mi In
In Service Date:
01/01/2017
Stock #: KS26-37

Service Advisor
KEVIN GOODIEL
goodielk

A.	MISCELLANEOUS	DEALER STATES KITCHEN WINDOW IS MISSING THE TWIST ROD	Warranty Pay	\$0.00
----	---------------	---	--------------	--------

Job added by KEVIN GOODIEL on Thu Mar 26, 2026 | 1:15 PM

1. Missing wand

Op:1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.39	0	0	\$0.00	\$0.00
shurterc	-	0.15	0	0	\$0.00	\$0.00

1. Requested new wand for blind

Total Labor Sale
\$0.00

Total Labor Cost
\$0.00

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

B.	MISCELLANEOUS	DEALER STATES REPLACE LEFT REAR RUNNING LIGHT BULB	Warranty Pay	\$0.00
----	---------------	--	--------------	--------

Job added by KEVIN GOODIEL on Thu Mar 26, 2026 | 1:15 PM

1. Bad led light





1025 WI-77 Minong WI US 54859 www.linkrvidirect.com

Invoice
\$0.00

RO# : 40292 Tag# : T8920585

Check-in: Thu Mar 26, 2026 | 1:15 PM
Ready for Pickup: Tue Apr 7, 2026 | 10:19 AM
Promise Time: Tue Mar 31, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD71552007091
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ASPEN
TRAIL
4YDTATG1XT8920585

Service Advisor
KEVIN GOODIEL
goodielk

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0	0	0	\$0.00	\$0.00
shurterc	-	0.4	0	0	\$0.00	\$0.00

1. Tested light, confirmed light does not work. Removed light, tested for 12v power. Power confirmed. Reinstalled dead light and taped to temporarily seal until new light arrives.

Total Labor Sale
\$0.00

Total Labor Cost
\$0.00

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

	Category	Sale	Cost
	Labor	\$0.00	\$0.00
	Parts	\$0.00	\$0.00
	Sublet	\$0.00	\$0.00
	Sublet Labor	\$0.00	\$0.00
	Sublet Parts	\$0.00	\$0.00
	Fees	\$0.00	\$0.00
	Discounts	\$0.00	-
	Tax	\$0.00	-
	Deductible	\$0.00	-
	Insurance/Warranty	\$0.00	-
	Invoice Total	\$0.00	\$0.00





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$0.00

RO# : 40292 Tag# : T8920585

Check-in: Thu Mar 26, 2026 | 1:15 PM
Ready for Pickup: Tue Apr 7, 2026 | 10:19 AM
Promise Time: Tue Mar 31, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ASPEN
TRAIL
4YDTATG1XT8920585

Service Advisor
KEVIN GOODIEL
goodielk

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
A	MISC	Tue Mar 31, 2026	2:21 PM	2:45 PM	0.39 hrs	W	matthewl	0 hrs
Tag: Regular Hour			Reason: -					
A	MISC	Wed Apr 1, 2026	12:29 PM	12:38 PM	0.15 hrs	W	shurterc	0 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Wed Apr 1, 2026	12:47 PM	1:10 PM	0.40 hrs	W	shurterc	0 hrs
Tag: Regular Hour			Reason: -					
B	MISC	-	-	-	0 hrs	W	matthewl	0 hrs

