



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$0.00

RO# : 39578 Tag# : TB526431

Check-in: Mon Oct 6, 2025 | 8:33 AM

Ready for Pickup: Mon Mar 2, 2026 | 10:17 AM

Promise Time: Sat Oct 11, 2025 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222
no@email.com
1025 WI-77
Minong, WI 54859

Pickup-Customer
Same as Customer

Billing-Customer
Same as Customer

Vehicle
2026 FOREST RIVER
TRACER
5ZT2TRNB6TB526431
1 Mi In / 1 Mi Out
Stock #: FR26-06

Service Advisor
BECKY DALEIDEN
beckl

A.	MISCELLANEOUS	DEALER STATES Front driver side of fiberglass has white caulk or paint on finish.	Warranty Pay	\$0.00
----	---------------	---	--------------	--------

Job added by BECKY DALEIDEN on Mon Oct 6, 2025 | 8:33 AM

1. Sloppy caulk

Op:1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$12.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.15	0.5	0.5	\$0.00	\$12.00

1. Scraped caulk with plastic putty knife. Cleaned area with rag.

Total Labor Sale
\$0.00

Total Labor Cost
\$12.00

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

B.	MISCELLANEOUS	DEALER STATES DEALER STATES CAULKING ON FRONT IS MESSED UP	Warranty Pay	\$0.00
----	---------------	--	--------------	--------

Tags: Add-on

Job added by BECKY DALEIDEN on Mon Oct 6, 2025 | 8:33 AM

1. ????





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$0.00

RO# : 39578 Tag# : TB526431

Check-in: Mon Oct 6, 2025 | 8:33 AM

Ready for Pickup: Mon Mar 2, 2026 | 10:17 AM

Promise Time: Sat Oct 11, 2025 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 FOREST RIVER
TRACER
5ZT2TRNB6TB526431

Service Advisor
BECKY DALEIDEN
beckl

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$12.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.32	0.5	0.5	\$0.00	\$12.00

1. Cleaned area. Taped area. Caulked a bead. Smoothed bead. Did documentation.

Total Labor Sale
\$0.00

Total Labor Cost
\$12.00

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

Category	Sale	Cost
Labor	\$0.00	\$24.00
Parts	\$0.00	\$0.00
Sublet	\$0.00	\$0.00
Sublet Labor	\$0.00	\$0.00
Sublet Parts	\$0.00	\$0.00
Fees	\$0.00	\$0.00
Discounts	\$0.00	-
Tax	\$0.00	-
Deductible	\$0.00	-
Insurance/Warranty	\$0.00	-
Invoice Total	\$0.00	\$24.00





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$0.00

RO# : 39578 Tag# : TB526431

Check-in: Mon Oct 6, 2025 | 8:33 AM

Ready for Pickup: Mon Mar 2, 2026 | 10:17 AM

Promise Time: Sat Oct 11, 2025 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 FOREST RIVER
TRACER
5ZT2TRNB6TB526431

Service Advisor
BECKY DALEIDEN
beckl

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
A	MISC	Mon Mar 2, 2026	8:03 AM	8:13 AM	0.15 hrs	W	matthewl	0.5 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Mon Mar 2, 2026	8:13 AM	8:32 AM	0.32 hrs	W	matthewl	0.5 hrs
Tag: Regular Hour			Reason: -					

Accounting Info - Warranty

GL Account #	Control #	Franchise	Amount
11400	39578	LINK RV	\$0.00
57200	39578	LINK RV	\$0.00
67200	39578	LINK RV	\$24.00
14400	matthewl	LINK RV	-\$24.00

