



Claim C3926224

Last Modified By

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed warranty rate	Type	Date of Purchase
C3926224	C3921040	3/13/2026	3/13/2026	4YDFAVU20TE760398	16105		Link Ford & RV Minong LLC 1025 Hokah St Minong, WI 54859	165.00	0.00	WARR	1/1/1970
	A										

Deny code	Item number	Name	Quantity	Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
30	777992	Switch - 12V - Weatherproof - SPST - On/Off - w/Plate - Gasket & Butyl Tape - Black - Sigma - SP0169-15-260B-B	1	0	9.79	30.00	12.73	24.45	24.45	0.00	Approved

Switch missing

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
5104114A		Power Center - Wiring - Repair	0.5	0.5	0	0	1	0.5	Denied

Complaint Dealership states the front cap lights don't work.

Cause Power wire for nose cone light not attached to anything.

Correction Removed light from nose and removed the silicone sealant covering the hole the wiring goes through. Pulled the connections through hole and tested for power. Light were not receiving any power. Remove passenger side extrusion along underside of nose cone to locate the wires for light and where they were going. They ran into the framing, so went to passenger side batter compartment to locate. The wires went into the compartment and then into front storage compartment. Located wires in compartment, but had to drop ceiling panel to further trace wires direction. Wires ran across unit and came out behind the leveling touchpad. Wires were laying in the empty cavity not attached to anything. Brought wires out enough to test if they were actually for the nose cone light, and they were. Reinstalled and sealed all pieces of unit that were removed. Took pics of disassembled/removed pieces of unit. Needs hole drilled and light switch installed. *Unsure on labor code- Diag was 4.2 hours, labor 1 hour

Notes Appeal for denied part on C3921040
0

Submitted parts & subLet	12.73	Approved parts & subLet	12.73
Submitted labor & subLet	82.50	Approved labor & subLet	0.00
Submitted freight	24.45	Approved freight	24.45
Total Submitted	119.68	Total approved	37.18