



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$439.09

RO# : 40149 Tag# : T8920590

Check-in: Mon Feb 9, 2026 | 9:13 AM
Ready for Pickup: Thu Mar 5, 2026 | 11:38 AM
Promise Time: Sat Feb 14, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222
NO@GMAIL.COM
1025 WI-77
Minong, WI 54859

Pickup-Customer
Same as Customer

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ASPEN
TRAIL
4YDTATJ21T8920590
1 Mi In / 1 Mi Out
In Service Date:
01/01/2017
Stock #: KS26-31

Service Advisor
KEVIN GOODIEL
goodielk

| | | | | |
|----|---------------|--|--------------|----------|
| A. | MISCELLANEOUS | DEALER STATES Water heater door latch is broken and will not stay closed. Was zip tied shut. Took pics of damaged latch. | Warranty Pay | \$113.27 |
|----|---------------|--|--------------|----------|

Job added by KEVIN GOODIEL on Mon Feb 9, 2026 | 9:13 AM

1. Damage noted when dropped off from manufacturer. .50hr requested.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$49.50
Labor Cost: \$15.50

| Technician | Certification Number | Actual Hours | Assigned Bill Hours | Flag Hours | Labor Sale | Labor Cost |
|------------|----------------------|--------------|---------------------|------------|------------|------------|
| lafavet | - | 0.09 | 0.5 | 0.5 | \$49.50 | \$15.50 |

1. Removed old door and replaced with new door and latch.

Parts

Parts Total Sale Amount \$39.30
Parts Total Cost Amount \$30.23

| Name | Quantity | Unit Price | Sale Price | Cost Price |
|----------------------------|----------|------------|------------|------------|
| 719737 - WATER HEATER DOOR | 1 | \$39.30 | \$39.30 | \$30.23 |

Fees \$24.47

| Code | Description | Sale Amount | Cost Amount |
|------|-------------|-------------|-------------|
| FF | Freight Fee | \$24.47 | \$0.00 |

| | | | |
|------------------|------------------|------------------|------------------|
| Total Labor Sale | Total Labor Cost | Total Parts Sale | Total Parts Cost |
| \$49.50 | \$15.50 | \$39.30 | \$30.23 |





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$439.09

RO# : 40149 Tag# : T8920590

Check-in: Mon Feb 9, 2026 | 9:13 AM
Ready for Pickup: Thu Mar 5, 2026 | 11:38 AM
Promise Time: Sat Feb 14, 2026 | 6:00 PM

| | | | |
|---|---|---|---|
| Customer linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222 | Billing-Customer Same as Customer | Vehicle 2026 Keystone ASPEN TRAIL 4YDTATJ21T8920590 | Service Advisor KEVIN GOODIEL goodielk |
|---|---|---|---|

| | | | |
|-------------------------|--|---------------------|-----------------|
| B. MISCELLANEOUS | DEALER STATES Clothes hanger rod in closet by entry door is too short, causing it to fall out of brackets. Took pics. | Warranty Pay | \$149.77 |
|-------------------------|--|---------------------|-----------------|

Job added by KEVIN GOODIEL on Mon Feb 9, 2026 | 9:13 AM

1. Rod was cut too short. .50hr requested.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$82.50
Labor Cost: \$15.50

| Technician | Certification Number | Actual Hours | Assigned Bill Hours | Flag Hours | Labor Sale | Labor Cost |
|------------|----------------------|--------------|---------------------|------------|------------|------------|
| lafavet | - | 0.29 | 0.5 | 0.5 | \$82.50 | \$15.50 |

1. Needs new hanger rod. Measured, cut and installed new hanger rod. Inspected to make sure wouldn't fall out again.

Parts

Parts Total Sale Amount \$15.07
Parts Total Cost Amount \$11.59

| Name | Quantity | Unit Price | Sale Price | Cost Price |
|---------------------|----------|------------|------------|------------|
| 676939 - CLOSET ROD | 1 | \$15.07 | \$15.07 | \$11.59 |

Fees \$52.20

| Code | Description | Sale Amount | Cost Amount |
|------|-------------|-------------|-------------|
| FF | Freight Fee | \$52.20 | \$0.00 |

| | | | |
|------------------------------------|------------------------------------|------------------------------------|------------------------------------|
| Total Labor Sale \$82.50 | Total Labor Cost \$15.50 | Total Parts Sale \$15.07 | Total Parts Cost \$11.59 |
|------------------------------------|------------------------------------|------------------------------------|------------------------------------|





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$439.09

RO# : 40149 Tag# : T8920590

Check-in: Mon Feb 9, 2026 | 9:13 AM
Ready for Pickup: Thu Mar 5, 2026 | 11:38 AM
Promise Time: Sat Feb 14, 2026 | 6:00 PM

| | | | |
|---|---|---|---|
| Customer linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222 | Billing-Customer Same as Customer | Vehicle 2026 Keystone ASPEN TRAIL 4YDTATJ21T8920590 | Service Advisor KEVIN GOODIEL goodielk |
|---|---|---|---|

| | | | |
|-------------------------|---|---------------------|----------------|
| C. MISCELLANEOUS | DEALER STATES Dinette back cushions Velcro isn't attached to dinette back, was never applied. Took pics of cushions. | Warranty Pay | \$33.00 |
|-------------------------|---|---------------------|----------------|

Job added by KEVIN GOODIEL on Mon Feb 9, 2026 | 9:13 AM

1. Velcro wasn't attached to dinette back from manufacturer. .50hr requested.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$33.00
Labor Cost: \$6.20

| Technician | Certification Number | Actual Hours | Assigned Bill Hours | Flag Hours | Labor Sale | Labor Cost |
|------------|----------------------|--------------|---------------------|------------|------------|------------|
| lafavet | - | 0.12 | 0.2 | 0.2 | \$33.00 | \$6.20 |

1. The Velcro pieces were stuck to the cushions, so removed the paper backing and stuck to the dinette backs on both benches. Stapled the strips of Velcro to the dinette backs and made sure they were not coming off.

| | | | |
|------------------------------------|-----------------------------------|-----------------------------------|-----------------------------------|
| Total Labor Sale \$33.00 | Total Labor Cost \$6.20 | Total Parts Sale \$0.00 | Total Parts Cost \$0.00 |
|------------------------------------|-----------------------------------|-----------------------------------|-----------------------------------|

| | | | |
|-------------------------|---|---------------------|----------------|
| D. MISCELLANEOUS | DEALER STATES Roof has several spots that need recaulk. Took pics. | Warranty Pay | \$60.55 |
|-------------------------|---|---------------------|----------------|

Job added by KEVIN GOODIEL on Mon Feb 9, 2026 | 9:13 AM

1. From manufacturer wasn't sealed correctly. .50hr requested.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$49.50
Labor Cost: \$15.50

| Technician | Certification Number | Actual Hours | Assigned Bill Hours | Flag Hours | Labor Sale | Labor Cost |
|------------|----------------------|--------------|---------------------|------------|------------|------------|
| lafavet | - | 0.33 | 0.5 | 0.5 | \$49.50 | \$15.50 |

1. Resealed areas that needed to be resealed.





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$439.09

RO# : 40149 Tag# : T8920590

Check-in: Mon Feb 9, 2026 | 9:13 AM
Ready for Pickup: Thu Mar 5, 2026 | 11:38 AM
Promise Time: Sat Feb 14, 2026 | 6:00 PM

| | | | |
|---|---|---|---|
| Customer linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222 | Billing-Customer Same as Customer | Vehicle 2026 Keystone ASPEN TRAIL 4YDTATJ21T8920590 | Service Advisor KEVIN GOODIEL goodielk |
|---|---|---|---|

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$49.50
Labor Cost: \$15.50

Parts

Parts Total Sale Amount \$11.05
Parts Total Cost Amount \$8.50

| Name | Quantity | Unit Price | Sale Price | Cost Price |
|----------------------------|----------|------------|------------|------------|
| 08091088 - LAP SEALANT WHT | 1 | \$11.05 | \$11.05 | \$8.50 |

| | | | |
|------------------|------------------|------------------|------------------|
| Total Labor Sale | Total Labor Cost | Total Parts Sale | Total Parts Cost |
| \$49.50 | \$15.50 | \$11.05 | \$8.50 |

| | | | |
|-------------------------|--|---------------------|----------------|
| E. MISCELLANEOUS | DEALER STATES TV Antenna booster is mounted crooked. Can pivot it on bottom screw, so top screw isn't holding at all. Took pic. | Warranty Pay | \$82.50 |
|-------------------------|--|---------------------|----------------|

Job added by KEVIN GOODIEL on Mon Feb 9, 2026 | 9:13 AM

1. Hole for coax and 12V wires was cut too large. .50hr requested.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$82.50
Labor Cost: \$15.50

| Technician | Certification Number | Actual Hours | Assigned Bill Hours | Flag Hours | Labor Sale | Labor Cost |
|------------|----------------------|--------------|---------------------|------------|------------|------------|
| lafavet | - | 0.27 | 0.5 | 0.5 | \$82.50 | \$15.50 |

1. Removed TV booster from wall and found the hole is cut too large. There are screw holes from it being moved before, but then it isn't in line with the 120V outlet that is right next to it. Took a section of scrap wall panel and inserted into hole to fill, then stapled to the units wall panel. Puttied the staple marks and then fastened the TV booster back in place.





1025 WI-77 Minong WI US 54859 www.linkrvidirect.com

Invoice
\$439.09

RO# : 40149 Tag# : T8920590

Check-in: Mon Feb 9, 2026 | 9:13 AM
Ready for Pickup: Thu Mar 5, 2026 | 11:38 AM
Promise Time: Sat Feb 14, 2026 | 6:00 PM

| | | | |
|---|---|---|---|
| Customer linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222 | Billing-Customer Same as Customer | Vehicle 2026 Keystone ASPEN TRAIL 4YDTATJ21T8920590 | Service Advisor KEVIN GOODIEL goodielk |
|---|---|---|---|

| | | | |
|------------------------------------|------------------------------------|-----------------------------------|-----------------------------------|
| Total Labor Sale \$82.50 | Total Labor Cost \$15.50 | Total Parts Sale \$0.00 | Total Parts Cost \$0.00 |
|------------------------------------|------------------------------------|-----------------------------------|-----------------------------------|

| | | | |
|-------------------------|---|---------------------|---------------|
| F. MISCELLANEOUS | DEALER STATES Nothing in unit uses a remote. NOT AN ACTUAL ISSUE | Warranty Pay | \$0.00 |
|-------------------------|---|---------------------|---------------|

Job added by KEVIN GOODIEL on Mon Feb 9, 2026 | 9:13 AM

1. NO ACTUAL ISSUE, JUST NOTED.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

| Technician | Certification Number | Actual Hours | Assigned Bill Hours | Flag Hours | Labor Sale | Labor Cost |
|------------|----------------------|--------------|---------------------|------------|------------|------------|
| lafavet | - | 0 | 0 | 0 | \$0.00 | \$0.00 |

1. no remote

| | | | |
|-----------------------------------|-----------------------------------|-----------------------------------|-----------------------------------|
| Total Labor Sale \$0.00 | Total Labor Cost \$0.00 | Total Parts Sale \$0.00 | Total Parts Cost \$0.00 |
|-----------------------------------|-----------------------------------|-----------------------------------|-----------------------------------|





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$439.09

RO# : 40149 Tag# : T8920590

Check-in: Mon Feb 9, 2026 | 9:13 AM
Ready for Pickup: Thu Mar 5, 2026 | 11:38 AM
Promise Time: Sat Feb 14, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ASPEN
TRAIL
4YDTATJ21T8920590

Service Advisor
KEVIN GOODIEL
goodielk

| Category | Sale | Cost |
|----------------------|-----------------|-----------------|
| Labor | \$297.00 | \$68.20 |
| Parts | \$65.42 | \$50.32 |
| Sublet | \$0.00 | \$0.00 |
| Sublet Labor | \$0.00 | \$0.00 |
| Sublet Parts | \$0.00 | \$0.00 |
| Fees | \$76.67 | \$0.00 |
| Discounts | \$0.00 | - |
| Tax | \$0.00 | - |
| Deductible | \$0.00 | - |
| Insurance/Warranty | \$0.00 | - |
| Invoice Total | \$439.09 | \$118.52 |

Clock In Info

| # | Opcode | Date | Clock In | Clock Out | Time Spent | Pay Type | Technician | Flag Hrs |
|---|--------|-----------------|--------------------------|------------------|------------|----------|------------|----------|
| E | MISC | Mon Feb 9, 2026 | 9:24 AM | 9:32 AM | 0.13 hrs | W | lafavet | 0.5 hrs |
| | | | Tag: Regular Hour | Reason: - | | | | |
| C | MISC | Mon Feb 9, 2026 | 9:51 AM | 9:58 AM | 0.12 hrs | W | lafavet | 0.2 hrs |
| | | | Tag: Regular Hour | Reason: - | | | | |
| B | MISC | Mon Feb 9, 2026 | 10:01 AM | 10:11 AM | 0.16 hrs | W | lafavet | 0.5 hrs |
| | | | Tag: Regular Hour | Reason: - | | | | |
| D | MISC | Mon Feb 9, 2026 | 10:14 AM | 10:34 AM | 0.33 hrs | W | lafavet | 0.5 hrs |
| | | | Tag: Regular Hour | Reason: - | | | | |
| E | MISC | Mon Feb 9, 2026 | 10:34 AM | 10:43 AM | 0.14 hrs | W | lafavet | - |
| | | | Tag: Regular Hour | Reason: - | | | | |





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$439.09

RO# : 40149 Tag# : T8920590

Check-in: Mon Feb 9, 2026 | 9:13 AM
Ready for Pickup: Thu Mar 5, 2026 | 11:38 AM
Promise Time: Sat Feb 14, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ASPEN
TRAIL
4YDTATJ21T8920590

Service Advisor
KEVIN GOODIEL
goodielk

Clock In Info

| # | Opcode | Date | Clock In | Clock Out | Time Spent | Pay Type | Technician | Flag Hrs |
|-------------------|--------|------------------|-----------|-----------|------------|----------|------------|----------|
| A | MISC | Mon Feb 23, 2026 | 2:06 PM | 2:07 PM | 0.02 hrs | W | lafavet | 0.5 hrs |
| Tag: Regular Hour | | | Reason: - | | | | | |
| B | MISC | Mon Feb 23, 2026 | 2:09 PM | 2:17 PM | 0.13 hrs | W | lafavet | - |
| Tag: Regular Hour | | | Reason: - | | | | | |
| A | MISC | Mon Feb 23, 2026 | 2:18 PM | 2:22 PM | 0.07 hrs | W | lafavet | - |
| Tag: Regular Hour | | | Reason: - | | | | | |
| F | MISC | - | - | - | 0 hrs | W | lafavet | 0 hrs |

