



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$65.42

RO# : 40149 Tag# : T8920590

Check-in: Mon Feb 9, 2026 | 9:13 AM
Ready for Pickup: Thu Feb 12, 2026 | 3:08 PM
Promise Time: Sat Feb 14, 2026 | 6:00 PM

Customer linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222 NO@GMAIL.COM 1025 WI-77 Minong, WI 54859	Pickup-Customer Same as Customer	Vehicle 2026 Keystone ASPEN TRAIL 4YDTATJ21T8920590 1 Mi In In Service Date: 01/01/2017 Stock #: KS26-31	Service Advisor KEVIN GOODIEL goodielk
	Billing-Customer Same as Customer		

A. MISCELLANEOUS	DEALER STATES Water heater door latch is broken and will not stay closed. Was zip tied shut. Took pics of damaged latch.	Warranty Pay	\$39.30
-------------------------	---	---------------------	----------------

Job added by KEVIN GOODIEL on Mon Feb 9, 2026 | 9:13 AM

1. Damage noted when dropped off from manufacturer. .50hr requested.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	0	0	0	\$0.00	\$0.00

Parts

Parts Total Sale Amount \$39.30

Parts Total Cost Amount \$30.23

Name	Quantity	Unit Price	Sale Price	Cost Price
719737 - WATER HEATER DOOR	1	\$39.30	\$39.30	\$30.23

Total Labor Sale
\$0.00

Total Labor Cost
\$0.00

Total Parts Sale
\$39.30

Total Parts Cost
\$30.23

B. MISCELLANEOUS	DEALER STATES Clothes hanger rod in closet by entry door is too short, causing it to fall out of brackets. Took pics.	Warranty Pay	\$15.07
-------------------------	--	---------------------	----------------

Job added by KEVIN GOODIEL on Mon Feb 9, 2026 | 9:13 AM

1. Rod was cut too short. .50hr requested.





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$65.42

RO# : 40149 Tag# : T8920590

Check-in: Mon Feb 9, 2026 | 9:13 AM
Ready for Pickup: Thu Feb 12, 2026 | 3:08 PM
Promise Time: Sat Feb 14, 2026 | 6:00 PM

Customer linkautomotive - 2174 PD71552007091 Customer 1235491 +1 - (715) 466 - 2222	Billing-Customer Same as Customer	Vehicle 2026 Keystone ASPEN TRAIL 4YDTATJ21T8920590	Service Advisor KEVIN GOODIEL goodielk
---	---	---	---

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00
Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	0.16	0	0	\$0.00	\$0.00

1. Needs new hanger rod.

Parts

Parts Total Sale Amount \$15.07
Parts Total Cost Amount \$11.59

Name	Quantity	Unit Price	Sale Price	Cost Price
676939 - CLOSET ROD	1	\$15.07	\$15.07	\$11.59

Total Labor Sale \$0.00	Total Labor Cost \$0.00	Total Parts Sale \$15.07	Total Parts Cost \$11.59
-----------------------------------	-----------------------------------	------------------------------------	------------------------------------

C. MISCELLANEOUS	DEALER STATES Dinette back cushions Velcro isn't attached to dinette back, was never applied. Took pics of cushions.	Warranty Pay	\$0.00
-------------------------	---	---------------------	---------------

Job added by KEVIN GOODIEL on Mon Feb 9, 2026 | 9:13 AM

1. Velcro wasn't attached to dinette back from manufacturer. .50hr requested.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00
Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	0.12	0	0	\$0.00	\$0.00

1. The Velcro pieces were stuck to the cushions, so removed the paper backing and stuck to the dinette backs on both





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$65.42

RO# : 40149 Tag# : T8920590

Check-in: Mon Feb 9, 2026 | 9:13 AM
Ready for Pickup: Thu Feb 12, 2026 | 3:08 PM
Promise Time: Sat Feb 14, 2026 | 6:00 PM

Customer linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	Billing-Customer Same as Customer	Vehicle 2026 Keystone ASPEN TRAIL 4YDTATJ21T8920590	Service Advisor KEVIN GOODIEL goodielk
---	---	---	---

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00
Labor Cost: \$0.00

benches. Stapled the strips of Velcro to the dinette backs and made sure they were not coming off.

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
\$0.00	\$0.00	\$0.00	\$0.00

D. MISCELLANEOUS	DEALER STATES Roof has several spots that need recaulk. Took pics.	Warranty Pay	\$11.05
------------------	--	--------------	---------

Job added by KEVIN GOODIEL on Mon Feb 9, 2026 | 9:13 AM

1. From manufacturer wasn't sealed correctly. .50hr requested.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00
Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	0.33	0	0	\$0.00	\$0.00

1. Resealed ares that needed to be resealed.

Parts

Parts Total Sale Amount \$11.05
Parts Total Cost Amount \$8.50

Name	Quantity	Unit Price	Sale Price	Cost Price
08091088 - LAP SEALANT WHT	1	\$11.05	\$11.05	\$8.50

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
\$0.00	\$0.00	\$11.05	\$8.50





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$65.42

RO# : 40149 Tag# : T8920590

Check-in: Mon Feb 9, 2026 | 9:13 AM
Ready for Pickup: Thu Feb 12, 2026 | 3:08 PM
Promise Time: Sat Feb 14, 2026 | 6:00 PM

Customer linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	Billing-Customer Same as Customer	Vehicle 2026 Keystone ASPEN TRAIL 4YDTATJ21T8920590	Service Advisor KEVIN GOODIEL goodielk
---	---	---	---

E. MISCELLANEOUS	DEALER STATES TV Antenna booster is mounted crooked. Can pivot it on bottom screw, so top screw isn't holding at all. Took pic.	Warranty Pay	\$0.00
-------------------------	--	---------------------	---------------

Job added by KEVIN GOODIEL on Mon Feb 9, 2026 | 9:13 AM

1. Hole for coax and 12V wires was cut too large. .50hr requested.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	0.27	0	0	\$0.00	\$0.00

1. Removed TV booster from wall and found the hole is cut too large. There are screw holes from it being moved before, but then it isn't in line with the 120V outlet that is right next to it. Took a section of scrap wall panel and inserted into hole to fill, then stapled to the units wall panel. Puttied the staple marks and then fastened the TV booster back in place.

Total Labor Sale \$0.00	Total Labor Cost \$0.00	Total Parts Sale \$0.00	Total Parts Cost \$0.00
-----------------------------------	-----------------------------------	-----------------------------------	-----------------------------------

F. MISCELLANEOUS	DEALER STATES Nothing in unit uses a remote. NOT AN ACTUAL ISSUE	Warranty Pay	\$0.00
-------------------------	---	---------------------	---------------

Job added by KEVIN GOODIEL on Mon Feb 9, 2026 | 9:13 AM

1. NO ACTUAL ISSUE, JUST NOTED.





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$65.42

RO# : 40149 Tag# : T8920590

Check-in: Mon Feb 9, 2026 | 9:13 AM
Ready for Pickup: Thu Feb 12, 2026 | 3:08 PM
Promise Time: Sat Feb 14, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ASPEN
TRAIL
4YDTATJ21T8920590

Service Advisor
KEVIN GOODIEL
goodielk

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00
Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	0	0	0	\$0.00	\$0.00

Total Labor Sale
\$0.00

Total Labor Cost
\$0.00

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

Category	Sale	Cost
Labor	\$0.00	\$0.00
Parts	\$65.42	\$50.32
Sublet	\$0.00	\$0.00
Sublet Labor	\$0.00	\$0.00
Sublet Parts	\$0.00	\$0.00
Fees	\$0.00	\$0.00
Discounts	\$0.00	-
Tax	\$0.00	-
Deductible	\$0.00	-
Insurance/Warranty	\$0.00	-
Invoice Total	\$65.42	\$50.32





1025 WI-77 Minong WI US 54859 www.linkrvidirect.com

Invoice
\$65.42

RO# : 40149 Tag# : T8920590

Check-in: Mon Feb 9, 2026 | 9:13 AM
Ready for Pickup: Thu Feb 12, 2026 | 3:08 PM
Promise Time: Sat Feb 14, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ASPEN
TRAIL
4YDTATJ21T8920590

Service Advisor
KEVIN GOODIEL
goodielk

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
E	MISC	Mon Feb 9, 2026	9:24 AM	9:32 AM	0.13 hrs	W	lafavet	0 hrs
Tag: Regular Hour			Reason: -					
C	MISC	Mon Feb 9, 2026	9:51 AM	9:58 AM	0.12 hrs	W	lafavet	0 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Mon Feb 9, 2026	10:01 AM	10:11 AM	0.16 hrs	W	lafavet	0 hrs
Tag: Regular Hour			Reason: -					
D	MISC	Mon Feb 9, 2026	10:14 AM	10:34 AM	0.33 hrs	W	lafavet	0 hrs
Tag: Regular Hour			Reason: -					
E	MISC	Mon Feb 9, 2026	10:34 AM	10:43 AM	0.14 hrs	W	lafavet	-
Tag: Regular Hour			Reason: -					
A	MISC	-	-	-	0 hrs	W	lafavet	0 hrs
F	MISC	-	-	-	0 hrs	W	lafavet	0 hrs

Accounting Info - Warranty

GL Account #	Control #	Franchise	Amount
11400	40149	LINK RV	\$65.42
57200	40149	LINK RV	\$0.00
54200	40149	LINK RV	-\$65.42
64000	40149	LINK RV	\$50.32
14000	40149	LINK RV	-\$50.32

