



Claim CLAIM82771 (C3926175)

Last Modified By

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Warranty rate	Changed Type	Date of Purchase
CLAIM82771 (C3926175)	40149	2/9/2026	3/5/2026	4YDTATJ21T8920590	PA03963102	16105	Link Ford & RV Minong LLC 1025 Hokah St Minong, WI 54859	165.00	0.00	WARR	1/1/1970

Deny code	Item number	Name	Quantity	Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
	719737	Water Heater - Door - For Tankless Water Heater - Black - ST Model	1	1	30.23	30.00	39.30	24.47	24.47	0.00	Approved
inv 5129626 Component Model ST42 Component Serial Number 253203260T											
90	676939	Rod - Closet - Vinyl Coated - 108" - Black	1	0	11.59	30.00	15.07	52.20	52.20	0.00	Approved
inv 5129507a Component Serial Number 815 12/2/25											
	211112	Warranty Shop Supply - Fasteners - Screws - Staples - Bolts and Etc.	1	0	2.00	30.00	2.60	0.00	0.00	0.00	Approved
	102107	Sealant - Silicone - Neutral Cure - Translucent - (30/Case)	1	0	8.50	30.00	11.05	0.00	0.00	0.00	Approved
	211112	Warranty Shop Supply - Fasteners - Screws - Staples - Bolts and Etc.	1	0	2.00	30.00	2.60	0.00	0.00	0.00	Approved

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	4131908B	Water Heater - Suburban - Exterior Door	0.3	0.3	49.5	0	1	0.3	Approved
Complaint DEALER STATES WATER HEATER DOOR LATCH IS BROKEN & WILL NOT STAY CLOSED.					Notes STOCK 49.5				
Cause FOUND THE WATER HEATER DOOR LATCH BROKEN.									
Correction TECH WILL REPLACE THE WATER HEATER DOOR, TEST TO MAKE SURE IT WORKS AS PER DESIGN. Requesting additional time for diagnostic per state of WI law. 0.5 hour total.									

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	3101714B	Closet - Clothes Hanger	0.5	0.5	82.5	0	1	0.5	Approved
Complaint Dealer states the close hanger rod in the closet by the entry door is too short causing it to fall out of brackets.									
Cause Rod was cut too short at the manufacturer.									
Correction Need to replace rod. 0.2 for diagnostics and 0.5 for repair.									



Claim CLAIM82771 (C3926175)

Last Modified By

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
3302114A		Dinette Cushions - Repair	0.2	0.2	33	0	1	0.2	Approved
<p>Complaint Dinette back cushions velcro isn't attached to dinette back, was never applied.</p> <p>Cause Velcro was never attached to the binette back from the manufacturer.</p> <p>Correction Velcro pieces were stud to the cushions so we removed the paper backing and stuck to the dinette backs on both benches. Stapled the strips of velcro to the dinette backs and made sure they were not coming off. Diagnostics 0.15 hour and Labor 0.5 hour</p>									

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
2203314D		Sealant - Roof Only Multiple Areas	0.3	0.3	49.5	0	1	0.3	Approved
<p>Complaint Dealer states the roof has several spots that need recaulk.</p> <p>Cause Was not sealed properly from manufacturer.</p> <p>Correction Resealed areas that needed to be resealed. 0.3 diagnostics and 0.5 labor.</p>									

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
4216014A		Antenna - Stationary - Complete Unit	0.5	0.5	82.5	0	1	0.5	Approved
<p>Complaint Dealer states the TV antenna booster is mounted crooked. Can pivot it on bottom screw so top screw isn't holding at all.</p> <p>Cause Hole for coax and 12V wires was cut too large from manufacturer.</p> <p>Correction Removed TV booster from wall and found the hole is cut too large. There are screw holes from it being moved before, but then it isn't in line with the 120V outlet that is right next to it. Took a section of scrap wall panel and inserted into hole to fill, then stapled to the units wall panel. Puttied the staple marks and then fastened the TV booster back in place. 0.3 diagnostics and 0.5 labor</p>									

Submitted parts & subLet 70.62

Submitted labor & subLet 297.00

Submitted freight 76.67

Total Submitted 444.29

Approved parts & subLet 70.62

Approved labor & subLet 297.00

Approved freight 76.67

Total approved 444.29