

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 1054928
 LINK FORD & RV MINONG LLC
 1025 W HOKAH ST
 MINONG, WI 54859
 USA

CLAIM STATUS Paid
 CLAIM 2593014
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 5ZT2AVPB7TB941916
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 050 / 050
 ITEM # AVT25RBS
 DEALER RO # 40179
 CLAIM START DATE 02/26/2026
 CLAIM END DATE 02/26/2026

Labor rate: \$165.00
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code 60-136-15-00-001499	Operational Description Water Line - Plumbing/Fresh Water Supply/Repair or Replace/No Tread Code
	Complaint, Cause, Correction	
	Original Note : alix@dealer-advisors.com, 2026-02-26 14:12:54 :: Complaint: Dealer states that the cup sprayer on the sink has no water coming out of it. Cause: Chunk of Styrofoam in the waterline causing no water to come through. Correction: Removed the Styrofoam from the water line and it now works as it should. Diagnosis - 0.17 hour, Labor 0.5 hour This was previously submitted and approved under the incorrect dealership/account number.	

Model#	Dlr Sub Hrs	0.67	Sub Labor Amt \$110.55
Serial#	Appr Hrs	0.67	Appr Labor Amt \$110.55

Notes

NVCB .67 to diag and remove the debris from the water line. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp.

Submitted	Labor Amt	\$110.55	Approved	Labor Amt	\$110.55
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$110.55		Total	\$110.55

DEALER _____ DATE _____
 SIGNATURE
 I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
 SIGNATURE
 All repairs described have been inspected and are satisfactory.