



Claim CLAIM83306 (C3926704) Last Modified By

										Changed		
Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	warranty rate	Date of Type	Purchase	
CLAIM83306 (C3926704)	40193	2/27/2026	3/13/2026	4YDFAVU20TE760398	PA03976256	16105	Link Ford & RV Minong LLC 1025 Hokah St Minong, WI 54859	165.00	0.00	WARR	1/1/1970	

Deny code	Item number	Name	Quantity	Qty Returned	Dealer price	Part Markup	Appr total	Sub Freight	Sub Freight	Sublet	Status
92	756339	Cover - Recessed Triangle Corner - 25 3/4" x 32 1/2" - ABS - Black	1	0	18.92	30.00	24.60	55.51	55.51	0.00	Approved
Inv 5135301											

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	3201808B	Decorative Wood Trim - Replace - per piece	0.2	0.2	33	0	1	0.2	Approved
Complaint Dealer states there is a broken corner moulding in the closet.			Notes Dealer Stock; Plant 311 1/29/26						
Cause Manufacturer overtightened the screws and it cracked the moulding.			33						
Correction R&R moulding.									
					Submitted parts & subLet	24.60	Approved parts & subLet	24.60	
					Submitted labor & subLet	33.00	Approved labor & subLet	33.00	
					Submitted freight	55.51	Approved freight	55.51	
					Total Submitted	113.11	Total approved	113.11	