

DEALER ACCOUNT #	1054928	CLAIM STATUS	Paid
LINK FORD & RV MINONG LLC		CLAIM	2601057
1025 W HOKAH ST		CLAIM ORIGIN	WEB
MINONG, WI 54859		ORIGINAL CLAIM ID	
USA		VIN	5ZT2TRPB1TB526933
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$165.00	SITE/WAREHOUSE	048 / 048B
OWNER INFORMATION		ITEM #	TRT248RE
		DEALER RO #	40235
		CLAIM START DATE	03/05/2026
		CLAIM END DATE	03/19/2026
Retail Date of Purchase		WARRANTY EXPIRATION DATE	

Labor Line# 1	Operation Code	Operational Description			
	70-170-01-11-002054	Suburban Furnace Wall Thermostat - Appliances/Furnace (Suburban)/Replace/ Electrical			
Complaint, Cause, Correction					
Original Note : alix@dealer-advisors.com, 2026-03-05 17:03:22 :: Complaint: Dealer states the control pad for the water heater is frozen. Blinks -5 and will not take any commands. Will not go up, down change from F to C.					
Cause: Water heater thermostat works like it should after camper was unplugged and moved to a different bay.					
Correction: Water heater thermostat works like it should after camper was unplugged and moved to a different bay. Just needed a power reboot. Tested water heater and it go up to temp like it should, re-winterized camper after testing. Additional Note : alix@dealer-advisors.com, 2026-03-05 17:03:41 :: No repair code.					
Model# 1	Dlr Sub Hrs	0.50	Sub Labor Amt \$82.50		
Serial# 1	Appr Hrs	0.00	Appr Labor Amt \$0.00		
Notes					
Denied, this is not a warranty issue. There was no issue found. Denied, Forest River respectfully denies warranty and goodwill participation in this repair to this unit. Dp					

Labor Line# 2	Operation Code		Operational Description	
	20-44-19-00-000553		Roof Moldings - Front or Rear - Exterior/Roof/Reseal/No Tread Code	
	Complaint, Cause, Correction			
	Original Note : alix@dealer-advisors.com, 2026-03-05 17:04:23 :: Complaint: Dealer states the roof needs to be sealed in some spots. Cause: Front corner extrusion was missing some sealant. Correction: Reseal roof.			
	Model#	Dir Sub Hrs	0.30	Sub Labor Amt
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$49.50
Notes				
NVCB .30 to use sealant to fill in and cover the seal voids. Per dealers description of this repair.				
This authorization is pending ALL requirements of repair code have been met. Dp.				

Part Line# 1	Item #	Description	Part tag
	USERPART	shop supplies - sealant	
	Model #	Serial #	Part tag
	Sub Qty 1.00	Sub Dlr Price \$2.48	Sub Freight \$0.00
	Appr Qty 1.00	Appr Dlr Price \$2.48	Appr Freight \$0.00
	Notes		

Labor	Operation Code	Operational Description
Line# 3	20-46-24-00-000721	Window - Exterior/Windows/Repair/No Tread Code
	Complaint, Cause, Correction	

Original Note : alix@dealer-advisors.com, 2026-03-05 17:05:48 :: Complaint: Dealer states the exterior wgold tinted window has what appears to be sealant smears on it. Attempted to remove with glass cleaner. Cause: Sealant dripped on window by main door. Correction: Cleaned window with adhesive remover to get the sealant off then cleaned with glass cleaner.

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$49.50
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$49.50

Notes
NVCB .30 to clean the excess sealant from the window. Per dealers description of this repair.
This authorization is pending ALL requirements of repair code have been met. Dp.

Part Line#	1	Item #	Description
		USERPART	shop supplies - adhesive remover and glass cleaner
		Model #	Serial #
		Sub Qty	1.00
		Sub Dlr Price	\$2.48
		Sub Freight	\$0.00
		Appr Qty	1.00
		Appr Dlr Price	\$2.48
		Appr Freight	\$0.00

Notes

Submitted			Approved		
Labor Amt	\$181.50		Labor Amt	\$99.00	
Parts & Freight	\$4.96		Parts & Freight	\$4.96	
Total	\$186.46		Total	\$103.96	

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.