



1025 WI-77 Minong WI US 54859 www.linkrvidirect.com

Invoice
\$379.50

RO# : 40247 Tag# : TB526916

Check-in: Mon Mar 9, 2026 | 3:41 PM
Ready for Pickup: Wed Mar 11, 2026 | 9:08 AM
Promise Time: Sat Mar 14, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222
NO@GMAIL.COM
1025 WI-77
Minong, WI 54859

Pickup-Customer
Same as Customer
Billing-Customer
Same as Customer

Vehicle
2026 FOREST RIVER
TRACER
5ZT2TRNB8TB526916
1 Mi In
Stock #: FR26-22

Service Advisor
KEVIN GOODIEL
goodielk

A.	MISCELLANEOUS	DEALER STATES THE FELT IS COMING OFF THE INSIDE OF CARGO BAY	Warranty Pay	\$0.00
----	---------------	--	--------------	--------

Job added by KEVIN GOODIEL on Mon Mar 9, 2026 | 3:41 PM

1. Felt like material was loose.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.14	0	0	\$0.00	\$0.00

1. Restapled felt.

Total Labor Sale
\$0.00

Total Labor Cost
\$0.00

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

B.	MISCELLANEOUS	DEALER STATES FAN COVER ON ROOF HAS A HUGE SMEAR OF UNKNOWN SUBSTANCE	Warranty Pay	\$66.00
----	---------------	---	--------------	---------

Job added by KEVIN GOODIEL on Mon Mar 9, 2026 | 3:41 PM

1. Smear





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$379.50

RO# : 40247 Tag# : TB526916

Check-in: Mon Mar 9, 2026 | 3:41 PM
Ready for Pickup: Wed Mar 11, 2026 | 9:08 AM
Promise Time: Sat Mar 14, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 FOREST RIVER
TRACER
5ZT2TRNB8TB526916

Service Advisor
KEVIN GOODIEL
goodielk

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$66.00

Labor Cost: \$9.60

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.31	0.4	0.4	\$66.00	\$9.60

1. Came off with citron and rag.

Total Labor Sale
\$66.00

Total Labor Cost
\$9.60

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

C. MISCELLANEOUS	DEALER STATES THE ROOF NEED SEALED IN SOME SPOTS	Warranty Pay	\$82.50
-------------------------	---	---------------------	----------------

Job added by KEVIN GOODIEL on Mon Mar 9, 2026 | 3:41 PM

1. All 4 corners of roof needed quad around drain spouts and extrusions.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$82.50

Labor Cost: \$12.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.05	0.5	0.5	\$82.50	\$12.00

1. resealed roof in spots that are needed

Total Labor Sale
\$82.50

Total Labor Cost
\$12.00

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

D. MISCELLANEOUS	DEALER STATES THE BOARD THAT ATTACHES ISLAND LEG TO THE FLOOR IS SPLIT IN 2 FROM SCREW BEING TOO TIGHT	Warranty Pay	\$99.00
-------------------------	---	---------------------	----------------





1025 WI-77 Minong WI US 54859 www.linkrvidirect.com

Invoice
\$379.50

RO# : 40247 Tag# : TB526916

Check-in: Mon Mar 9, 2026 | 3:41 PM
Ready for Pickup: Wed Mar 11, 2026 | 9:08 AM
Promise Time: Sat Mar 14, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 FOREST RIVER
TRACER
5ZT2TRNB8TB526916

Service Advisor
KEVIN GOODIEL
goodielk

Job added by KEVIN GOODIEL on Mon Mar 9, 2026 | 3:41 PM

1. Wood was split from screw.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$99.00

Labor Cost: \$14.40

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.59	0.6	0.6	\$99.00	\$14.40

1. Had to chisel old wood out. Removed staples, had to remove old screw with vice grip, cut new piece of wood, predrilled so it would not split, fastened wood, stapled leg to wood anchor.

Total Labor Sale
\$99.00

Total Labor Cost
\$14.40

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

E.	MISCELLANEOUS	DEALER STATES THAT 2 OUT OF 4 CABINET FACES ON ISLAND ARE CROOKED.	Warranty Pay	\$132.00
----	---------------	--	--------------	----------

Tags: [Add-on](#)

Job added by KEVIN GOODIEL on Mon Mar 9, 2026 | 3:43 PM

1. Drawer tracks were crooked,, out of square.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$132.00

Labor Cost: \$19.20

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.61	0.8	0.8	\$132.00	\$19.20

1. Removed drawers. Unscrewed back of track, squared tracks to cabinet, Refastened tracks on 2 out of drawers. Top and bottom.





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$379.50

RO# : 40247 Tag# : TB526916

Check-in: Mon Mar 9, 2026 | 3:41 PM
Ready for Pickup: Wed Mar 11, 2026 | 9:08 AM
Promise Time: Sat Mar 14, 2026 | 6:00 PM

Customer linkautomotive - 2174 PD71552007091 Customer 1235491 +1 - (715) 466 - 2222	Billing-Customer Same as Customer	Vehicle 2026 FOREST RIVER TRACER 5ZT2TRNB8TB526916	Service Advisor KEVIN GOODIEL goodielk
---	---	--	---

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
\$132.00	\$19.20	\$0.00	\$0.00

F. MISCELLANEOUS	DEALER STATES THE AWNING DOES NOT ROLL IN PROPERLY DUE TO UNEVEN ROLL OF FABRIC. BACK SIDE IS WRINKLED. FRONT SIDE HANGS AWAY FROM UNIT APPROXIAMATLY 4"	Warranty Pay	\$0.00
------------------	--	--------------	--------

Tags: Add-on

Job added by KEVIN GOODIEL on Mon Mar 9, 2026 | 3:45 PM

1. Awning fabric was not set properly, causing it to roll up crooked, leading to extreme stretching and wrinkles in fabric. Recommend new awning.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$24.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.97	1	1	\$0.00	\$24.00

1. tried adjusting could not get wrinkles out due to stretching

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
\$0.00	\$24.00	\$0.00	\$0.00





1025 WI-77 Minong WI US 54859 www.linkrvidirect.com

Invoice
\$379.50

RO# : 40247 Tag# : TB526916

Check-in: Mon Mar 9, 2026 | 3:41 PM
Ready for Pickup: Wed Mar 11, 2026 | 9:08 AM
Promise Time: Sat Mar 14, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 FOREST RIVER
TRACER
5ZT2TRNB8TB526916

Service Advisor
KEVIN GOODIEL
goodielk

	Category	Sale	Cost
	Labor	\$379.50	\$79.20
	Parts	\$0.00	\$0.00
	Sublet	\$0.00	\$0.00
	Sublet Labor	\$0.00	\$0.00
	Sublet Parts	\$0.00	\$0.00
	Fees	\$0.00	\$0.00
	Discounts	\$0.00	-
	Tax	\$0.00	-
	Deductible	\$0.00	-
	Insurance/Warranty	\$0.00	-
	Invoice Total	\$379.50	\$79.20

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
F	MISC	Tue Mar 10, 2026	2:25 PM	2:33 PM	0.14 hrs	W	matthewl	1 hrs
Tag: Regular Hour			Reason: -					
A	MISC	Tue Mar 10, 2026	2:33 PM	2:42 PM	0.14 hrs	W	matthewl	0 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Tue Mar 10, 2026	2:42 PM	3:00 PM	0.31 hrs	W	matthewl	0.4 hrs
Tag: Regular Hour			Reason: -					
C	MISC	Tue Mar 10, 2026	3:00 PM	3:03 PM	0.04 hrs	W	matthewl	0.5 hrs
Tag: Regular Hour			Reason: -					
C	MISC	Tue Mar 10, 2026	3:03 PM	3:03 PM	0 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$379.50

RO# : 40247 Tag# : TB526916

Check-in: Mon Mar 9, 2026 | 3:41 PM
Ready for Pickup: Wed Mar 11, 2026 | 9:08 AM
Promise Time: Sat Mar 14, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 FOREST RIVER
TRACER
5ZT2TRNB8TB526916

Service Advisor
KEVIN GOODIEL
goodielk

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
C	MISC	Tue Mar 10, 2026	3:03 PM	3:04 PM	0.01 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
D	MISC	Tue Mar 10, 2026	3:04 PM	3:40 PM	0.59 hrs	W	matthewl	0.6 hrs
Tag: Regular Hour			Reason: -					
E	MISC	Tue Mar 10, 2026	3:40 PM	4:16 PM	0.61 hrs	W	matthewl	0.8 hrs
Tag: Regular Hour			Reason: -					
F	MISC	Tue Mar 10, 2026	4:17 PM	4:31 PM	0.24 hrs	W	matthewl	-
Tag: Regular Hour			Reason: Employee shift is ended					
F	MISC	Wed Mar 11, 2026	8:04 AM	8:39 AM	0.59 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					

Accounting Info - Warranty

GL Account #	Control #	Franchise	Amount
11400	40247	LINK RV	\$379.50
57200	40247	LINK RV	-\$379.50
67200	40247	LINK RV	\$79.20
14400	matthewl	LINK RV	-\$79.20

