



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$950.45

RO# : 40250 Tag# : TB941913

Check-in: Tue Mar 10, 2026 | 9:58 AM
Ready for Pickup: Wed Apr 1, 2026 | 3:46 PM
Promise Time: Sun Mar 15, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222
NO@GMAIL.COM
1025 WI-77
Minong, WI 54859

Pickup-Customer
Same as Customer

Billing-Customer
Same as Customer

Vehicle
2026 FOREST RIVER
AVENGER
5ZT2AVPB1TB941913
1 Mi In / 1 Mi Out
Stock #: FR26-20

Service Advisor
KEVIN GOODIEL
goodielk

A.	MISCELLANEOUS	DEALER STATES FABRIC ABOVE ODS FRONT TIRE IS RIPPED.	Warranty Pay	\$17.88
----	---------------	--	--------------	---------

Job added by KEVIN GOODIEL on Tue Mar 10, 2026 | 9:58 AM

1. Debris from tire

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$16.50

Labor Cost: \$12.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.48	0.5	0.5	\$16.50	\$12.00

1. Holes in fabric above tire. Recommend new fabric

2. Patched hole.

Parts

Parts Total Sale Amount \$1.38

Parts Total Cost Amount \$1.06

Name	Quantity	Unit Price	Sale Price	Cost Price
F100697246 - WOVEN UNDERBELLY	2	\$0.69	\$1.38	\$1.06

Total Labor Sale
\$16.50

Total Labor Cost
\$12.00

Total Parts Sale
\$1.38

Total Parts Cost
\$1.06

B.	MISCELLANEOUS	DEALER STATES THE ROOF NEEDS TO BE SEALED IN SPOTS	Warranty Pay	\$49.50
----	---------------	--	--------------	---------

Job added by KEVIN GOODIEL on Tue Mar 10, 2026 | 9:58 AM

1. Missed sealant





1025 WI-77 Minong WI US 54859 www.linkrvidirect.com

Invoice
\$950.45

RO# : 40250 Tag# : TB941913

Check-in: Tue Mar 10, 2026 | 9:58 AM
Ready for Pickup: Wed Apr 1, 2026 | 3:46 PM
Promise Time: Sun Mar 15, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 FOREST RIVER
AVENGER
5ZT2AVPB1TB941913

Service Advisor
KEVIN GOODIEL
goodielk

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$49.50

Labor Cost: \$7.20

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.23	0.3	0.3	\$49.50	\$7.20

1. Applied white quad around both extrusions on rear.

Total Labor Sale
\$49.50

Total Labor Cost
\$7.20

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

C. MISCELLANEOUS	DEALER STATES BLIND ABOVE STOVE IS MISSING PLASTIC WAND.	Warranty Pay	\$0.33
-------------------------	---	---------------------	---------------

Job added by KEVIN GOODIEL on Tue Mar 10, 2026 | 9:58 AM

1. Missing stick to turn the blinds. Recommend ordering stick.
2. Received wand. Installed wand.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.14	0	0	\$0.00	\$0.00

1. Took photo of missing stick

Parts

Parts Total Sale Amount \$0.33

Parts Total Cost Amount \$0.25





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$950.45

RO# : 40250 Tag# : TB941913

Check-in: Tue Mar 10, 2026 | 9:58 AM
Ready for Pickup: Wed Apr 1, 2026 | 3:46 PM
Promise Time: Sun Mar 15, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD71552007091
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 FOREST RIVER
AVENGER
5ZT2AVPB1TB941913

Service Advisor
KEVIN GOODIEL
goodielk

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Name	Quantity	Unit Price	Sale Price	Cost Price
30I42148A - WAND , ALUMINUM BLINDS , 12", (MFG# WAND), 9475	1	\$0.33	\$0.33	\$0.25

Total Labor Sale
\$0.00

Total Labor Cost
\$0.00

Total Parts Sale
\$0.33

Total Parts Cost
\$0.25

D. MISCELLANEOUS	DEALER STATES BLIND IN SLIDEOUT, CLOSEST TO REAR DOES NOT STAY UP.	Warranty Pay	\$1.65
------------------	--	--------------	--------

Job added by KEVIN GOODIEL on Tue Mar 10, 2026 | 9:58 AM

1. Loose string.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$1.65

Labor Cost: \$9.60

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.32	0.4	0.4	\$1.65	\$9.60

1. Unscrewed string. Moved knot up. Tested. Clipped excess string.

Total Labor Sale
\$1.65

Total Labor Cost
\$9.60

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

E. MISCELLANEOUS	DEALER STATES DECORATIVE FASCIAS TRIM ON SLIDEOUT IS PEELING.	Warranty Pay	\$756.75
------------------	---	--------------	----------

Job added by KEVIN GOODIEL on Tue Mar 10, 2026 | 9:58 AM





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$950.45

RO# : 40250 Tag# : TB941913

Check-in: Tue Mar 10, 2026 | 9:58 AM
Ready for Pickup: Wed Apr 1, 2026 | 3:46 PM
Promise Time: Sun Mar 15, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 FOREST RIVER
AVENGER
5ZT2AVPB1TB941913

Service Advisor
KEVIN GOODIEL
goodielk

1. Horizontal top fascia trim has nick and peeling laminent. "Weather protectant fascia board wrap" for lack of a proper term is protruding from the top of trim. Recommend new fascia trim and cut and hide fascia wrap.
2. Opened and inspected trim piece. Removed old trim, removed staples and scraped glue off, Taped frayed weather barrier to fascia, cut trim piece to size, fastened new trim in place.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$165.00

Labor Cost: \$24.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.76	1	1	\$165.00	\$24.00

1. Opened and inspected trim piece. Removed old trim, removed staples and scraped glue off, Taped frayed weather barrier to fascia, cut trim piece to size, fastened new trim in place.

Parts

Parts Total Sale Amount \$22.54

Parts Total Cost Amount \$17.34

Name	Quantity	Unit Price	Sale Price	Cost Price
F100766940 - SLIDEOUT FASCIA USERPART	1	\$22.54	\$22.54	\$17.34

Fees \$569.21

Code	Description	Sale Amount	Cost Amount
FF	Freight Fee	\$569.21	\$0.00

Total Labor Sale
\$165.00

Total Labor Cost
\$24.00

Total Parts Sale
\$22.54

Total Parts Cost
\$17.34

F. MISCELLANEOUS	DEALER STATES SHOWER DOESN'T WORK ON HOT OR COLD, POSSIBLY CLOGGED.	Warranty Pay	\$16.50
-------------------------	--	---------------------	----------------

Job added by KEVIN GOODIEL on Tue Mar 10, 2026 | 9:58 AM

1. Construction debris





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$950.45

RO# : 40250 Tag# : TB941913

Check-in: Tue Mar 10, 2026 | 9:58 AM
Ready for Pickup: Wed Apr 1, 2026 | 3:46 PM
Promise Time: Sun Mar 15, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 FOREST RIVER
AVENGER
5ZT2AVPB1TB941913

Service Advisor
KEVIN GOODIEL
goodielk

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$16.50

Labor Cost: \$9.60

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.22	0.4	0.4	\$16.50	\$9.60

1. Removed shower head. Hit with pressurized hose from both ends. Reattached. Works as it should. There was a noticeable amount of debris in waste tank that was apparent after draining.

Total Labor Sale
\$16.50

Total Labor Cost
\$9.60

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

G. MISCELLANEOUS	DEALER STATES THE PLASTIC COVER FOR 30 AMP PLUG IN IS BROKEN	Warranty Pay	\$107.84
------------------	--	--------------	----------

Tags: [Add-on](#)

Job added by KEVIN GOODIEL on Tue Mar 10, 2026 | 1:30 PM

1. ????

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$82.50

Labor Cost: \$12.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.47	0.5	0.5	\$82.50	\$12.00

1. Opened 30 amp plug to provide power. Cover came off. Receptacle is broken at hinge. Recommend new receptacle.
2. Replaced plug. Works as it should.





1025 WI-77 Minong WI US 54859 www.linkrvidirect.com

Invoice
\$950.45

RO# : 40250 Tag# : TB941913

Check-in: Tue Mar 10, 2026 | 9:58 AM
Ready for Pickup: Wed Apr 1, 2026 | 3:46 PM
Promise Time: Sun Mar 15, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 FOREST RIVER
AVENGER
5ZT2AVPB1TB941913

Service Advisor
KEVIN GOODIEL
goodielk

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$82.50

Labor Cost: \$12.00

Parts

Parts Total Sale Amount \$25.34

Parts Total Cost Amount \$19.49

Name	Quantity	Unit Price	Sale Price	Cost Price
F100371675 - INLET, 30A, FOR POWER CORDS, 803EZ-A-SQBK	1	\$25.34	\$25.34	\$19.49

Total Labor Sale
\$82.50

Total Labor Cost
\$12.00

Total Parts Sale
\$25.34

Total Parts Cost
\$19.49

Category	Sale	Cost
Labor	\$331.65	\$74.40
Parts	\$49.59	\$38.14
Sublet	\$0.00	\$0.00
Sublet Labor	\$0.00	\$0.00
Sublet Parts	\$0.00	\$0.00
Fees	\$569.21	\$0.00
Discounts	\$0.00	-
Tax	\$0.00	-
Deductible	\$0.00	-
Insurance/Warranty	\$0.00	-
Invoice Total	\$950.45	\$112.54





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$950.45

RO# : 40250 Tag# : TB941913

Check-in: Tue Mar 10, 2026 | 9:58 AM
Ready for Pickup: Wed Apr 1, 2026 | 3:46 PM
Promise Time: Sun Mar 15, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD71552007091
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 FOREST RIVER
AVENGER
5ZT2AVPB1TB941913

Service Advisor
KEVIN GOODIEL
goodielk

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
A	MISC	Tue Mar 10, 2026	1:04 PM	1:12 PM	0.13 hrs	W	matthewl	0.5 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Tue Mar 10, 2026	1:12 PM	1:26 PM	0.23 hrs	W	matthewl	0.3 hrs
Tag: Regular Hour			Reason: -					
C	MISC	Tue Mar 10, 2026	1:26 PM	1:27 PM	0.01 hrs	W	matthewl	0 hrs
Tag: Regular Hour			Reason: -					
D	MISC	Tue Mar 10, 2026	1:27 PM	1:31 PM	0.07 hrs	W	matthewl	0.4 hrs
Tag: Regular Hour			Reason: -					
C	MISC	Tue Mar 10, 2026	1:31 PM	1:33 PM	0.03 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
D	MISC	Tue Mar 10, 2026	1:33 PM	1:48 PM	0.25 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
E	MISC	Tue Mar 10, 2026	1:48 PM	2:02 PM	0.24 hrs	W	matthewl	1 hrs
Tag: Regular Hour			Reason: -					
F	MISC	Tue Mar 10, 2026	2:02 PM	2:15 PM	0.22 hrs	W	matthewl	0.4 hrs
Tag: Regular Hour			Reason: -					
G	MISC	Tue Mar 10, 2026	2:16 PM	2:25 PM	0.15 hrs	W	matthewl	0.5 hrs
Tag: Regular Hour			Reason: -					
A	MISC	Tue Mar 31, 2026	10:18 AM	10:32 AM	0.23 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$950.45

RO# : 40250 Tag# : TB941913

Check-in: Tue Mar 10, 2026 | 9:58 AM
Ready for Pickup: Wed Apr 1, 2026 | 3:46 PM
Promise Time: Sun Mar 15, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 FOREST RIVER
AVENGER
5ZT2AVPB1TB941913

Service Advisor
KEVIN GOODIEL
goodielk

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
G	MISC	Tue Mar 31, 2026	10:33 AM	10:51 AM	0.32 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
C	MISC	Tue Mar 31, 2026	10:52 AM	10:58 AM	0.10 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
E	MISC	Tue Mar 31, 2026	10:58 AM	11:29 AM	0.52 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
A	MISC	Tue Mar 31, 2026	11:29 AM	11:37 AM	0.12 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					

Accounting Info - Warranty

GL Account #	Control #	Franchise	Amount
11400	40250	LINK RV	\$950.45
57200	40250	LINK RV	-\$331.65
67200	40250	LINK RV	\$74.40
14400	matthewl	LINK RV	-\$74.40
54200	40250	LINK RV	-\$49.59
64000	40250	LINK RV	\$38.14
14000	40250	LINK RV	-\$38.14
76710	40250	LINK RV	-\$569.21

