



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$330.56

RO# : 40294 Tag# : T1J10054

Check-in: Fri Mar 27, 2026 | 12:09 PM

Ready for Pickup: Wed Apr 1, 2026 | 10:41 AM

Promise Time: Wed Apr 1, 2026 | 6:00 PM

Customer
BARBARA JEANNE GROVE
1244465
+1 - (612) 390 - 6430
ferlinfrye@gmail.com
15911 Edgewater Road
Northeast
Pine City, MN 55063

Pickup-Customer
Same as Customer

Billing-Customer
Same as Customer

Vehicle
2026 JAYCO JAY FEATHER 21MML
1UJBB0BL0T1J10054
2 Mi In
Sold Date: 12/17/2025
Stock #: 26-03

Service Advisor
KEVIN GOODIEL
goodielk

A. MISCELLANEOUS	CUSTOMER STATES THE WATER HEATER DONT WORK THE CONTROLLER WAS THROWING A CODE AND BLOWER WOULD NEVER ENGAGE.	Customer Pay	\$297.00
-------------------------	---	---------------------	-----------------

Job added by KEVIN GOODIEL on Fri Mar 27, 2026 | 12:09 PM

1. ST90 suburban water heater has an E5 code checked the limit switch and its not tripped has power on both sides of it also checked power to the exhaust fan motor power there but when you ask for hot water that fan doesn't move at all causing the water heater not to ignite will need a new exhaust motor ordered and installed if available. I did check to make sure the tube from exhaust was clear of debris and had no water in tube

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$297.00

Labor Cost: \$55.80

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
kastenm	-	1.79	1.8	1.8	\$297.00	\$55.80

1. ST90 suburban water heater has an E5 code checked the limit switch and its not tripped has power on both sides of it also checked power to the exhaust fan motor power there but when you ask for hot water that fan doesn't move at all causing the water heater not to ignite will need a new exhaust motor ordered and installed if available. I did check to make sure the tube from exhaust was clear of debris and had no water in tube requesting 1 additional hour.

Total Labor Sale
\$297.00

Total Labor Cost
\$55.80

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

Additional Fees	Sale Amount	Cost Amount
SSC - Shop Supply Charges	\$16.33	\$0.00





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$330.56

RO# : 40294 Tag# : T1J10054

Check-in: Fri Mar 27, 2026 | 12:09 PM

Ready for Pickup: Wed Apr 1, 2026 | 10:41 AM

Promise Time: Wed Apr 1, 2026 | 6:00 PM

Customer
BARBARA JEANNE
GROVE
1244465
+1 - (612) 390 - 6430

Billing-Customer
Same as Customer

Vehicle
2026 JAYCO JAY
FEATHER 21MML
1UJBB0BL0T1J10054

Service Advisor
KEVIN GOODIEL
goodielk

	Category	Sale	Cost
	Labor	\$297.00	\$55.80
	Parts	\$0.00	\$0.00
	Sublet	\$0.00	\$0.00
	Sublet Labor	\$0.00	\$0.00
	Sublet Parts	\$0.00	\$0.00
	Fees	\$16.33	\$0.00
	Discounts	\$0.00	-
	Tax	\$17.23	-
	Deductible	\$0.00	-
	Insurance/Warranty	\$0.00	-
	Invoice Total	\$330.56	\$55.80

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
A	MISC	Tue Mar 31, 2026	8:20 AM	10:07 AM	1.79 hrs	CP	kastenm	1.8 hrs

Tag: Regular Hour

Reason: -

Accounting Info - Customer Pay

GL Account #	Control #	Franchise	Amount
57000	40294	LINK RV	-\$297.00
67000	40294	LINK RV	\$55.80
14400	kastenm	LINK RV	-\$55.80
77700	40294	LINK RV	-\$16.33
21500	SALES TAX	LINK RV	-\$15.66
21510	COUNTY TAX	LINK RV	-\$1.57

