



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$181.50

RO# : 40235 Tag# : TB526933

Check-in: Thu Mar 5, 2026 | 8:23 AM
Ready for Pickup: Thu Mar 5, 2026 | 2:12 PM
Promise Time: Tue Mar 10, 2026 | 7:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222
NO@GMAIL.COM
1025 WI-77
Minong, WI 54859

Pickup-Customer
Same as Customer

Billing-Customer
Same as Customer

Vehicle
2026 FOREST RIVER
TRACER
5ZT2TRPB1TB526933
1 Mi In / 1 Mi Out
Stock #: FR26-23

Service Advisor
KEVIN GOODIEL
goodielk

A. MISCELLANEOUS	DEALER STATES THE CONTROL PAD FOR THE WATER HEATER IS FROZEN. BLINKS -5 AND WILL NOT TAKE ANY COMMANDS. WILL NOT GO UP, DOWN CHANGE FROM F TO C.	Warranty Pay	\$82.50
-------------------------	---	---------------------	----------------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 8:23 AM

1. Water heater thermostat works like it should after camper was unplugged and moved to a different bay. Request .50 for testing

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$82.50

Labor Cost: \$9.50

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
boiem	-	0.46	0.5	0.5	\$82.50	\$9.50

1. Water heater thermostat works like it should after camper was unplugged and moved to a different bay. Just needed a power reboot. Tested water heater and it got up to temp like it should, re-winterized camper after testing.

Total Labor Sale
\$82.50

Total Labor Cost
\$9.50

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

B. MISCELLANEOUS	DEALER STATES THE ROOF NEEDS TO BE SEALED IN SOME SPOTS TOOK PICS	Warranty Pay	\$49.50
-------------------------	--	---------------------	----------------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 8:23 AM

1. Front corner extrusion was missing some sealant, request .20 for reseal





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$181.50

RO# : 40235 Tag# : TB526933

Check-in: Thu Mar 5, 2026 | 8:23 AM
Ready for Pickup: Thu Mar 5, 2026 | 2:12 PM
Promise Time: Tue Mar 10, 2026 | 7:00 PM

Customer
linkautomotive - 2174
PD71552007091
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 FOREST RIVER
TRACER
5ZT2TRPB1TB526933

Service Advisor
KEVIN GOODIEL
goodielk

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$49.50

Labor Cost: \$5.70

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
boiem	-	0.2	0.3	0.3	\$49.50	\$5.70

1. resealed front corner of camper

Total Labor Sale
\$49.50

Total Labor Cost
\$5.70

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

C. MISCELLANEOUS	DEALER STATES THE EXTERIOR WOULD TINTED WINDOW HAS WHAT APPEARS TO BE SEALANT SMEARS ON IT. ATTEMPTED TO REMOVE WITH GLASS CLEANER	Warranty Pay	\$49.50
------------------	--	--------------	---------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 8:23 AM

1. Sealant dripped on window by main door, requiring .20 to clean off window

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$49.50

Labor Cost: \$5.70

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
boiem	-	0.13	0.3	0.3	\$49.50	\$5.70

1. cleaned window with adhesive remover to get the sealant off then cleaned with glass cleaner

Total Labor Sale
\$49.50

Total Labor Cost
\$5.70

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$181.50

RO# : 40235 Tag# : TB526933

Check-in: Thu Mar 5, 2026 | 8:23 AM
Ready for Pickup: Thu Mar 5, 2026 | 2:12 PM
Promise Time: Tue Mar 10, 2026 | 7:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 FOREST RIVER
TRACER
5ZT2TRPB1TB526933

Service Advisor
KEVIN GOODIEL
goodielk

	Category	Sale	Cost
	Labor	\$181.50	\$20.90
	Parts	\$0.00	\$0.00
	Sublet	\$0.00	\$0.00
	Sublet Labor	\$0.00	\$0.00
	Sublet Parts	\$0.00	\$0.00
	Fees	\$0.00	\$0.00
	Discounts	\$0.00	-
	Tax	\$0.00	-
	Deductible	\$0.00	-
	Insurance/Warranty	\$0.00	-
	Invoice Total	\$181.50	\$20.90

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
A	MISC	Thu Mar 5, 2026	8:55 AM	9:22 AM	0.46 hrs	W	boiem	0.5 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Thu Mar 5, 2026	9:44 AM	9:56 AM	0.20 hrs	W	boiem	0.3 hrs
Tag: Regular Hour			Reason: -					
C	MISC	Thu Mar 5, 2026	10:29 AM	10:37 AM	0.13 hrs	W	boiem	0.3 hrs
Tag: Regular Hour			Reason: -					

Accounting Info - Warranty

GL Account #	Control #	Franchise	Amount
11400	40235	LINK RV	\$181.50
57200	40235	LINK RV	-\$181.50





1025 WI-77 Minong WI US 54859 www.linkrvidirect.com

Invoice
\$181.50

RO# : 40235 Tag# : TB526933

Check-in: Thu Mar 5, 2026 | 8:23 AM
Ready for Pickup: Thu Mar 5, 2026 | 2:12 PM
Promise Time: Tue Mar 10, 2026 | 7:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 FOREST RIVER
TRACER
5ZT2TRPB1TB526933

Service Advisor
KEVIN GOODIEL
goodielk

Accounting Info - Warranty

GL Account #	Control #	Franchise	Amount
67200	40235	LINK RV	\$20.90
14400	boiem	LINK RV	-\$20.90

