



12024 Central Ave SE ★ Albuquerque NM 87123  
 www.MYERSRV.com  
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72145  
 Promised Date:  
 15 AUG 25



WO #: 72145  
 Customer Name: 1000 - MYERS "RV"  
 CENTER, INC.

Completed Date:  
 Invoice#:  
 Author: BRIAN  
 Stock Desc: 9579 2026 DUTCH STAR  
 4081  
 Serial#: 611863  
 Chassis#: WR9220  
 Miles/Hrs:  
 Tag#:  
 Purchased Date:  
 Warranty Date:

Date In: 06 AUG 25  
 Time In:

**Job #1 - Internal**  
 CHECK IN NEW UNIT

<b>Labor</b>				
Job #	Description			Total
1	DIAGNOSIS			N/C
<b>Other Services</b>				
Code	Description	Qty	Price	Total
SS-I	SHOP SUPPLIES - INTERNAL	1.00	N/C	N/C
<b>Subtotal for Job #1:</b>				<b>0.00</b>

**Job #2 - Internal**  
 COMPLAINT: PRE-PDI

CAUSE: Inspection  
 CORRECTION: Complete

<b>Labor</b>				
Job #	Description			Total
2	PRE-PDI			N/C
<b>Parts</b>				
Part #	Description	Qty	Price	Total
16058	SLICK SLICK STUFF - LUBE SPRAY	1.00	N/C	N/C
<b>Subtotal for Job #2:</b>				<b>0.00</b>

**Job #3 - Warranty**  
 COMPLAINT: Front emblem is peeling off

CAUSE: Double sided tape used to adhere the emblem was full of dust and debris not sticking to the front cap

CORRECTION: Order a new emblem with the adhesive on it. Will have to clean the front cap and apply new emblem.  
 1.00HRS

Customer #: 1000  
 MYERS "RV" CENTER,  
 INC.,





Labor			Total
Job #	Description		N/C
3	FRONT EMBLEM		N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
<b>Subtotal for Job #3:</b>				<b>0.00</b>

**Job #4 - Warranty**

COMPLAINT: Missing Oasis reservoir cap

CAUSE: Missing the cap for the Oasis reservoir

CORRECTION: Order and install

Used a plastic bag and a rubber band for now to prevent dirt from getting in.

.20HRS

Labor			Total
Job #	Description		N/C
4	OASIS CAP		N/C

**Subtotal for Job #4: 0.00**

**Job #5 - Warranty**

COMPLAINT: No video detected right turn camera

CAUSE: LOOSE CONNECTION AT MONITOR

CORRECTION: RESECURED AND SECURED WIRING

.25HRS

Labor			Total
Job #	Description		N/C
5	RIGHT TURN CAMERA		N/C

**Subtotal for Job #5: 0.00**

**Job #6 - Warranty**

COMPLAINT: Battery not charging inverter INOP

CAUSE: Setting were wrong on the inverter panel

CORRECTION: Spoke with Jason at Newmar case 1024896.

1.20HRS

Went through the settings in the panel and inverter, got it working as designed per Jason.

Labor			Total
Job #	Description		N/C
6	INVERTER		N/C

**Subtotal for Job #6: 0.00**

**Job #7 - Warranty**

COMPLAINT: Entry door awning INOP

CAUSE: There was no power to the controller for the entry door awning

CORRECTION: I called and talked to several people trying to figure out this awning, including Newmar KIBE Gerrard. Case number 102-6073. While Ive been on hold with everybody doing some poking around I found that there was no power run to the controller or no ground. I had to make a small jumper wire to get ground and I was able to plug in the spade connector for Power. I also had to call Gerard to get them to.



Through re-pairing process. Everything is now working as designed. Job completed.  
3.50HRS

<b>Labor</b>		
Job #	Description	Total
7	ENTRY DOOR AWNING	N/C
<b>Subtotal for Job #7:</b>		<b>0.00</b>

**Job #8 - Warranty**

COMPLAINT: Sliding bedroom door not secured

CAUSE: The bracket that ties the two doors connected wasnt attached to both doors

CORRECTION: Loosened the bracket, attached tk the other door, tested function, and adjusted the tilt of the door slightly. Job completed.

.30hrs

<b>Labor</b>		
Job #	Description	Total
8	BEDROOM DOOR	N/C
<b>Subtotal for Job #8:</b>		<b>0.00</b>

**Job #9 - Warranty**

COMPLAINT: Door and cabinet inserts are shrinking throughout unit

CAUSE: Dry climate, wood shrinks

CORRECTION: In the corners of all the cabinets is a darker outline of the panel. Use a stain pen to color fill the bare wood

order a stain pen and use to fill in all bare areas.

Also need to order the white paint for the cabinets for touchup.

2.00hrs

<b>Labor</b>		
Job #	Description	Total
9	CABINET INSERTS	N/C
<b>Subtotal for Job #9:</b>		<b>0.00</b>

**Job #10 - Warranty**

COMPLAINT: Cabinet door gaps are crooked

CAUSE: Several cabinet door gaps were not aligned properly

CORRECTION: Using the adjustments on the hinges, adjusted the door gaps. Job completed.

.20HRS

<b>Labor</b>		
Job #	Description	Total
10	CABINET DOORS	N/C
<b>Subtotal for Job #10:</b>		<b>0.00</b>

**Job #11 - Warranty**

COMPLAINT: Cutting boards unglued from stove cover

CAUSE: Silicone failed to adhere the cutting board to the countertop stove cover

CORRECTION: I had to scrape the silicone from the stove covers and the cutting boards clean with adhesive cleaner apply silicone adhesive for plastics and use a battery to weigh them down for the weekend. Job completed.

.80HRS

W/O: 72145  
Promised Date: 15 AUG 25



Customer #: 1000  
MYERS "RV" CENTER,  
INC.,





<b>Labor</b>				
Job #	Description			Total
11	CUTTING BOARDS			N/C
<b>Parts</b>				
Part #	Description	Qty	Price	Total
18012	TRANSLUCENT GLAZING SILICONE 10 OZ	1.00	N/C	N/C
<b>Subtotal for Job #11:</b>				<b>0.00</b>

**Job #WIN-DLX - Internal**  
 COMPLAINT: WINTERIZE INCLUDE W/D, ICEMAKER

CAUSE: Winter is coming.

CORRECTION: Done.

<b>Labor</b>				
Job #	Description			Total
WIN-DLX	WINTERIZE RV - DELUXE CLASS A			N/C
<b>Parts</b>				
Part #	Description	Qty	Price	Total
21622	ANTIFREEZE	8.00	N/C	N/C
<b>Other Services</b>				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
<b>Subtotal for Job #WIN-DLX:</b>				<b>0.00</b>

Parts Total: 0.00  
 Labour Total: 0.00  
 Sublet Total: 0.00  
 Extras Total: 0.00  
**WORK ORDER TOTAL: 0.00**

NOTICE:  
 DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

\*\*MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND\*\*

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 06 Jan 2026

Customer Signature : \_\_\_\_\_

