



12024 Central Ave SE ★ Albuquerque NM 87123  
 www.MYERSRV.com  
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73070  
 Promised Date:  
 23 APR 26



WO #: 73070 (Appointment Date: 21 MAR 2026 - Time: 10:15am)  
 Customer Name: 60239 - RAMOS, RAMON  
 Completed Date:  
 Invoice#:  
 Author: ADVISOR  
 Stock Desc: 9554 2026 AVENGER 26DBS  
 Serial#: 5ZT2AVRB3TB940730  
 Chassis#: 5ZT2AVRB3TB940730  
 Miles/Hrs:  
 Tag#: 7132  
 Purchased Date: 03 JUL 25  
 Warranty Date: 03 JUL 25  
 Date In: 21 MAR 26  
 Time In:

**Job #1 - Warranty**

CUSTOMER STATES REPAIR CARPET ON SLIDE (REFERENCE: 71948)

**Labor**

Job #	Description	Total
1	MISC LABOUR CODE (WARRANTY)	N/C

**Other Services**

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

**Subtotal for Job #1: 0.00**

**Job #2 - Warranty**

COMPLAINT: CUSTOMER STATES WATER PUMP WILL WORK THEN STOP WORKING - LIKE IT'S OVERHEATING. WHEN THEY FILLED THE FRESH WATER TANK AND TURNED PUMP ON IT CAME OUT THRU THE CITY WATER FILL INLET

CAUSE: Customer complaint water not working correctly

CORRECTION: Filled fresh tank to full  
 Checked the city water connection found the washer with screen cone facing in which was pressing the back flow preventer. Turned the washer screen to the proper position  
 Ran water through all facets for over 5 minutes straight. Water pump never shut down or stopped working, no water was coming out of the city water connection. Water pump is working as it should no water coming out of the city connector.  
 Work complete Requesting .75

**Labor**

Job #	Description	Total
2	WATER PUMP DIAGNOSE	N/C

**Subtotal for Job #2: 0.00**

**Job #3 - Warranty**

COMPLAINT: JOB ADDED: CUSTOMER STATES THERE IS A GAUGE ON THE BATHROOM SHELF UNDER THE MIRROR

CAUSE: Large gouge in cabinet face at the shelf

CORRECTION: Need to replace the cabinet face

Customer #: 60239  
 RAMOS, RAMON



19 x 30  
Request 1 hour

**Labor**

Job #	Description	Total
3	CABINET EDGE	N/C
<b>Subtotal for Job #3:</b>		<b>0.00</b>

**Job #4 - Warranty**

COMPLAINT: JOB ADDED: CUSTOMER STATES SCREWS ON THE BEDROOM WINDOW VALANCE - WINDOW TO THE LEFT WHEN STANDING AT FOOT OF BED - HAVE PULLED OUT

CAUSE: Screws pulled out

CORRECTION: Removed loose screws replaced them with larger screws. Now secure  
Work complete. Requesting .25

**Labor**

Job #	Description	Total
4	WINDOW LANACE BRACKET	N/C
<b>Subtotal for Job #4:</b>		<b>0.00</b>

**Job #5 - Warranty**

COMPLAINT: JOB ADDED: CUSTOMER STATES THE SCREEN FRAME - WHEN STANDING AT THE FOOT OF BED TO THE LEFT CAME OFF

CAUSE: Screen came off

CORRECTION: Clipped screen back in place  
Work complete Requesting .10

**Labor**

Job #	Description	Total
5	WINDOW SCREEN INSTALL	N/C
<b>Subtotal for Job #5:</b>		<b>0.00</b>

**Job #6 - Warranty**

COMPLAINT: JOB ADDED: CUSTOMER STATES INSIDE THE FREEZER THE SCREWS ON BOTH SIDES ARE OXIDIZED

CAUSE: Screws have rust were not caped

CORRECTION: Put the plastic caps over the screws  
Nothing can be done to prevent rust from forming on the screws it is a moist environment placing the caps over the screws keeps the screws from being visible.  
Work completed. Requesting .10

**Labor**

Job #	Description	Total
6	REFRIGERATOR SCREWS	N/C
<b>Subtotal for Job #6:</b>		<b>0.00</b>

**Job #7 - Warranty**

COMPLAINT: JOB ADDED: CUSTOMER STATES AT THE BOTTOM BUNK LEFT WALL THER SCREW HOLE AND THE TRIM IS COMING OFF

CAUSE: Large screw hole in the wall

CORRECTION: Recommend replacement of panel screw hole not repairable. Will need full sheet of panel. Will need 3 batten trims. Will require the removal of both bunk beds, removal of he damaged panel. Cut the new sheet of panel to fit and install, reinstall both bunk beds.

W/O: 73070  
Promised Date: 03 APR 26



Customer #: 60239  
RAMOS, RAMON



Requesting 8 hours

**Labor**

Job #	Description	Total
7	PANEL /TRIM - INTERIOR	N/C

**Subtotal for Job #7: 0.00**

**Job #8 - Warranty**

COMPLAINT: JOB ADDED: CUSTOMER STATES THE BOTTOM BUNK AT FOOT OF BED THE CHARGER IS NOT WORKING

CAUSE: USB charging port plug not working

CORRECTION: Tested the port no power. Removed port from the wall tested the power at the wire nuts did have correct voltage. Need to replace the plug.

Needs to be ordered - Requesting .25

**Labor**

Job #	Description	Total
8	CHARGING PORT	N/C

**Subtotal for Job #8: 0.00**

**Job #9 - Warranty**

COMPLAINT: JOB ADDED: CUSTOMER STATES KITCHEN BLIND BY THE DINETTE TABLE WILL NOT STAY UP

CAUSE: Loose adjustment cords

CORRECTION: Adjusted the tension on the adjustment cords. Blind will now stay up.

Completed Requesting .10

**Labor**

Job #	Description	Total
9	BLIND ADJUST	N/C

**Subtotal for Job #9: 0.00**

**Job #10 - Warranty**

COMPLAINT: JOB ADDED: CUSTOMER STATES PANTRY LATCH NOT LOCKING

CAUSE: Latch is broken

CORRECTION: Pantry door latch is broken keeping it from fully locking and is misaligned

Need to order new latch and align it properly.

Hold for parts

Request .5 time

**Labor**

Job #	Description	Total
10	CABINET LATCH ADJUST	N/C

**Subtotal for Job #10: 0.00**

**Job #11 - Warranty**

COMPLAINT: JOB ADDED: CUSTOMER STATES SINCE PANTRY LATCH NOT WORKING IT CAUSED DAMAGE TO THE SLIDE FACIA

CAUSE: Large gouge in top facia

CORRECTION: Received wrong facia, wrong color and wrong length

Need to reorder facia

5 1/2 inches wide 154 inches long

Requesting 1.0

W/O: 73070  
Promised Date: 03 APR 26



Customer #: 60239  
RAMOS, RAMON





<b>Labor</b>		
Job #	Description	Total
11	SLIDE OUT FASCIA	N/C
<b>Subtotal for Job #11:</b>		<b>0.00</b>

**Job #12 - Warranty**

COMPLAINT: JOB ADDED: CUSTOMER STATES THE TRIM AROUND THE TABLE BOOTH HAS COME OFF - THE TRIM IS ON THE TABLE

CAUSE: Plastic u shaped trim pulled off base of dinette bench

CORRECTION: Recommend replacement  
Trim was folded and creased will need to be replaced  
14 inches long 3/4 inch wide  
Requesting .15

<b>Labor</b>		
Job #	Description	Total
12	PANEL / TRIM	N/C
<b>Subtotal for Job #12:</b>		<b>0.00</b>

**Job #13 - Warranty**

COMPLAINT: JOB ADDED: CUSTOMER REQUEST CHECK FUSES UNDER FRIDGE - SAYS THE FUSES KEEP BLOWING SHUTTING OFF FRIDGE - THEY NEED TO KEEP REPLACING THEM

CAUSE: Customer complaint blowing fuses for refrigerator when turning refrigerator off

CORRECTION: Turned refrigerator on and off several times on shore power didn't blow a fuse  
Unplugged shore power turned refrigerator on and off while just on battery power several times didn't blow a fuse  
Could not replicate Requesting .15

<b>Labor</b>		
Job #	Description	Total
13	FUSES	N/C
<b>Subtotal for Job #13:</b>		<b>0.00</b>

**Job #14 - Warranty**

COMPLAINT: JOB ADDED: CUSTOMER STATES WHEN EXITING THE UNIT - DOOR FRAME ON LEFT SIDE IS MISSING THE BUTTON

CAUSE: Screw cap for trim above the entry door missing

CORRECTION: Need to order new cap see photos  
Requesting .10

<b>Labor</b>		
Job #	Description	Total
14	BUTTON / DOOR	N/C
<b>Subtotal for Job #14:</b>		<b>0.00</b>

**Job #15 - Warranty**

COMPLAINT: JOB ADDED: CUSTOMER STATES THE POCKET DOOR TO BEDROOM IS DAMAGED DUE TO THE BUTTON MISSING ON THE EXIT DOOR

CAUSE: Door damaged when it was not latched

CORRECTION: Recommend replacement of the barn door  
30 x 74  
Request 1 hour



Will have to remove the trim from in front of the door  
Will have to install all hardware on the new door  
And install the door

**Labor**

Job #	Description	Total
15	POCKET DOOR / BEDROOM	N/C

**Subtotal for Job #15: 0.00**

**Job #16 - Warranty**

COMPLAINT: JOB ADDED: CUSTOMER STATES THE FRONT PASS. LIGHT STRIP IS DAMAGED AND DOES NOT WORK

CAUSE: Light strip and rail damaged  
Light strip has a cut  
Rail is bent

CORRECTION: Recommend replacement of the light strip and rail.  
Over length 10 feet. Light strip fits inside rail like vinyl insert  
The fail is corner molding and is curved. Will have to remove the corner mold and light disconnect wiring  
Clean off all old sealant  
Prep new corner molding and install  
Install new light and connect wiring and test.  
Requesting 2 hours to replace

**Labor**

Job #	Description	Total
16	LIGHT STRIP	N/C

**Subtotal for Job #16: 0.00**

**Job #17 - Warranty**

COMPLAINT: JOB ADDED: CUSTOMER STATES THE FRONT LIGHT STRIP ON DRIVERS SIDE IS HANGING DOWN

CAUSE: Light strip slipped down in the track

CORRECTION: Pushed the light back in place  
Used a pair of Pilars and crimped the end to prevent the light from slipping down again  
Work complete Requesting .15

**Labor**

Job #	Description	Total
17	LIGHT STRIP	N/C

**Subtotal for Job #17: 0.00**

**Job #18 - Warranty**

COMPLAINT: CUSTOMER STATES PART ON ORDER FOR WINDOW ON PASS. SIDE TO THE LEFT OF THE ENTRY DOOR - REE KNEW ABOUT THIS

CAUSE: Screws all the bay through the frame

CORRECTION: Unscrewed the window blind  
Unscrewed the retainer ring inside the unit. Removed the window from the outside, Un-boxed the new window and cleaned all styrofoam off the window  
Set the new window in place. Attached the retainer ring from the inside.  
Straightened the blind from being screwed to the wall. Drilled the holes in the blind so that it would bend again  
Reattached the window blind to the wall  
Tested the window for operation  
Work complete. Requesting 1.5

W/O: 73070  
Promised Date: 03 APR 26



Customer #: 60239  
RAMOS, RAMON



<b>Labor</b>		
Job #	Description	Total
18	MISC LABOUR CODE (WARRANTY)	N/C
<b>Subtotal for Job #18:</b>		<b>0.00</b>

**Job #19 - Warranty**

COMPLAINT: JOB ADDED: THE CUSHIONS AT THE TABLE ARE COMING UNRAVELED

CAUSE: Fabric coming apart

CORRECTION: Recommend replacement both seat cushions

23 x 40 1/2

See photos

<b>Labor</b>		
Job #	Description	Total
19	DINETTE CUSHIONS	N/C
<b>Subtotal for Job #19:</b>		<b>0.00</b>

**Job #NOTE - External**

CUSTOMER STATES UNIT IS NOT WINTERIZED

**Subtotal for Job #NOTE: 0.00**

Parts Total: 0.00  
 Labour Total: 0.00  
 Sublet Total: 0.00  
 Extras Total: 0.00

**WORK ORDER TOTAL: 0.00**

NOTICE:  
 DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

\*\*MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND\*\*

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 08 Apr 2026

Customer Signature : \_\_\_\_\_

