



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 71872
 Promised Date:



WO #: 71872 (Appointment Date: 20 JUN 2025 - Time: 09:15am)
 Customer Name: 60168 - BUFF, AUSTIN Completed Date:
 Invoice#:
 Author: ADVISOR
 Stock Desc: 2025 CANYON STAR 3947
 Serial#: 163024
 Chassis#: 4UZACMFC7SCVV9661 Date In: 20 JUN 25
 Miles/Hrs: 9543 Time In:
 Tag#: 6745
 Purchased Date:
 Warranty Date:

Job #0 - Warranty

REFERENCE CLAIM: 71872

Subtotal for Job #0: 0.00

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES THE SLIDE IS NOT GETTING POWER.
 PROGRESSIVE INSURANCE
 JAKE HAMMER 1-239-980-1040

CAUSE: Spoke with Doug at Newmar. E2 code on controller with 13.7 vdc input.
 Bad controller

CORRECTION: Replace controller APN-0159
 1.50HRS

Labor

Job #	Description	Total
1	ELECTRICAL REPAIR	166.50

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00

Subtotal for Job #1: 166.50

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES THE AWNING ISN'T EXTENDING

CAUSE: Lockout relay stuck with ignition off or on

CORRECTION: Removed relay and cleaned. Reinstalled and verified proper lock out procedures. Tested for proper function. Completed
 1.20HRS

Labor

Job #	Description	Total
2	ELECTRICAL REPAIR	185.00

Customer #: 60168
 BUFF, AUSTIN



Subtotal for Job #2: 185.00

Job #3 - Warranty

COMPLAINT: CUSTOMER STATES FRESH WATER TANK INDICATOR IS NOT WORKING

CAUSE: Spoke with Chad at Newmar. Attempted recalibration. Cycled 12 volt power. No success. Constant 0% on fresh. Called Newmar again. Spoke with Troy. 3way call with Walt at Kib.

CORRECTION: Replace tank sensors and retest.
Had to fill and empty tank twice to perform reset.
2.00HRS

Labor

Job #	Description	Total
3	ELECTRICAL REPAIR	168.35

Subtotal for Job #3: 168.35

Job #4 - Warranty

COMPLAINT: CUSTOMER STATES VACCUM IS NOT GETTING POWER

CAUSE: No power out from vacuum motor. Power is present at vacuum on/off micro switch on one side. Micro switch at vacuum not consistently transferring power to vacuum. Bypassed switch and tested vacuum function.

CORRECTION: Replace vacuum micro switch. See pics
1.25HRS

Labor

Job #	Description	Total
4	ELECTRICAL REPAIR	92.50

Subtotal for Job #4: 92.50

Parts Total: 0.00
 Labour Total: 612.35
 Sublet Total: 0.00
 Extras Total: 0.00

WORK ORDER TOTAL: 612.35

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 03 Jan 2026

W/O: 71872
Promised Date: 30 JUL 25



Customer #: 60168
BUFF, AUSTIN

