



Warranty Claim Detail

R.O. Number **72946**
Job **1**

COMPLAINT INFORMATION	
Flat Rate Code	1039
Description	A/C-Dometic, Noise/vibration
Occurrences	1
Requested Hours	.50
Authorized Hours	.50
Fault Code	28-Misaligned
Vendor Responsible	89996-NEWMAR WORKMANSHIP Hours:.50

CUSTOMER COMPLAINT
COMMENT ENTERED ON 03/02/2026 AT 10:50 AM BY DEALER Rear air conditioner makes rubbing noise when on
AUTHORIZATION NOTES
DEALER CORRECTION
COMMENT ENTERED ON 03/02/2026 AT 10:50 AM BY DEALER Fan is rubbing against the housing. Adjusted and tested.

GENERAL INFORMATION	
Status	Paid
Date In	02/20/2026
Submit Date	03/02/2026
Authorization	No 04/09/2026
Work Complete	Yes 04/09/2026
Payment	Yes 04/10/2026

TOTALS	Requested	Authorized
Labor	92.50	92.50
Sublet	.00	.00
Parts	.00	.00
Freight	.00	.00
Adjustments	.00	.00
TOTAL	92.50	92.50
TOTAL PAID		92.50

