



Warranty Claim Detail

R.O. Number **73043**
Job **1**

COMPLAINT INFORMATION	
Flat Rate Code	26V 108
Description	NEWMAR - SECURE BSCA BTCA HOOD BRACKETS
Occurrences	1
Requested Hours	.30
Authorized Hours	.30
Fault Code	42-Recall
Vendor Responsible	89996-NEWMAR WORKMANSHIP Hours:.00

CUSTOMER COMPLAINT
COMMENT ENTERED ON 04/02/2026 AT 10:45 AM BY DEALER Recall 26V 108
AUTHORIZATION NOTES
DEALER CORRECTION
COMMENT ENTERED ON 04/02/2026 AT 10:45 AM BY DEALER Holes need to be drilled on the left and right hood stop and attached with bolts and lock washers. Predrilled holes for bolts and nuts and washers that manufacturer sent and installed and tightened down

GENERAL INFORMATION	
Status	Paid
Date In	04/16/2026
Submit Date	04/02/2026
Authorization	No 04/02/2026
Work Complete	Yes 04/02/2026
Payment	Yes 04/10/2026

TOTALS	Requested	Authorized
Labor	55.50	55.50
Sublet	.00	.00
Parts	.96	.96
Freight	.00	.00
Adjustments	.00	.00
TOTAL	56.75	56.75
TOTAL PAID		56.75

