



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72998
Promised Date:
13 MAR 26



WO #: 72998

Customer Name: 60002 - BARELA JR,
FRANK

Completed Date: 27 MAR 26

Invoice#:

Author: BRIAN

Stock Desc: 9431 2025 OPEN RANGE

22MLS

Serial#: 58TBM0BM1S7543053

Date In: 04 MAR 26

Chassis#: 58TBM0BM1S7543053

Time In:

Miles/Hrs:

Tag#: 6749

Purchased Date: 24 JUN 25

Warranty Date: 24 JUN 25

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES FURNACE WILL NOT LIGHT

CAUSE: Furnace will not light

Fan runs for 12 seconds and shuts off

CORRECTION: Checked the propane to insure there was propane in the bottles

Lit the cook top burners lit and had proper flame

Removed and tested the thermostat for proper operation is working properly

In order to gain full access to the furnace for further testing

I will have to remove the right dinette bench completely

The water pump and tank fill line will have to be removed

Duct work disconnected

Disconnect the exhaust and cut silicone on the outside

Disconnect electrical and unscrew furnace from the floor

Remove the furnace and bench test for further diagnostic

Request 3 hours for disassembly and re-assembly not including any diagnostic time or furnace repairs

Removed dinette table

Removed bench numerous screws from the floor and wall

Disconnected the gas line

Unscrewed the furnace from the floor

Removed the exhaust tubes

Disconnected air duct on the rear and dinette side

Removed the furnace

Bench tested the furnace

Tested power to the sail switch and continuity was work correctly

Tested the control board was working correctly

Found the on/off switch inside the face that is to the out outer wall of the unit was off

Turned the switch on tested the gas valve

Hooked the furnace up to gas and power and ran furnace worked

Took the furnace back into the unit

Reconnected the furnace the electric gas and duct

Reattached the exhaust

Bubble tested the gas

Turned the furnace on and it was working properly

Finished the furnace install that it was completely installed and hooked up

Reinstalled the bench and table

Ran the furnace on and off two more times worked each time

Work on the furnace is complete

Customer #: 60002
BARELA JR, FRANK



3.50HRS

Labor

Job #	Description	Total
1	FURNACE DIAGNOSTIC TIME	447.50

Subtotal for Job #1: 447.50

Job #2 - Internal

Transferred to RV*73101 on 27 MAR 26
Estimate amount was 0.00
REPLACE SLIDE FACIA

Labor

Job #	Description	Total
2	SLIDE FACIA	N/C

Other Services

Code	Description	Qty	Price	Total
SS-I	SHOP SUPPLIES - INTERNAL	0.00	N/C	N/C

Subtotal for Job #2: 0.00

Job #3 - Internal

COMPLAINT: CLEAN LINOLEUM

CAUSE: Water mark on the floor

CORRECTION: Mopped the whole unit and scrubbed the water mark

Labor

Job #	Description	Total
3	CLEAN LINOLEUM	N/C

Subtotal for Job #3: 0.00

Parts Total: 0.00
 Labour Total: 447.50
 Sublet Total: 0.00
 Extras Total: 0.00

WORK ORDER TOTAL: 447.50

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 27 Mar 2026

W/O: 72998
Promised Date: 13 MAR 26



Customer #: 60002
BARELA JR, FRANK

