



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73133
Promised Date:
17 APR 26



WO #: 73133

Customer Name: 1000 - MYERS "RV"
CENTER, INC.

Completed Date: 06 APR 26

Invoice#:

Author: BRIAN

Stock Desc: 9476 2025 OPEN RANGE
3X 287RLS

Serial#: 58TCM0BS2S3B53091

Date In: 31 MAR 26

Chassis#: 58TCM0BS2S3B53091

Time In:

Miles/Hrs:

Tag#:

Purchased Date: 28 MAR 26

Warranty Date: 28 MAR 26

Job #0 - Warranty

CLAIM: J01534032

Subtotal for Job #0: 0.00

Job #1 - Warranty

COMPLAINT: STOVE/OVEN INOPERATIVE

CAUSE: Disconnected wire at control board in the basement

CORRECTION: Found the stove oven had no power not allowing burners to light

Tracked the wiring from behind the stove to the basement

Opened the access panel in the basement for the control boards

Located the wiring for the stove and found the power side was disconnected

Using a volt meter found the connector for he stove

Reconnected the wire

Tested the stove and oven all components are now working

.80HRS

Labor

Job #	Description	Total
1	STOVEOVEN	143.20

Subtotal for Job #1: 143.20

Job #2 - Internal

COMPLAINT: WATER HEATER DISCONNECTED / FILTER BROKEN AT TRUMA

CAUSE: Found the water heater water lines were disconnected from the back of the water

Found the refrigerator water filter was full of antifreeze

Found the filter for the trauma aqua go was broken

CORRECTION: Reconnected the water lines to he back of the water heater

Found the filter for the water heater in the battery compartment

Installed the filter in the water heater

Turned the pump on to fill the water heater

Found water flowing out of the filter

Turned pump off

Found a stock unit with the same trauma system taken from 28551

Customer #: 1000
MYERS "RV" CENTER,
INC.,



Installed the filter and was able to test the water heater for leaks and functioning
 Water heater worked on both gas and electric
 Work completed

Labor				
Job #	Description			Total
2	WATER HEATER			N/C

Other Services				
Code	Description	Qty	Price	Total
SS-I	SHOP SUPPLIES - INTERNAL	1.00	N/C	N/C
Subtotal for Job #2:				0.00

Job #3 - Internal
 COMPLAINT: DRAWER IN KITCHEN MISSING GUIDES

CAUSE: Drawer guides missing

CORRECTION: Installed new drawer guides
 Verified drawer operation
 Works correctly
 Work complete

Labor				
Job #	Description			Total
3	DRAWER			N/C

Parts				
Part #	Description	Qty	Price	Total
16092	18" DRAWER SLIDE (SET OF 2)	1.00	N/C	N/C
Subtotal for Job #3:				0.00

Job #4 - Internal
 COMPLAINT: UNIT MISSING 50AM POWER CORD

CAUSE: Power cord missing

CORRECTION: Replaced power with new reference 73103

Labor				
Job #	Description			Total
4	INSTALL CORD			N/C

Subtotal for Job #4: 0.00

Job #5 - Internal
 COMPLAINT: Transferred to RV*73133A on 03 APR 26
 Estimate amount was 0.00
 DAMAGED EXTERIOR KITCHEN COMPARTMENT DOOR

CAUSE: Open door while slide was extending struck the building

CORRECTION: During the sfd the outdoor kitchen door was open
 Extending the slide the door struck the building causing heavy damage to the door
 The door was removed straightened and squared so that it will open and close the damaged edge was sealed with silicone and additional rivets added inside to hold the door together
 Pictures attached to the sfd
 Door needs to be replaced along with the decals
 Job on hold for parts

Labor				
Job #	Description			Total
5	COMPARTMENT DOOR			N/C

W/O: 73133
 Promised Date: 17 APR 26



Customer #: 1000
 MYERS "RV" CENTER,
 INC.,



Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: BEDROOM (BARN) DOORS LATCH INOP

CAUSE: Latch pulled out of keeper

CORRECTION: Removed knob from the door placed the elastic band back inside and reattached the knob
.10HRS

Labor

Job #	Description	Total
6	DOOR LATCH	17.90

Subtotal for Job #6: 17.90

Job #7 - Warranty

COMPLAINT: REFER NOT INSTALLED STRAIGHT

CAUSE: NOT STRAIGHT AND LOOSE

CORRECTION: Found the refrigerator was not in the cabinet square. the bottom was sticking out more than an inch further than top
 Found the refrigerator only has rollers on all four corners and the rear is not adjustable
 Removed the plastic grill from the front bottom and found the adjustment screws
 Lowered the front rollers until the refrigerator was much more plumb in the cabinet
 Also found the refrigerator was secured in the cabinet at all and was free to move in and out
 Found shop supplies metal angle shelf supports that fit at the front base that could be attached to the floor to prevent the refrigerator from rolling forward
 The angles were attached the refrigerator is now secure
 1.25hrs

Labor

Job #	Description	Total
7	REFER	179.00

Parts

Part #	Description	Qty	Price	Total
18935	GE REFRIGERATOR WATER FILTER	1.00	64.97	64.97

Subtotal for Job #7: 243.97

Job #8 - Warranty

COMPLAINT: BRAKE AMPS LOW

CAUSE: Break away amps not correct
Bad connectors
Damaged wire

CORRECTION: Found during the sfd the brake amps for the break away was 6.8 which is too low for tandem axle unit
 Followed the wiring into the 7 way junction box verified correct wiring which was correct
 Verified voltage in the junction box which was correct
 Got under the unit and checked amperage at the back of each hub
 Found the correct amperage to both rear hubs and no amperage at either hub on the front axle
 Inspected the wiring and found two issues
 First the connectors from the main wire to split to the brake hubs appeared to be damaged allowing to much play in the wires
 Second one of he wires from the connector to the drivers side front hub had been rubbing on the leaf spring and had been arcing on the metal
 Replaced the two connectors for the main wiring then cut and spliced the damaged wire
 Retested the amps at the break away and found the amps were now 12.2 which is within acceptable range
 Work completed
 1.50hrs

W/O: 73133
Promised Date: 17 APR 26



Customer #: 1000
MYERS "RV" CENTER,
INC.,





Labor		
Job #	Description	Total
8	BRAKES	268.50
Subtotal for Job #8:		268.50

Job #9 - Warranty

COMPLAINT: BEDROOM CHARGING STATION INOP

CAUSE: Not wired for power

CORRECTION: Check of the charging center in the front bedroom found the lighter style 12v plug had no power removed the dresser drawer and found the plug was not wired for power at all
 Used two female blade connectors and wire connected the plug to power and tested is now working correctly
 .50hrs

Labor		
Job #	Description	Total
9	ELECTRIC REPAIR	89.50
Subtotal for Job #9:		89.50

Job #10 - Internal

COMPLAINT: CAMERAS WILL NOT PAIR

CAUSE: No power to the camera
 Camera would not pair

CORRECTION: Attempted to pair the camera at the front door
 Camera would not pair
 Removed camera to verify it was plugged in found the camera was plugged in
 Pulled the wiring out of the wall checked the wire nuts there were connected
 Checked voltage at the wire nuts and had no voltage
 Checked the fuse panel no blown fuses
 Checked all 12 v systems in the unit all were working
 Found the camera is powered from the 7 way and will only be operational when the unit is plugged into the tow vehicle
 Was able to pair the camera and it is working
 Reinstalled the camera and verified again the camera is working
 Job complete

Labor		
Job #	Description	Total
10	CAMERA	N/C

Parts				
Part #	Description	Qty	Price	Total
4911	BATTERY AAA	2.00	N/C	N/C
Subtotal for Job #10:				0.00

Parts Total:	64.97
Labour Total:	698.10
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	763.07



NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 06 Apr 2026

Customer Signature : _____

Customer Work Order

W/O: 73133
Promised Date: 17 APR 26



Customer #: 1000
MYERS "RV" CENTER,
INC.,

