



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72379
Promised Date:
24 MAR 26



WO #: 72379

Customer Name: 1000 - MYERS "RV"
CENTER, INC.

Completed Date: 01 APR 26

Invoice#:

Author: ADVISOR

Stock Desc: 9612 2026 AVENGER
26DBS

Serial#: 5ZT2AVRB3TB941232

Chassis#: 5ZT2AVRB3TB941232

Miles/Hrs:

Tag#:

Purchased Date:

Warranty Date:

Date In: 19 SEP 25

Time In:

Job #1 - Internal

Transferred to RV*72379-1 on 17 JAN 26

Estimate amount was 0.00

CHECK IN NEW UNIT

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: Wrinkled decals

CAUSE: Decals are not smooth to the skin of the trailer

CORRECTION: Bubbles need to be smoothed out.

Request 0.6 hours to smooth bubbles throughout trailer

Labor

Job #	Description	Total
2	MULTIPLE LABOR CODES	114.00

Subtotal for Job #2: 114.00

Job #3 - Warranty

COMPLAINT: Black tank valve leaks through the valve while closed

CAUSE: Debris between seals not allowing a proper seal.

CORRECTION: Dumped the tank, used a bent screwdriver to feel between seals, pulled out some abs shavings, closed and filled tank, still leaking slowly, dumped again, pulled out more shavings, retested. NO more leaks. Dumped tank and checked again. NO more debris. Job completed. 1.0 requested for repair.

Labor

Job #	Description	Total
3	BLACK TANK VALVE	95.00

Subtotal for Job #3: 95.00

Job #4 - Warranty

COMPLAINT: Kink in the waterline near the pump

CAUSE: Theres a kink in the waterline that goes from the pump output to the water filter canister that is

Customer #: 1000
MYERS "RV" CENTER,
INC.,



impeding flow

CORRECTION: The kink is close to the fitting, will need to cut the kink out of the hose reattach hose to the T fitting and realign the output to alleviate kinking. Request .6 for repair.

Labor

Job #	Description	Total
4	MULTIPLE LABOR CODES	114.00

Parts

Part #	Description	Qty	Price	Total
88-9165	1/2 PLUMB-PEX CLAMP (OETIKER)	1.00	0.51	0.51

Subtotal for Job #4: 114.51

Job #5 - Warranty

COMPLAINT: 50 amp twist lock will not allow the cord to lock in place

CAUSE: The angle that the cord has to be plugged in does not allow the cord to stay locked in position the handle and cord pull the connector down to the left into the unlocked position

CORRECTION: Need to remove the four screws for the twist lock rotate 180 and reinstall so that when the cord is connected, the weight of the cord keeps the plug in the lock position. Request 0.54 repair

Labor

Job #	Description	Total
5	MULTIPLE LABOR CODES	102.60

Subtotal for Job #5: 102.60

Job #6 - Warranty

COMPLAINT: Chipped paint on metal plate inside slide fascia

CAUSE: The metal plate on the corner of the inner fascia of the slide has chipping paint and the paint is wrinkled in two areas

CORRECTION: Remove three screws sand down the wrinkled area, repaint the metal and reinstall. Will need to remove the other corner fascia and spray so that the paint matches. 0.6 requested for repair.

Labor

Job #	Description	Total
6	MULTIPLE LABOR CODES	114.00

Subtotal for Job #6: 114.00

Job #7 - Warranty

COMPLAINT: Missing valance in the kitchen. Metal.

CAUSE: There is no valance in the kitchen above the sinks. The valances in the living area are all metal and it looks like the kitchen window should have one

CORRECTION: Order a metal window valance and install. Shade length is 50 inches. Request .3 to install valance

Labor

Job #	Description	Total
7	MULTIPLE LABOR CODES	57.00

Parts

Part #	Description	Qty	Price	Total
F100711502	VALANCE, 3" X 54" X 2", TEXTURED BLACK - 48" X 29" WINDOW	1.00	27.40	27.40

Other Services

Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	54.39	54.39

W/O: 72379
Promised Date: 31 MAR 26



Customer #: 1000
MYERS "RV" CENTER,
INC.,



Subtotal for Job #7: 138.79

Job #8 - Warranty

COMPLAINT: CLOSET PANEL MISALIGNED

CAUSE: The panels in the two side closets in the master bedroom are not wide enough to fit between the cabinet and the wall. Leaving gaps and screws that have pulled out out of the wall panel panels.

CORRECTION: I will have to remove back panels on both sides inch by half inch wooden cleats, relocate them and reinstall the panels. Essentially I have to widen both panels by about a half an inch. Request 0.75 for each closet for repair. Total time of 1.5.

Labor

Job #	Description	Total
8	MULTIPLE LABOR CODES	285.00

Subtotal for Job #8: 285.00

Job #10 - Warranty

COMPLAINT: KITCHEN BLINDS BENT

CAUSE: Kitchen blinds are bent noted on delivery
1004 ISSUE CAUSED BY thereWas no valance and the blinds were broken in the unit

CORRECTION: Will need to order metal blinds, black, 32 inches tall and 51 inches wide. .5 for removal and replacement of blinds.
Installed new blinds and new valance checked for operation goes up and down Smoothly and blinds shut properly.

Labor

Job #	Description	Total
10	KITCHEN BLINDS	57.00

Parts

Part #	Description	Qty	Price	Total
F100728686	BLIND, MINI BLACK 50" X 31" (29892)	1.00	54.54	54.54

Other Services

Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	54.39	54.39

Subtotal for Job #10: 165.93

Job #11 - Warranty

COMPLAINT: DINETTE FRAME DAMAGED

CAUSE: Unknown, caused in manufacturing, noted at time of delivery.

CORRECTION: Three cross braces will have to be removed. The long piece of cracked wood will have to be removed and replaced and cross braces reinstalled using screws. 1.0 hour requested for repair, for disassembly cutting a piece of wood to fit and reassembly

Labor

Job #	Description	Total
11	MULTIPLE LABOR CODES	190.00

Subtotal for Job #11: 190.00

Job #PDI1 - Internal

COMPLAINT: Transferred to RV*72379-1 on 17 JAN 26
Estimate amount was 0.00
PRE-PDI NEW TT - 3.0

CAUSE: Pdi

W/O: 72379
Promised Date: 31 MAR 26



Customer #: 1000
MYERS "RV" CENTER,
INC.,



CORRECTION: Done

Labor

Job #	Description	Total
PDI1	PDI TRAVEL TRAILER	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #PDI1: 0.00

Job #WIN-STD - Internal

COMPLAINT: Transferred to RV*72379-1 on 17 JAN 26

Estimate amount was 0.00

WINTERIZE STANDARD

CAUSE: Winter

CORRECTION: Done

Labor

Job #	Description	Total
WIN-STD	WINTERIZE RV - BASIC	N/C

Subtotal for Job #WIN-STD: 0.00

Parts Total:	82.45
Labour Total:	1,128.60
Sublet Total:	0.00
Extras Total:	108.78
WORK ORDER TOTAL:	1,319.83

NOTICE:

DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 01 Apr 2026

W/O: 72379
Promised Date: 31 MAR 26



Customer #: 1000
MYERS "RV" CENTER,
INC.,

