

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Authorized
MYERS RV CENTER INC		CLAIM	2618745
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT2AVRBXTB941728
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	050 / 050
OWNER INFORMATION		ITEM #	AVT26DBS
		DEALER RO #	72859
		CLAIM START DATE	03/24/2026
		CLAIM END DATE	01/01/1900

Retail Date of Purchase _____ WARRANTY EXPIRATION DATE _____

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 40-196-24-11-001297 Interior 12 Volt Wiring - Electrical/12 Volt Interior/Repair/Electrical
Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-03-24 12:16:01 :: Complaint: Water pump kills battery power when running. Water pump only works when living room light switch is on. All lights dim severely when pump is running and power drops from 13.5V to 10.3V. Converter, battery and 120 are all in passing order. Cause: After extensive diagnosis, found no dedicated circuit for monitor panel or water pump. Ground supply was bad to the bathroom as well. Ran test circuits to verify problem and confirm resolution. Correction: Need to run a dedicated circuit from panel in living room to water pump controls in bathroom. Must run new ground from 12V distribution panel to the bathroom to resole bad ground issue. Must remove water pump from living room light circuit.

Model#	Dlr Sub Hrs	8.00	Sub Labor Amt \$1,520.00
Serial#	Appr Hrs	5.00	Appr Labor Amt \$950.00

Notes

NvCB,Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. TD

Labor

Line# 2 **Operation Code** **Operational Description**
 70-507-24-00-001901 AC Duct - Appliances/Ducting/Repair/No Tread Code
Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-03-24 12:18:48 :: Complaint: Air conditioner in living room is quick cycling compressor Cause: Manifold is not sealed properly Correction: reseal manifold Additional Note : stephanie@dealer-advisors.com, 2026-03-24 12:24:47 :: **There were only two labor codes available for the GE ACs. I picked a close code, but could not find one that really fit this repair**

Model#	Dlr Sub Hrs	0.50	Sub Labor Amt \$95.00
Serial#	Appr Hrs	0.50	Appr Labor Amt \$95.00

Notes

nvCB,Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. TD

Labor

Line# 3 **Operation Code** **Operational Description**
 30-100-36-00-001035 Cabinet Door - Interior/Cabinetry/Touch Up/No Tread Code
Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-03-24 12:26:07 :: **just noting at this time, no time needed right now. Bedroom door is peeling and there are scratches ion the cabinet in the bedroom.**

Model#	Dlr Sub Hrs	0.00	Sub Labor Amt \$0.00
Serial#	Appr Hrs	0.00	Appr Labor Amt \$0.00

Notes

Submitted	Labor Amt	\$1,615.00
	Parts & Freight	\$0.00
	Total	\$1,615.00

Approved	Labor Amt	\$1,045.00
	Parts & Freight	\$0.00
	Total	\$1,045.00

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.