

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b>	0008794	<b>CLAIM STATUS</b>	Paid
<b>MYERS RV CENTER INC</b>		<b>CLAIM</b>	2602813
12024 CENTRAL AVE S.E.		<b>CLAIM ORIGIN</b>	WEB
ALBUQUERQUE, NM 87123		<b>ORIGINAL CLAIM ID</b>	
USA		<b>VIN</b>	5ZT3CS2B9TG128553
		<b>CHASSIS VIN</b>	
		<b>MILEAGE</b>	0
<b>Labor rate:</b>	\$190.00	<b>SITE/WAREHOUSE</b>	049 / 049B
<b>OWNER INFORMATION</b>		<b>ITEM #</b>	CSFFAM37
JASON O'CONNOR		<b>DEALER RO #</b>	72909
10967 WISHING CLOUD RD		<b>CLAIM START DATE</b>	03/09/2026
Land O' Lakes, FL 34638		<b>CLAIM END DATE</b>	03/31/2026
USA			
<b>Retail Date of Purchase</b>	03/07/2026	<b>WARRANTY EXPIRATION DATE</b>	03/07/2027

## Claim Line Details

### Labor

<b>Line# 1</b>	<b>Operation Code</b>	<b>Operational Description</b>		
	20-46-19-00-000721	Window - Exterior/Windows/Reseal/No Tread Code		
	<b>Complaint, Cause, Correction</b>			
	Original Note : stephanie@dealer-advisors.com, 2026-03-09 10:18:43 :: Complaint: Sealant is coming out from around the window Cause: Sealant not properly adhered Correction: Scrape sealant and removed, added new sealant			
<b>Model#</b>		<b>Dlr Sub Hrs</b>	0.20	<b>Sub Labor Amt</b> \$38.00
<b>Serial#</b>		<b>Appr Hrs</b>	0.20	<b>Appr Labor Amt</b> \$38.00
	<b>Notes</b>			

### Part

<b>Line# 1</b>	<b>Item #</b>	<b>Description</b>			
	USERPART	Sealant			
	<b>Model #</b>	<b>Serial #</b>		<b>Part tag</b>	
	<b>Sub Qty</b> 1.00	<b>Sub Dlr Price</b> \$1.90		<b>Sub Freight</b>	\$0.00
	<b>Appr Qty</b> 1.00	<b>Appr Dlr Price</b> \$1.90		<b>Appr Freight</b>	\$0.00
	<b>Notes</b>				

### Labor

<b>Line# 2</b>	<b>Operation Code</b>	<b>Operational Description</b>		
	30-102-24-00-001094	Wall Panel Touch up - Luan - Interior/Panels, Ceilings, & Interior Moldings/ Repair/No Tread Code		
	<b>Complaint, Cause, Correction</b>			
	Original Note : stephanie@dealer-advisors.com, 2026-03-09 10:20:20 :: Complaint: Unfinished staples, nails and excessive putty Cause: Staple holes were not filled and putty found on walls Correction: Filled unfinished staples and nails and wiper down excessive putty. Reset nails sticking up Touched up the gouge in the wall. Touched up marks on closet and cabinet door.			
<b>Model#</b>		<b>Dlr Sub Hrs</b>	1.00	<b>Sub Labor Amt</b> \$190.00
<b>Serial#</b>		<b>Appr Hrs</b>	1.00	<b>Appr Labor Amt</b> \$190.00
	<b>Notes</b>			
	NVCB,Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD			

### Part

<b>Line# 1</b>	<b>Item #</b>	<b>Description</b>			
	USERPART	Putty & touch up			
	<b>Model #</b>	<b>Serial #</b>		<b>Part tag</b>	
	<b>Sub Qty</b> 1.00	<b>Sub Dlr Price</b> \$9.50		<b>Sub Freight</b>	\$0.00

Appr Qty 1.00 Appr Dlr Price \$9.50 Appr Freight \$0.00  
Notes

---

**Submitted**

Labor Amt \$228.00  
Parts & Freight \$11.40  
Total \$239.40

**Approved**

Labor Amt \$228.00  
Parts & Freight \$11.40  
Total \$239.40

---

**DEALER** \_\_\_\_\_ **DATE**

**SIGNATURE**

I certify that I have performed these repairs consistent with Forest River Policies.

---

**CUSTOMER** \_\_\_\_\_ **DATE**

**SIGNATURE**

All repairs described have been inspected and are satisfactory.