

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794		CLAIM STATUS Paid	
MYERS RV CENTER INC		CLAIM 2628731	
12024 CENTRAL AVE S.E.		CLAIM ORIGIN WEB	
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT3SN3B7TG706104
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	049 / 049A
OWNER INFORMATION		ITEM #	SNF38LAUNDRY
SASHA FLETCHER		DEALER RO #	73082A
PO BOX 265		CLAIM START DATE	04/02/2026
Ribera, NM 87560		CLAIM END DATE	04/06/2026
USA			
Retail Date of Purchase 03/26/2026		WARRANTY EXPIRATION DATE 03/26/2027	

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	30-98-24-00-002295	Bed or Bunk Structure - Interior/Beds, Mattress/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-04-02 10:16:10 :: Complaint: Master bed slide is dragging on the floor when all the way retracted Cause: Bed slide supports are too far back and are off center. Frame is not completely secure to the slide. Correction: Removed the mattress. Disconnected the struts from under bed storage. Removed both pieces of plywood. Unscrewed the bed frame from the slide room. Checked the bed supports by measurements and found they were too far back to support the foot of the bed and off center to the right. Moved the bed supports forward and put shims under them. Moved them to be centered under the bed Set the bed frame back in place. Found the bed frame was screwed to the floor with 2 screws at the edge of the slide, but nothing at the head of the bed. Added screws at the head of the bed. Completely reattached the bed frame back to the slide. Reinstalled the plywood and struts. Tested the bed on extend and retract and now stays well above the floor. Reattached the trim that was pulled off from dragging on the floor. Put mattress back in place.			
Model#	Dlr Sub Hrs	1.75	Sub Labor Amt	\$332.50
Serial#	Appr Hrs	1.75	Appr Labor Amt	\$332.50
	Notes			
	nVCB,Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD			

Part

Line# 1	Item #	Description	
	USERPART	Shims & screws	
	Model #	Serial #	Part tag
	Sub Qty 1.00	Sub Dlr Price \$16.63	Sub Freight \$0.00
	Appr Qty 1.00	Appr Dlr Price \$16.63	Appr Freight \$0.00
	Notes		

Labor

Line# 2	Operation Code	Operational Description		
	30-100-24-00-001046	Cabinet Door - Interior/Cabinetry/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-04-02 10:18:25 :: Complaint: Cabinet door is misaligned			
	Cause: Out of adjustment Correction: Adjusted the doors under the sink to the left of the microwave/pantry			
Model#	Dlr Sub Hrs	0.40	Sub Labor Amt	\$76.00
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$57.00
	Notes			
	nVCB,Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD			

Labor
Line# 3 **Operation Code** **Operational Description**
30-102-01-00-001097 Seam Tape, per 8 ft. Strip - Interior/Panels, Ceilings, & Interior Moldings/Replace/
No Tread Code

Complaint, Cause, Correction
Original Note : stephanie@dealer-advisors.com, 2026-04-02 10:20:33 :: Complaint: Seam tape is peeling off the
wall in the laundry room Cause: Seam tape peeling Correction: Removed seam tape and replace with new seam
tape

Model# **Dlr Sub Hrs** 0.20 **Sub Labor Amt** \$38.00
Serial# **Appr Hrs** 0.20 **Appr Labor Amt** \$38.00

Notes
nVCB,Per dealers description of this repair. This authorization is pending ALL requirements of
repair code have been met.TD

Part
Line# 1 **Item #** **Description**
USERPART Seam tape
Model # **Serial #** **Part tag**
 Sub Qty 1.00 **Sub Dlr Price** \$1.90 **Sub Freight** \$0.00
 Appr Qty 1.00 **Appr Dlr Price** \$1.90 **Appr Freight** \$0.00

Notes

Labor
Line# 4 **Operation Code** **Operational Description**
40-106-12-00-001320 Exterior Recept - Electrical/12 Volt Exterior/Resecure or Tighten/No Tread Code
Complaint, Cause, Correction
Original Note : stephanie@dealer-advisors.com, 2026-04-02 10:22:10 :: Complaint: Plug in basement fell off
Cause: PPlug with back board fell off Correction: Moved the backer board over slightly and rescrewed it to the
floor

Model# **Dlr Sub Hrs** 0.15 **Sub Labor Amt** \$28.50
Serial# **Appr Hrs** 0.10 **Appr Labor Amt** \$19.00

Notes
nVCB,Per dealers description of this repair. This authorization is pending ALL requirements of
repair code have been met.TD

Labor
Line# 5 **Operation Code** **Operational Description**
30-102-24-00-001094 Wall Panel Touch up - Luan - Interior/Panels, Ceilings, & Interior Moldings/
Repair/No Tread Code
Complaint, Cause, Correction
Original Note : stephanie@dealer-advisors.com, 2026-04-02 10:23:51 :: Complaint: Dime size hole in the paneling
Cause: Hole in panel Correction: Fill hole with silicone, ran seam tape from floor to ceiling to cover the hole

Model# **Dlr Sub Hrs** 0.20 **Sub Labor Amt** \$38.00
Serial# **Appr Hrs** 0.20 **Appr Labor Amt** \$38.00

Notes

Part
Line# 1 **Item #** **Description**
USERPART Silicone & seam tape
Model # **Serial #** **Part tag**
 Sub Qty 1.00 **Sub Dlr Price** \$1.90 **Sub Freight** \$0.00
 Appr Qty 1.00 **Appr Dlr Price** \$1.90 **Appr Freight** \$0.00

Notes

Labor
Line# 9 **Operation Code** **Operational Description**
30-101-24-00-001074 Interior Door Jamb, U-Channel, Casing, Frame - Interior/Interior Doors/Repair/No
Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-04-02 10:32:54 :: Complaint: Door will open past the strop trim Cause: Door jamb is not square Correction: Added shims under the jamb, got the jamb square so the door will close properly. Puttied all staple holes and nail holes.

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$57.00
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$57.00

Notes
nVCB,Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD

Part Line# 1	Item #		Description			
	USERPART		Shims & putty			
	Model #		Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$2.85	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$2.85	Appr Freight	\$0.00
	Notes					

Submitted			Labor Amt	\$570.00	Approved			Labor Amt	\$541.50
			Parts & Freight	\$23.28				Parts & Freight	\$23.28
			Total	\$593.28				Total	\$564.78

DEALER	DATE
SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.	

CUSTOMER	DATE
SIGNATURE	
All repairs described have been inspected and are satisfactory.	