

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Paid
MYERS RV CENTER INC		CLAIM	2586842
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	4X4TUMB29TB035467
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	080 / 080B
OWNER INFORMATION		ITEM #	UMT26ML-80
AARON SPENCE		DEALER RO #	72941
6 WESTLAKE DR NE		CLAIM START DATE	02/20/2026
Albuquerque, NM 87112		CLAIM END DATE	04/06/2026
USA			
Retail Date of Purchase	02/19/2026	WARRANTY EXPIRATION DATE	02/19/2027

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	30-100-01-00-001035	Cabinet Door - Interior/Cabinetry/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-02-20 12:18:33 :: Complaint: Cabinet door when opened hits factory installed hooks on wall, the door is damaged Cause: Hangers are not installed in the correct spot and door is hitting it Correction" Remove and replace cabinet door and relocate the hangers to prevent damage in the future. Unit sold, had to cover with a stop to allow customer to use Additional Note : stephanie@dealer-advisors.com, 2026-02-20 12:19:21 :: Time is for replacement of door AND relocation of wall hangers			
Model#	Dlr Sub Hrs	0.85	Sub Labor Amt	\$161.50
Serial#	Appr Hrs	0.85	Appr Labor Amt	\$161.50
	Notes			
	authorized to replace cabinet door and repair as stated			

Part

Line# 1	Item #	Description			
	F100425182	DOOR, FLAT PANEL 17-1/2 X 48 - BRIGHTON WHITE - SOP - *632025*			
	Model #	Serial #	Part tag		
	Sub Qty	1.00	Sub Dlr Price	\$41.86	
	Appr Qty	1.00	Sub Freight	\$54.91	
			Appr Dlr Price	\$41.86	
			Appr Freight	\$54.91	
	Notes				

Submitted	Labor Amt	\$161.50	Approved	Labor Amt	\$161.50
	Parts & Freight	\$96.77		Parts & Freight	\$96.77
	Total	\$258.27		Total	\$258.27

DEALER _____ **DATE** _____
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ **DATE** _____
SIGNATURE

All repairs described have been inspected and are satisfactory.