

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Paid
MYERS RV CENTER INC		CLAIM	2415769
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT2CXS047066
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	220 / 220A
OWNER INFORMATION		ITEM #	APTT265RBSS
VAL ARMSTRONG		DEALER RO #	72032
54 JASON RD		CLAIM START DATE	08/27/2025
Los Lunas, NM 87031		CLAIM END DATE	08/27/2025
USA			
Retail Date of Purchase	10/11/2024	WARRANTY EXPIRATION DATE	10/11/2025

Claim Line Details

Labor

Line# 2	Operation Code	Operational Description		
	30-102-12-00-001095	Ceiling Panel - Interior/Panels, Ceilings, & Interior Moldings/Resecure or Tighten/ No Tread Code		
	Complaint, Cause, Correction			
	Original Note : s.caffrey@myersrv.com, 2025-08-27 10:14:48 :: CUSTOMER STATES CEILING PANELS SEPARATING AT SLIDE / Staples pulled out / Removed old seam tape Stapled panel back to the ceiling Replaced the seam tape with new Job complete			
Model#	Dlr Sub Hrs	0.40	Sub Labor Amt	\$76.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$19.00
Notes				

Part

Line# 1	Item #	Description	
	USERPART	SHOP SUPPLIES - SEAM TAPE	
	Model #	Serial #	Part tag
	Sub Qty	1.00	Sub Dlr Price \$2.50
	Appr Qty	1.00	Sub Freight \$0.00
		Appr Dlr Price \$2.50	Appr Freight \$0.00
Notes			

Labor

Line# 3	Operation Code	Operational Description		
	20-57-24-00-000605	Loose Moldings - Exterior/Exterior Fiberglass Walls/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : s.caffrey@myersrv.com, 2025-08-27 10:17:21 :: CUSTOMER STATES JWRAP LOOSE / CUSTOMER STATES JWRAP LOOSE / Replaced the missing screws added a screw on the bottom lip cleaned the tape residue off job complete			
	Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$38.00
	Serial#	Appr Hrs	0.20	Appr Labor Amt \$38.00
	Notes			

Labor

Line# 4	Operation Code	Operational Description
	60-142-24-00-003327	Faucet - Plumbing/Miscellaneous Plumbing/Repair/No Tread Code
	Complaint, Cause, Correction	
	Original Note : s.caffrey@myersrv.com, 2025-08-27 10:21:13 :: CUSTOMER STATES KITCHEN FAUCET LEAKS AT BASE WHILE PRESSURIZED / Set screws loose / Found the whole facet moved at the base not allowing the gasket to seal Removed cabinet drawers and access panels Checked the set screws found they were loose	

Tightened the set screws , facet does not move at the base Checked the facet under pressure to the city water hook up no leaks detected Put access panels back and the drawers Cabinet was so small I could not physically see the set screws they were tightened by feel Job completed

Model#	Dlr Sub Hrs	0.40	Sub Labor Amt	\$76.00
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$57.00
Notes				

Labor

Line# 5	Operation Code 20-73-24-00-000739 Complaint, Cause, Correction Original Note : s.caffrey@myersrv.com, 2025-08-27 10:23:22 :: CUSTOMER STATES PASSENGER FENDERSKIRT LOOSE / Missing screws screws fell out / Replaced missing screws Added screws to secure the fender skirt Job complete	Operational Description Fenderskirt - Exterior/Fender Skirts, Wheel Well/Repair/No Tread Code		
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$19.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$19.00
Notes				

Labor

Line# 6	Operation Code 20-73-19-00-000739 Complaint, Cause, Correction Original Note : s.caffrey@myersrv.com, 2025-08-27 10:24:44 :: CUSTOMER STATES BELT MOLDING LOOSE AND SEPARATING / Missing. Silicone / Cleaned belt rail Added silicone to the areas on either end of the of the fender skirt Job completed	Operational Description Fenderskirt - Exterior/Fender Skirts, Wheel Well/Reseal/No Tread Code		
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$38.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$38.00
Notes				

Labor

Line# 8	Operation Code 30-101-24-00-001078 Complaint, Cause, Correction Original Note : s.caffrey@myersrv.com, 2025-08-27 10:40:04 :: CUSTOMER STATES BATHROOM DOOR FELL AND WALL SEPARATING / Screws pulled out of the roller on the top of the door / Removed facia trim Unlocked rollers and removed the door Moved the locking pin forward a 1/4 inch and screwed back to the door Moved the bottom guide back 1/4 inch one screw was between the door jam and stud causing the jam to separate Locked the door back on the rollers Reattached the facia trim Removed the strap that keeps the door in place during transport repaired the snap and reattached the strap Checked the door for proper operation and works properly job complete	Operational Description Sliding, Pocket Door - Interior/Interior Doors/Repair/No Tread Code		
Model#	Dlr Sub Hrs	1.00	Sub Labor Amt	\$190.00
Serial#	Appr Hrs	0.80	Appr Labor Amt	\$152.00
Notes				

Submitted	Labor Amt	\$437.00
	Parts & Freight	\$2.50
	Total	\$439.50

Approved	Labor Amt	\$323.00
	Parts & Freight	\$2.50
	Total	\$325.50

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.