



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72358
 Promised Date:
 15 SEP 25



WO #: 72358 (Appointment Date: 15 SEP 2025 - Time: 09:45am)
 Customer Name: 58933 - SPRINKLE JR, JAMES KENT
 Completed Date: 24 NOV 25
 Invoice#: _____
 Author: BRIAN
 Stock Desc: 9478 2025 BAY STAR 3225
 Serial#: 142117
 Chassis#: 1F66F5DN0R0A02245 Date In: 15 SEP 25
 Miles/Hrs: 3640 Time In: _____
 Tag#: 6778
 Purchased Date: 18 FEB 25
 Warranty Date: 18 FEB 25

Job #1 - Internal

COMPLAINT: CUSTOMER STATES THE BAR TO ROTATE DRIVERS SEAT IS BROKEN HE HAS REMOVED THE BAR BUT CAN'T FIND IT / CHECK AND ADVISE

CAUSE: Couldnt duplicate customer complaint.

CORRECTION: Tested with release lever on left side of chair. Swivel operation normal.
 Completed

Labor

Job #	Description	Total
1	DRIVER CHAIR	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
SS-I	SHOP SUPPLIES - INTERNAL	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES CHECK MAIN AWNING. THE TAPE TO SECURE THE WIRING IS PEELING.

CAUSE: Resecured

CORRECTION: Completed

Labor

Job #	Description	Total
2	MULTIPLE LABOR CODES	55.50

Subtotal for Job #2: 55.50

Job #3 - Warranty

COMPLAINT: Transferred to RV*72358-1 on 24 NOV 25
 Estimate amount was 0.00
 CUSTOMER STATES THE DINING ROOM BLACK OUT SHADE WILL NOT STAY CLOSED

CAUSE: Internal spring not catching

CORRECTION: Replace shade

Customer #: 58933
 SPRINKLE JR, JAMES
 KENT



48 wide x 32 tall

Labor

Job #	Description	Total
3	WINDOW SHADE DIAGNOSE	0.00

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: CUSTOMER STATES FULL WALL SLIDE IS UNEVEN AT FRONT. TOP GOES IN MORE AND PAST THE FRAMING (NOT FLUSH)

CAUSE: Performed adjustments to slide.

CORRECTION: As best as possible. Fascia warped. Completed

Labor

Job #	Description	Total
4	MULTIPLE LABOR CODES	185.00

Subtotal for Job #4: 185.00

Job #5 - Warranty

COMPLAINT: CUSTOMER STATES THE BEDROOM PASSENGER REAR SLIDE IS LOUD / MAKES NOISE

CAUSE: Lubricated rollers

CORRECTION: Completed

Labor

Job #	Description	Total
5	MULTIPLE LABOR CODES	74.00

Subtotal for Job #5: 74.00

Parts Total: 0.00
Labour Total: 314.50
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 314.50

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 25 Feb 2026

W/O: 72358
Promised Date: 15 SEP 25



Customer #: 58933
SPRINKLE JR, JAMES
KENT

