

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794
 MYERS RV CENTER INC
 12024 CENTRAL AVE S.E.
 ALBUQUERQUE, NM 87123
 USA

CLAIM STATUS Paid
 CLAIM 2538167
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 5ZT2LNMB7T9011956
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 501 / 501
 ITEM # LNT230FK
 DEALER RO # 71719
 CLAIM START DATE 12/30/2025
 CLAIM END DATE 02/18/2026

Labor rate: \$190.00
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 2 **Operation Code** **Operational Description**
 20-69-01-00-000706 Compartment Door - Exterior/Compartment Doors/Replace/No Tread Code
Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2025-12-30 15:08:09 :: Complaint: Outside docking station door is missing Cause: Docking station door damaged Correction: Replace docking station door
 Model# Dlr Sub Hrs 0.50 Sub Labor Amt \$95.00
 Serial# Appr Hrs 0.50 Appr Labor Amt \$95.00
 Notes

Part

Line# 1 **Item #** **Description**
 F100570206 HATCH, MULTIPURPOSE 7-3/4X12-1/2 BK THUMB OPEN 24/BOX
 Model # Serial # Part tag
 Sub Qty 1.00 Sub Dlr Price \$22.68 Sub Freight \$16.70
 Appr Qty 1.00 Appr Dlr Price \$22.68 Appr Freight \$16.70
 Notes

Labor

Line# 3 **Operation Code** **Operational Description**
 60-137-20-00-001509 Thetford Toilet - Standard Model - Plumbing/Toilet (Thetford)/Reset/No Tread Code
Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-01-05 09:46:00 :: Complaint: Toilet is loose, rocks to both sides Cause: Bolts on sides of toilet are loose Correction: Tightened the bolts that hold the toilet down.
 Model# 31835 Dlr Sub Hrs 0.30 Sub Labor Amt \$57.00
 Serial# E156ABVSAE715 Appr Hrs 0.30 Appr Labor Amt \$57.00
 Notes

Submitted	Labor Amt	\$152.00	Approved	Labor Amt	\$152.00
	Parts & Freight	\$39.38		Parts & Freight	\$39.38
	Total	\$191.38		Total	\$191.38

DEALER _____ DATE _____
 SIGNATURE
 I certify that I have performed these repairs consistent with Forest

CUSTOMER _____ DATE _____
 SIGNATURE
 All repairs described have been inspected and are satisfactory.

