

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794 MYERS RV CENTER INC 12024 CENTRAL AVE S.E. ALBUQUERQUE, NM 87123 USA	CLAIM STATUS Authorized CLAIM 2577317 CLAIM ORIGIN WEB ORIGINAL CLAIM ID VIN 5ZT2ALTB4S9010709 CHASSIS VIN MILEAGE 0 SITE/WAREHOUSE 501 / 501 ITEM # ALT2800KBH DEALER RO # 72918 CLAIM START DATE 02/11/2026 CLAIM END DATE 01/01/1900
Labor rate: \$190.00 OWNER INFORMATION BRITNEY KAYREN RINEHART 220 LOS MIRADORES PL NE Rio Rancho, NM 87124 USA	Retail Date of Purchase 09/03/2025 WARRANTY EXPIRATION DATE 09/03/2026

Claim Line Details

Labor

Line# 1	Operation Code 20-58-01-00-002310	Operational Description Vinyl Insert (per 10') - Exterior/Metal, Aluminum Siding/Replace/No Tread Code
	Complaint, Cause, Correction	Original Note : stephanie@dealer-advisors.com, 2026-02-11 12:46:37 :: Complaint: Customer states vinyl insert loose at front cap on the passenger and driver side Cause: Insert trim is loose on both sides Correction: Remove and replace vinyl insert on both sides, .35 per side
Model#	Dlr Sub Hrs	Sub Labor Amt \$133.00
Serial#	Appr Hrs	Appr Labor Amt \$114.00
	Notes	Dealer has requested more time than what is normally approved for this repair. Dealer asked for more time.

Labor

Line# 2	Operation Code 20-58-01-00-002310	Operational Description Vinyl Insert (per 10') - Exterior/Metal, Aluminum Siding/Replace/No Tread Code
	Complaint, Cause, Correction	Original Note : stephanie@dealer-advisors.com, 2026-02-11 12:49:07 :: Complaint: Vinyl insert is loose and cracked at rear upper cap Cause: Found vinyl cracked Correction: Remove and replace vinyl insert
Model#	Dlr Sub Hrs	Sub Labor Amt \$57.00
Serial#	Appr Hrs	Appr Labor Amt \$57.00
	Notes	

Submitted	Labor Amt	\$190.00	Approved	Labor Amt	\$171.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$190.00		Total	\$171.00

DEALER _____ **DATE** _____
SIGNATURE
 I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ **DATE** _____
SIGNATURE
 All repairs described have been inspected and are satisfactory.